



Technical Service Bulletin

Technical Service Bulletin: tsb102469

Released Date: 04-Sep-2007

Revision, Install Step (Gear Cover, Front) Procedure

Revision, Install Step (Gear Cover, Front) Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises procedure 001-031, (Gear Cover, Front), for the Troubleshooting and Repair Manuals listed.

The revision is the increase in the torque specification for the 6C, C8.3, C8.3G, C Gas Plus and L Gas Plus gear housing front cover.

The 10 mm head capscrews pass through the gear cover and thread into the front gear housing. The 11 mm head capscrews pass through the gear cover and the front gear housing and thread into the cylinder block.

Related Procedures

100-001-031-tr
(/qs3/pubsys2/xml/en/procedures/100/100-001-031-tr.html)

Gear Cover, Front
(/qs3/pubsys2/xml/en/procedures/100/100-001-031-tr.html)

Last Modified: 04-Sep-2007