



Technical Service Bulletin

Technical Service Bulletin: tsb102977

Released Date: 29-Jul-2008

Lubricating Oil Pan Procedure, Note Addition

Lubricating Oil Pan Procedure, Note Addition

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic adds a note to explain that the C and L Series engines have several oil pan sealing options and to use the sealing method originally used for the oil pan.

Related Procedures

100-007-025-tr-gc
(/qs3/pubsys2/xml/en/procedures/100/100-007-025-tr-gc.html)

Lubricating Oil Pan
(/qs3/pubsys2/xml/en/procedures/100/100-007-025-tr-gc.html)

Last Modified: 29-Jul-2008