



Technical Service Bulletin

Technical Service Bulletin: tsb103008

Released Date: 15-Aug-2008

(Bearings, Main) Procedure, General Information Section Revision

(Bearings, Main) Procedure, General Information Section Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises a statement about the upper main bearing shells in the General Information Section of the (Bearings, Main) Procedure, Procedure 001-006 for 6C, C8.3, C8.3G, C Gas Plus, and L Gas Plus engines in the C Series Troubleshooting and Repair Manual, Bulletin 3666003 and the C8.3G, C Gas Plus, and L Gas Plus Engines, Troubleshooting and Repair Manual, Bulletin 3666206.

Related Procedures

100-001-006-tr-gc
(/qs3/pubsys2/xml/en/procedures/100/100-001-006-tr-gc.html)

Bearings, Main
(/qs3/pubsys2/xml/en/procedures/100/100-001-006-tr-gc.html)

Last Modified: 15-Aug-2008