



Technical Service Bulletin

Technical Service Bulletin: tsb103526

Released Date: 21-May-2009

Maintenance Schedule Revision

Maintenance Schedule Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 102-002 (Maintenance Schedule) in Section 2 of the above listed manuals, to add the Radiator Pressure Cap maintenance check. The manuals are being revised to make certain the radiator pressure cap is functioning correctly. The system **must** maintain pressure to make sure of proper engine performance.

Related Procedures

41-102-002-om-auto
(/qs3/pubsys2/xml/en/procedures/41/41-102-002-om-auto.html)

Maintenance Schedule
(/qs3/pubsys2/xml/en/procedures/41/41-102-002-om-auto.html)

Last Modified: 21-May-2009