



Technical Service Bulletin

Technical Service Bulletin: tsb103857

Released Date: 16-Jun-2009

Lubricating Oil Filter (Spin-On) Procedure, Measure Section Addition

Lubricating Oil Filter (Spin-On) Procedure, Measure Section Addition

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic adds a Measure section to Procedure 007-013 (Lubricating Oil Filter (Spin-On)). This new section provides part numbers and instructions for measuring the lubricating oil filter differential pressure.

Related Procedures

41-007-013-tr
(/qs3/pubsys2/xml/en/procedures/41/41-007-013-tr.html)

Lubricating Oil Filter (Spin-On)
(/qs3/pubsys2/xml/en/procedures/41/41-007-013-tr.html)

Last Modified: 16-Jun-2009