



Technical Service Bulletin

Technical Service Bulletin: tsb103973

Released Date: 02-Nov-2009

Lubricating Oil Filter Head (Remote-Mounted) Procedure, Install Section Torque Revisions

Lubricating Oil Filter Head (Remote-Mounted) Procedure, Install Section Torque Revisions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the torque values in the Install section section of Procedure 007-017(Lubricating Oil Filter Head (Remote-Mounted)).

Related Procedures

20-007-017
(/qs3/pubsys2/xml/en/procedures/20/20-007-017.html)

Lubricating Oil Filter Head (Remote-Mounted)
(/qs3/pubsys2/xml/en/procedures/20/20-007-017.html)

Last Modified: 02-Nov-2009