



Technical Service Bulletin

Technical Service Bulletin: tsb104113

Released Date: 29-Apr-2010

Camshaft Bushings, Install Section Revisions

Camshaft Bushings, Install Section Revisions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the Install section of Procedure 001-010 (Camshaft Bushings) with revised illustrations showing the radial notch and the presence of two lubricating oil holes in the camshaft bushing.

Related Procedures

39-001-010-tr (/qs3/pubsys2/xml/en/procedures/39/39-001-010-tr.html)	Camshaft Bushings (Troubleshooting and Repair Manual, 3666206) (/qs3/pubsys2/xml/en/procedures/39/39-001-010-tr.html)
39-001-010-tr-gc (/qs3/pubsys2/xml/en/procedures/39/39-001-010-tr-gc.html)	Camshaft Bushings (Service Manual, 4021641) (/qs3/pubsys2/xml/en/procedures/39/39-001-010-tr-gc.html)
41-001-010 (/qs3/pubsys2/xml/en/procedures/41/41-001-010.html)	Camshaft Bushings (Troubleshooting and Repair Manual, 3666003) (/qs3/pubsys2/xml/en/procedures/41/41-001-010.html)
45-001-010-tr-iscl07 (/qs3/pubsys2/xml/en/procedures/45/45-001-010-tr-iscl07.html)	Camshaft Bushings (Troubleshooting and Repair Manual, 4021569) (/qs3/pubsys2/xml/en/procedures/45/45-001-010-tr-iscl07.html)
45-001-010-tr-iscl10 (/qs3/pubsys2/xml/en/procedures/45/45-001-010-tr-iscl10.html)	Camshaft Bushings (Service Manual, 4022257) (/qs3/pubsys2/xml/en/procedures/45/45-001-010-tr-iscl10.html)

45-001-010-tr-isclw (/qs3/pubsys2/xml/en/procedures/45/45-001-010-tr-isclw.html)	Camshaft Bushings (Service Manual, 4021630) (/qs3/pubsys2/xml/en/procedures/45/45-001-010-tr-isclw.html)
45-001-010-tr-islg (/qs3/pubsys2/xml/en/procedures/45/45-001-010-tr-islg.html)	Camshaft Bushings (Service Manual, 4021649) (/qs3/pubsys2/xml/en/procedures/45/45-001-010-tr-islg.html)
45-001-010-tr (/qs3/pubsys2/xml/en/procedures/45/45-001-010-tr.html)	Camshaft Bushings (Troubleshooting and Repair Manual, 4021418) (/qs3/pubsys2/xml/en/procedures/45/45-001-010-tr.html)

Last Modified: 29-Apr-2010
