



Technical Service Bulletin

Technical Service Bulletin: TSB104267

Released Date: 10-Jan-2011

New Alternator Guards and Related Parts

New Alternator Guards and Related Parts

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document announces new alternator guards and related parts for use on K19 and QSK19 series engines. These parts are in compliance with the European Commission Directive 2006/42/EC for protective guards that went in effect 01-Jan-2010. The new guards contain captive fasteners that are an integral part of the bracket assembly.

Procedure 008-001 (Belt Guard) and Procedure 013-005 (Drive Belt, Alternator) have been updated in the following manuals:

- K19 Service Manual, Bulletin 4021499
- QSK19, QSK19 CM850 MCRS, and QSK19 CM2150 MCRS Service Manual, Bulletin 4021592
- K19 Industrial and Marine Operation and Maintenance Manual, Bulletin 3666013
- QSK19, QSK19 CM850 MCRS, and QSK19 CM2150 MCRS Operation and Maintenance Manual, Bulletin 3666120.

All new options are fully compatible with the old options. The new guards can be fitted as replacements for the old ones. Use of the remaining stock of old guards **must** be limited to applications outside of the European Economic Area (EEA).

Table 1: Options Reference Table

Engine Family	Old Option	New Option
K19	AP 4704	AP 4702
QSK19	AP 4705	AP 4703
QSK19	DA 4068	DA 4048
K19	SG 4003	SG 4040
K19	SG 4009	SG 4048
K19	SG 4013	SG 4046
QSK19	SG 4021	SG 4041 / SG 4746
QSK19	SG 4026 / SG 4022	SG 4041 / SG 4745

Table 1: Options Reference Table		
QSK19	SG 4027	SG 4044
K19	SG 4039	SG 4045
K19	SG 4708	SG 4751
K19	SG 4709	SG 4747
QSK19	SG 4711 / DA 4068	SG 4042 / SG 4754
K19	SG 4717	SG 4744
QSK19	SG 4725 / DA 4068	SG 4042 / SG 4748
QSK19	SG 4727	SG 4746
QSK19	SG 4728	SG 4745
QSK19	SG 4730	SG 4752
QSK19	SG 4732	SG 4749

Document History

Date	Details
2010-12-20	Module Created