



Technical Service Bulletin

Technical Service Bulletin: TSB110054

Released Date: 25-Feb-2011

Cylinder Head Gasket

Cylinder Head Gasket

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document was originally released between 1994 and 2001. It has been added to QSOL for informational purposes

It has been reported that the fully molded head gasket (Part No. 3076189) has an incomplete seal on some engines. Most of these engines have cylinder block counterbore salvage sleeves. The reports have been on oil leaks, water leaks, and compression gas leaks. Most of the leaks are detected prior to the engine leaving the repair location.

Because of this, the parts business has reintroduced the old style oversize grommet gasket (Part No. 3049998), since 24May1996. They have also put a warning label on the kits listed below that the old style gasket may need to be used if the engine has counter bore sleeves installed. For counterbore salvage sleeve applications, use head gasket (Part No. 3049998) with oversize grommets in place of fully molded head gasket (Part No. 3076189).

Listed below are the gasket sets that use the new fully molded gasket. All of these have the warning label attached which explains the need to use the old style gasket (Part No. 3049998) on sleeved block engines.

3803981	3803982	3803983	3804274	3804275
3804276	3804279	3804281	3804282	3804283
3804284	3804286	3804287	3804288	3804291

Document History

Date	Details
2011-2-25	Module Created

