



Technical Service Bulletin

Technical Service Bulletin: TSB110067

Released Date: 08-Mar-2011

New PT (G) and PT (G) and AFC Rebuild Kits (t022)

New PT (G) and PT (G) and AFC Rebuild Kits (t022)

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document was originally released between 1994 and 2001. It has been added to QSOL for informational purposes

The purpose of this document is to introduce two new kits to the field to assist in the rebuilding of both PT (G) and PT (G) and AFC fuel pumps. The addition of these kits will reduce the proliferation of part numbers that presently need to be stocked and will encourage appropriate replacement of key parts since they will be included in the kit. These kits will be available from the Parts Distribution Center (PDC).

Details of the contents of each kit are lined out in the tables below, Table 1 contains the parts for the PT(G)/AFC rebuild kit Part No. 3803780, Table 2 contains the parts for the PT(G) rebuild kit Part No. 3803781.

Page 3 illustrates the kit's parts locations.

Table 1. PTG/AFC Repair Kit - Part No. 3803780

Ref. No.	Part No.	Description	Qty Req
99	S16052	Ball Bearing	1
168	S2286	Drive Screw	4
58	70690	Fuel Control Plunger Driver	1
73	146483	Screen Filter	1
100	212601	Main Drive Shaft	1
112	212607	Tachometer Drive Shaft	1
113	212609	Tachometer Shaft Bushing	1
107	212668	Square Key	1

Table 1. PTG/AFC Repair Kit - Part No. 3803780

Ref. No.	Part No.	Description	Qty Req
68	213769	Ball Plug	1
69	3000446	Throttle Shaft Cover	1
N/I*	3010242	Fuel Pump Gasket Kit	1
134	3013811	AFC Diaphragm	1
61	3027633	Thrust Bearing	1
12	3030970	Shutoff Valve Disc	1
45	3033740	Check Valve Elbow	1
160	3040817	O-Ring Seal	1
N/I*	3046200	Jaw Coupling Spider	1
60	3048557	Governor Plunger Spacer	1

* Not Illustrated


Table 2. PTG Repair Kit-Part No. 3803781

Ref. No.	Part No.	Description	Qty Req
N/I*	BM68356	Fuel Pump Gasket Set	1
99	S1650	Ball Bearing	1
168	S2286	Drive Screw	4
107	68174	Rectangular Key	1
58	70690	Fuel Control Plunger Driver	1
113	70723	Tachometer Drive Bushing	1
100	100192	Main Drive Shaft	1
112	104087	Tachometer Drive Shaft	1
73	146483	Screen Filter	1
69	148977	Throttle Shaft Cover	1
68	213769	Ball Plug	1
45	3027507	Check Valve Elbow	1
61	3027633	Thrust Bearing	1
12	3030970	Shutoff Valve Disc	1
160	3040817	O-Ring Seal	1
N/I*	3046200	Jaw Coupling Spider	1

Table 2. PTG Repair Kit-Part No. 3803781

Ref. No.	Part No.	Description	Qty Req
60	3048557	Governor Plunger Spacer	1
* Not Illustrated			

©Cummins Inc



PT (TYPE G) AFC FUEL PUMP PARTS

Document History

Date	Details
2011-3-8	Module Created

