



Technical Service Bulletin

Technical Service Bulletin: TSB110096

Released Date: 08-Apr-2011

Rocker Lever Adjusting Screw Change

Rocker Lever Adjusting Screw Change

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document was originally released between 1994 and 2001. It has been added to QSOL for informational purposes

This document introduces a new rocker lever adjusting screw for B and C Series engines.

The rocker lever adjusting screw for the B and C Series engines has been changed from a slotted-head screw, Part No. 3900706, to an internal hex-head screw, Part No. 3934086, as a product improvement.

The internal hex screw allows for automated valve lash adjustment completed at the plant. The **only** procedural change for service is use of a 5 mm Allen wrench instead of a flat-head screwdriver to adjust the new screws. The slotted screw assemblies are still available for service.

The ESN First for the Cummins Diesel Corporation is 45688397, 20 Apr 1998.

The ESN First for the Columbus Midrange Engine Plant is 56419958, 19 Dec 1997.

Part numbers for service are as follows:

Rocker and Screw Assembly		
	Slotted Screw	Hex Screw
C Series	3934916	3901717
B Series Intake	3934918	3910811
B Series Exhaust	3934917	3910810

Note : Slotted and hex adjusting screws can be intermixed without affecting the performance of the engine.

Document History

Date	Details
2011-3-30	Module Created

Last Modified: 08-Apr-2011
