



Technical Service Bulletin

Technical Service Bulletin: TSB130087

Released Date: 14-May-2013

Delco-Remy™ 35MT Starter to Replace 38MT Non-IMS and 38MT IMS

Delco-Remy™ 35MT Starter to Replace 38MT Non-IMS and 38MT IMS

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

The 35MT obsoletes and supersedes all 38MT starters in all options. The 35MT has an integrated magnetic switch (IMS) and improved starting capability compared to the 38MT and 38MT IMS. The 35MT provides these product improvements in a smaller package than the 38MT.

See Table 1 below to determine the appropriate part number.

Table 1: Part Number Supersession Table

New Part Number	Old Part Number
5267908	3965283
	3978387
5267909	3968284
	3978388
5267911	3965281
	3978385
5267912	3965282
	3978386
	4940750

Document History

Date	Details
2013-5-13	Module Created

