



Technical Service Bulletin

Technical Service Bulletin: TSB140070

Released Date: 02-Jul-2014

New Boost Hose for QSK19 Engines

New Boost Hose for QSK19 Engines

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document introduces a new boost hose for three options on QSK19 engines.

This change is being made to address leaks seen on the previous boost hose (Figure 1). The new boost hose (Figure 2) has a metal ring around it to improve the stability of the connection and reduce ballooning of the hose.

The engine serial number (ESN) for this change is 37259200.

There is no change to the installation or removal procedure due to these changes.

Table 1 lists the old and new part numbers.

Table 1: Boost Hose Part Numbers

Opyion	Old Part Number	New Part Number
IT4003	3627750	3636437
IT4001	3630125	3636437
IT4026	3630125	3636437



10k00031

Figure 1



10k00033

Figure 2

Document History

Date	Details
2014-5-30	Module Created

Last Modified: 02-Jul-2014
