



Technical Service Bulletin

Technical Service Bulletin: TSB140152

Released Date: 06-Nov-2014

New Turbocharger Oil Supply Line for QSK19 CM850 and CM2150

New Turbocharger Oil Supply Line for QSK19 CM850 and CM2150

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document introduces a new turbocharger oil supply line for QSK19 CM850 and CM2150 engines using engine option TP 4725.

Reason for Change

A section of rigid tube has been added to the new turbocharger oil supply line. This change improves orientation of the turbocharger oil supply line between the turbocharger turbine housing and turbocharger coolant supply line.

Service Parts Available

Yes. See Table 1.

Part Structure

The new part number does not obsolete and supersede the existing part number. The new part is backward compatible with the existing part. The existing part will remain available.

Part Disposition

None.

Production Status

Implemented for production. See Table 2.

Publications Affected

None.

Table1, Turbocharger Oil Supply Lines Part Numbers

Part Description	Existing Part Number	New Part Number
Turbocharger Oil Supply Line	3086021	4333931

Table 2, Plant Information

New Part Number	ESN First	Build Date	Plant
4333931	37262382	21 July 2014	Seymour Engine Plant

The following plants may also be affected, however ESN first and build date information is **not** available.

- Chongqing Cummins Engine Company
- Cummins India LTD Plant

©Cummins Inc



10r00088

Figure 1, New Turbocharger Oil Supply Line




Figure 2, New Turbocharger Oil Supply Line Installed On Engine

Document History

Date	Details
2014-10-27	Module Created

Last Modified: 06-Nov-2014
