



Technical Service Bulletin

Technical Service Bulletin: TSB150085

Released Date: 13-Apr-2017

NT-855 Equipped Rail Application Air Compressor Migration from Holset® ST773 to Wabco™ 636

NT-855 Equipped Rail Application Air Compressor Migration from Holset® ST773 to Wabco™ 636

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

Diesel Multiple Unit and Railcar Applications **Only**

ReCon® NT-855 Engines Affected:

- DR0683800RX (R1)
- DR0683900RX (R1)
- DR0684100RX (R3)
- DR0684200RX (R3)

Description of Change

The Holset® ST773 air compressor, Part Number 3048671, can no longer be supported. An air compressor upfit kit has been created to allow Wabco™ 636 twin air compressors, Part Number 4337583, to be used on the product affected.

Service Instructions

For Wabco™ 636 twin air compressor installation instructions. Refer to Installation Instruction, NT-855 Equipped Rail Application Air Compressor Migration from Holset® ST773 to Wabco™ 636, Bulletin 4908443.

Service Parts Availability

See Table 1 for required service parts to complete the air compressor conversion.

Table 1, Required Components for Wabco™ Air Compressor Conversion

Part Description	Quantity	Cummins® Part Number
Wabco™ 636 Twin Air Compressor	1	4337583

Table 1, Required Components for Wabco™ Air Compressor Conversion		
Part Description	Quantity	Cummins® Part Number
Air Compressor Upfit Kit	1	4337605
Associated Publications		
For a complete list of Service Manual procedures needed to remove, install, and troubleshoot the Wabco™ 636 twin air compressor, see TSB150086.		

Document History

Date	Details
2015-5-29	Module Created
2017-4-7	Non-Product Problem Solving (PPS)

Last Modified: 13-Apr-2017
