



Technical Service Bulletin: TSB150143

Released Date: 13-Oct-2015

Relocation of Coolant Temperature Sensor and Introduction of Resistor Capacitor Circuit

Relocation of Coolant Temperature Sensor and Introduction of Resistor Capacitor Circuit

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Issue

High ambient air temperatures near the existing location of the engine coolant temperature sensor can lead to false coolant temperature readings being observed and possible engine shutdown conditions.

Product Affected

- 6C8.3 (Air compressor applications **only**)

Resolution

The coolant temperature sensor has been relocated using a new wiring harness with integrated resistor capacitor circuit. See Figure 1 below for the existing location and the new location of the coolant temperature sensor.



Figure 1, Coolant Temperature Sensor Locations. Left: Existing Location. Right: New Location.



Figure 2, Resistor Capacitor Circuit in Wiring Harness

Service Instructions

This change is for new production engine builds **only**.

Production Status

Implemented for production. See Table 2 below.

Table 2, Production Information		
ESN First	Build Date*	Plant
25780103	08 June 2013	Cummins India LTD. Plant
*Engine build date can be found on the engine dataplate.		

Document History

Date	Details
2015-8-18	Module Created