



Technical Service Bulletin: TSB200118

Released Date: 01-Jun-2020

ReCon® Cylinder Head Mounting Hole Salvaging

ReCon® Cylinder Head Mounting Hole Salvaging

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- N14 CELECT
- N14 CELECT PLUS
- N14 MECHANICAL
- NH/NT 855
- QSN14 CM876 N103
- QSN14 CM876 N105
- QSNT14 CM876 N102

Description of Change

- This document is to inform field that ReCon® cylinder heads produced and sold using machining processes may look different, but have the same fit, form, and function. Reference Figure 1 below.
- ReCon® cylinder heads can have waviness or chattering marks observed on mounting hole face after spot machining operation on the rocker lever face side.
- Spot machining is one of the multiple regular salvaging processes deployed during remanufacturing to remove the step marks at that location after dismantling.
- After spot facing of mounting holes, waviness or chattering marks is predominantly observable in cylinder heads which have undergone welding salvage at mounting hole compared to the ones which did **not** need the welding salvage.




Figure 1, Acceptable Recon® Cylinder Head Mounting Hole Salvaging

Service Parts Availability

Part numbers are **not** changed for cylinder head assemblies. Service parts are available. See Table 1 for part numbers.

Table 1, Service Parts

Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
N series cylinder head assembly	2889411-PX	No	No	-
N series cylinder head assembly	3008095-RX	No	No	-
N series cylinder head assembly	3008100-RX	No	No	-
N series cylinder head assembly	3008101-RX	No	No	-
N series cylinder head assembly	3037989-RX	No	No	-
N series cylinder head assembly	3041993-RX	No	No	-
N series cylinder head assembly	3050419-RX	No	No	-
N series cylinder head assembly	3053346-RX	No	No	-

N series cylinder head assembly	3055098-RX	No	No	-
N series cylinder head assembly	3075422-RX	No	No	-
N series cylinder head assembly	3081224-RX	No	No	-
N series cylinder head assembly	3081225-RX	No	No	-
N series cylinder head assembly	3406737-RX	No	No	-
N series cylinder head assembly	3406739-RX	No	No	-
N series cylinder head assembly	3406742-RX	No	No	-
N series cylinder head assembly	3652600-RX	No	No	-
N series cylinder head assembly	3652807-RX	No	No	-
N series cylinder head assembly	3652808-RX	No	No	-
N series cylinder head assembly	3675505-RX	No	No	-
N series cylinder head assembly	3675506-RX	No	No	-
N series cylinder head assembly	R1307413H91 RX	No	No	-

Document History

Date	Details
2020-5-14	Module Created

Last Modified: 01-Jun-2020
