

Manual Change History (4021530) QSK45 and QSK60 Service Manual

Date	Not Available
Section	Front
Procedure Number	4021530-toc (/qs3/pubsys2/xml/en/manual/4021530/4021530-toc.html)
Procedure Title	Table of Contents
Update Reason	

Date	12-Mar-2002
Section	Section i - Introduction
Procedure Number	99-204-004 (/qs3/pubsys2/xml/en/procedures/99/99-204-004.html)
Procedure Title	Symbols
Update Reason	

Date	12-Mar-2002
Section	Section i - Introduction
Procedure Number	99-204-005 (/qs3/pubsys2/xml/en/procedures/99/99-204-005.html)
Procedure Title	Illustrations
Update Reason	

Date	03-Apr-2002
Section	Section TS - Troubleshooting Symptoms
Procedure Number	99-t00-002 (/qs3/pubsys2/xml/en/procedures/99/99-t00-002.html)
Procedure Title	Troubleshooting Symptoms Charts
Update Reason	

Date	03-Jul-2002
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	56-013-009 (/qs3/pubsys2/xml/en/procedures/56/56-013-009.html)
Procedure Title	Battery Cables and Connections
Update Reason	
Date	03-Jul-2002
Section	Section 14 - Engine Testing - Group 14
Procedure Number	56-014-001 (/qs3/pubsys2/xml/en/procedures/56/56-014-001.html)
Procedure Title	Dynamometer Worksheet
Update Reason	
Date	15-May-2003
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-008-007-shopds (/qs3/pubsys2/xml/en/procedures/56/56-008-007-shopds.html)
Procedure Title	Coolant Filter Head
Update Reason	
Date	15-May-2003
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-009-004-shopds (/qs3/pubsys2/xml/en/procedures/56/56-009-004-shopds.html)
Procedure Title	Accessory Drive Pulley
Update Reason	
Date	15-May-2003
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-009-016-shopds (/qs3/pubsys2/xml/en/procedures/56/56-009-016-shopds.html)
Procedure Title	Hydraulic Pump Drive
Update Reason	

Date	15-May-2003
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-009-016-shopas (/qs3/pubsys2/xml/en/procedures/56/56-009-016-shopas.html)
Procedure Title	Hydraulic Pump Drive
Update Reason	
Date	15-May-2003
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-009-004-shopas (/qs3/pubsys2/xml/en/procedures/56/56-009-004-shopas.html)
Procedure Title	Accessory Drive Pulley
Update Reason	
Date	15-May-2003
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-008-007-shopas (/qs3/pubsys2/xml/en/procedures/56/56-008-007-shopas.html)
Procedure Title	Coolant Filter Head
Update Reason	
Date	15-May-2003
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-007-tr (/qs3/pubsys2/xml/en/procedures/56/56-008-007-tr.html)
Procedure Title	Coolant Filter Head
Update Reason	
Date	15-May-2003
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-035 (/qs3/pubsys2/xml/en/procedures/56/56-008-035.html)
Procedure Title	Fan Hub Bracket
Update Reason	

Date	15-May-2003
Section	Section 9 - Drive Units - Group 09
Procedure Number	56-009-004-tr (/qs3/pubsys2/xml/en/procedures/56/56-009-004-tr.html)
Procedure Title	Accessory Drive Pulley
Update Reason	
Date	15-May-2003
Section	Section 9 - Drive Units - Group 09
Procedure Number	56-009-011 (/qs3/pubsys2/xml/en/procedures/56/56-009-011.html)
Procedure Title	Fuel Pump Drive
Update Reason	
Date	15-May-2003
Section	Section 9 - Drive Units - Group 09
Procedure Number	56-009-016-tr (/qs3/pubsys2/xml/en/procedures/56/56-009-016-tr.html)
Procedure Title	Hydraulic Pump Drive
Update Reason	
Date	15-May-2003
Section	Section 9 - Drive Units - Group 09
Procedure Number	56-009-039-tr (/qs3/pubsys2/xml/en/procedures/56/56-009-039-tr.html)
Procedure Title	Accessory Drive Cover
Update Reason	
Date	17-Jun-2003
Section	Section 10 - Air Intake System - Group 10
Procedure Number	56-010-006 (/qs3/pubsys2/xml/en/procedures/56/56-010-006.html)
Procedure Title	Aftercooler Coolant Tube
Update Reason	

Date	28-Jul-2003
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	56-012-010 (/qs3/pubsys2/xml/en/procedures/56/56-012-010.html)
Procedure Title	Air Compressor Pin Bore Wear
Update Reason	
Date	28-Jul-2003
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	56-012-013-tr (/qs3/pubsys2/xml/en/procedures/56/56-012-013-tr.html)
Procedure Title	Air Compressor Unloader and Valve Assembly
Update Reason	
Date	04-Aug-2003
Section	Section 10 - Air Intake System - Group 10
Procedure Number	56-010-031 (/qs3/pubsys2/xml/en/procedures/56/56-010-031.html)
Procedure Title	Air Intake Restriction
Update Reason	
Date	04-Aug-2003
Section	Section 17 - Miscellaneous - Group 17
Procedure Number	56-017-001-tr (/qs3/pubsys2/xml/en/procedures/56/56-017-001-tr.html)
Procedure Title	Capscrew
Update Reason	
Date	04-Aug-2003
Section	Section 17 - Miscellaneous - Group 17
Procedure Number	56-017-002-tr (/qs3/pubsys2/xml/en/procedures/56/56-017-002-tr.html)
Procedure Title	Cup Plug
Update Reason	

Date	04-Aug-2003
Section	Section 17 - Miscellaneous - Group 17
Procedure Number	56-017-005-tr (/qs3/pubsys2/xml/en/procedures/56/56-017-005-tr.html)
Procedure Title	Flexible Hose
Update Reason	
Date	04-Aug-2003
Section	Section 17 - Miscellaneous - Group 17
Procedure Number	56-017-007-tr (/qs3/pubsys2/xml/en/procedures/56/56-017-007-tr.html)
Procedure Title	Pipe Plug
Update Reason	
Date	07-Aug-2003
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-013-021-shopds (/qs3/pubsys2/xml/en/procedures/56/56-013-021-shopds.html)
Procedure Title	Belt Tensioner, Automatic (Alternator)
Update Reason	
Date	07-Aug-2003
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-013-001-shopds (/qs3/pubsys2/xml/en/procedures/56/56-013-001-shopds.html)
Procedure Title	Alternator
Update Reason	
Date	07-Aug-2003
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-013-001-shopas (/qs3/pubsys2/xml/en/procedures/56/56-013-001-shopas.html)
Procedure Title	Alternator
Update Reason	

Date	07-Aug-2003
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-013-021-shopas (/qs3/pubsys2/xml/en/procedures/56/56-013-021-shopas.html)
Procedure Title	Belt Tensioner, Automatic (Alternator)
Update Reason	
Date	07-Aug-2003
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	56-013-001-tr (/qs3/pubsys2/xml/en/procedures/56/56-013-001-tr.html)
Procedure Title	Alternator
Update Reason	
Date	07-Aug-2003
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	56-013-005-tr (/qs3/pubsys2/xml/en/procedures/56/56-013-005-tr.html)
Procedure Title	Drive Belt, Alternator
Update Reason	
Date	07-Aug-2003
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	56-013-017 (/qs3/pubsys2/xml/en/procedures/56/56-013-017.html)
Procedure Title	Started Magnetic Switch
Update Reason	
Date	07-Aug-2003
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	56-013-018 (/qs3/pubsys2/xml/en/procedures/56/56-013-018.html)
Procedure Title	Starter Switch
Update Reason	

Date	07-Aug-2003
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	56-013-019 (/qs3/pubsys2/xml/en/procedures/56/56-013-019.html)
Procedure Title	Starter Solenoid
Update Reason	
Date	07-Aug-2003
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	56-013-021-tr (/qs3/pubsys2/xml/en/procedures/56/56-013-021-tr.html)
Procedure Title	Belt Tensioner, Automatic (Alternator)
Update Reason	
Date	20-Aug-2003
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	56-016-008-tr (/qs3/pubsys2/xml/en/procedures/56/56-016-008-tr.html)
Procedure Title	Flywheel Ring Gear
Update Reason	
Date	21-Aug-2003
Section	Section 14 - Engine Testing - Group 14
Procedure Number	56-014-008-tr (/qs3/pubsys2/xml/en/procedures/56/56-014-008-tr.html)
Procedure Title	Engine Testing (In Chassis)
Update Reason	
Date	09-Oct-2003
Section	Section F - Familiarization
Procedure Number	56-016-999 (/qs3/pubsys2/xml/en/procedures/56/56-016-999.html)
Procedure Title	Mounting Adaptations - Overview
Update Reason	

Date	09-Oct-2003
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-001-017-shopds (/qs3/pubsys2/xml/en/procedures/56/56-001-017-shopds.html)
Procedure Title	Crankshaft Adapter
Update Reason	
Date	09-Oct-2003
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-001-017-shopas (/qs3/pubsys2/xml/en/procedures/56/56-001-017-shopas.html)
Procedure Title	Crankshaft Adapter
Update Reason	
Date	09-Oct-2003
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-017-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-017-tr.html)
Procedure Title	Crankshaft Adapter
Update Reason	
Date	27-Oct-2003
Section	Section 10 - Air Intake System - Group 10
Procedure Number	56-010-084 (/qs3/pubsys2/xml/en/procedures/56/56-010-084.html)
Procedure Title	Intercooler Element
Update Reason	
Date	27-Oct-2003
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	56-012-022 (/qs3/pubsys2/xml/en/procedures/56/56-012-022.html)
Procedure Title	Air Starting Motor
Update Reason	

Date	09-Dec-2003
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-012-014-shopds (/qs3/pubsys2/xml/en/procedures/56/56-012-014-shopds.html)
Procedure Title	Air Compressor
Update Reason	
Date	09-Dec-2003
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-010-083-shopds (/qs3/pubsys2/xml/en/procedures/56/56-010-083-shopds.html)
Procedure Title	Intercooler Assembly
Update Reason	
Date	09-Dec-2003
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-009-010-shopds (/qs3/pubsys2/xml/en/procedures/56/56-009-010-shopds.html)
Procedure Title	Alternator Drive Pulley
Update Reason	
Date	09-Dec-2003
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-009-010-shopas (/qs3/pubsys2/xml/en/procedures/56/56-009-010-shopas.html)
Procedure Title	Alternator Drive Pulley
Update Reason	
Date	09-Dec-2003
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-010-083-shopas (/qs3/pubsys2/xml/en/procedures/56/56-010-083-shopas.html)
Procedure Title	Intercooler Assembly
Update Reason	

Date	09-Dec-2003
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-008-116-shopas (/qs3/pubsys2/xml/en/procedures/56/56-008-116-shopas.html)
Procedure Title	Right Bank Number 8 Coolant Loop
Update Reason	
Date	09-Dec-2003
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-012-014-shopas (/qs3/pubsys2/xml/en/procedures/56/56-012-014-shopas.html)
Procedure Title	Air Compressor
Update Reason	
Date	09-Dec-2003
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-022 (/qs3/pubsys2/xml/en/procedures/56/56-008-022.html)
Procedure Title	Cooling System Service Requirements
Update Reason	
Date	09-Dec-2003
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-116-tr (/qs3/pubsys2/xml/en/procedures/56/56-008-116-tr.html)
Procedure Title	Right Bank Number 8 Coolant Loop
Update Reason	
Date	09-Dec-2003
Section	Section 9 - Drive Units - Group 09
Procedure Number	56-009-010-tr (/qs3/pubsys2/xml/en/procedures/56/56-009-010-tr.html)
Procedure Title	Alternator Drive Pulley
Update Reason	

Date	09-Dec-2003
Section	Section 9 - Drive Units - Group 09
Procedure Number	56-009-035-tr (/qs3/pubsys2/xml/en/procedures/56/56-009-035-tr.html)
Procedure Title	Engine Barring Device
Update Reason	
Date	09-Dec-2003
Section	Section 10 - Air Intake System - Group 10
Procedure Number	56-010-083-tr (/qs3/pubsys2/xml/en/procedures/56/56-010-083-tr.html)
Procedure Title	Intercooler Assembly
Update Reason	
Date	09-Dec-2003
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	56-012-014-tr (/qs3/pubsys2/xml/en/procedures/56/56-012-014-tr.html)
Procedure Title	Air Compressor
Update Reason	
Date	09-Dec-2003
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	56-012-017 (/qs3/pubsys2/xml/en/procedures/56/56-012-017.html)
Procedure Title	Air Governor (Air Compressor Will Not Pump)
Update Reason	

Date	09-Dec-2003
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	56-012-018 (/qs3/pubsys2/xml/en/procedures/56/56-012-018.html)
Procedure Title	Air Governor (Air Compressor Pumps Continuously)
Update Reason	

Date	11-Dec-2003
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-016-002-shopds (/qs3/pubsys2/xml/en/procedures/56/56-016-002-shopds.html)
Procedure Title	Engine Support Bracket, Front
Update Reason	

Date	11-Dec-2003
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-016-002-shopas (/qs3/pubsys2/xml/en/procedures/56/56-016-002-shopas.html)
Procedure Title	Engine Support Bracket, Front
Update Reason	

Date	11-Dec-2003
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	56-012-020 (/qs3/pubsys2/xml/en/procedures/56/56-012-020.html)
Procedure Title	Air Compressor (Oil Carryover)
Update Reason	

Date	11-Dec-2003
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	56-013-006 (/qs3/pubsys2/xml/en/procedures/56/56-013-006.html)
Procedure Title	Alternator Pulley
Update Reason	
Date	11-Dec-2003
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	56-013-007 (/qs3/pubsys2/xml/en/procedures/56/56-013-007.html)
Procedure Title	Batteries
Update Reason	
Date	11-Dec-2003
Section	Section 14 - Engine Testing - Group 14
Procedure Number	56-014-002 (/qs3/pubsys2/xml/en/procedures/56/56-014-002.html)
Procedure Title	Engine Testing (Chassis Dynamometer)
Update Reason	
Date	11-Dec-2003
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	56-016-002-tr (/qs3/pubsys2/xml/en/procedures/56/56-016-002-tr.html)
Procedure Title	Engine Support Bracket, Front
Update Reason	
Date	15-Jan-2004
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-010-035-shopds (/qs3/pubsys2/xml/en/procedures/56/56-010-035-shopds.html)
Procedure Title	Turbocharger, Low Pressure
Update Reason	

Date	15-Jan-2004
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-010-035-shopas (/qs3/pubsys2/xml/en/procedures/56/56-010-035-shopas.html)
Procedure Title	Turbocharger, Low Pressure
Update Reason	
Date	15-Jan-2004
Section	Section 2 - Cylinder Head - Group 02
Procedure Number	56-002-021 (/qs3/pubsys2/xml/en/procedures/56/56-002-021.html)
Procedure Title	Cylinder Head Gasket
Update Reason	
Date	15-Jan-2004
Section	Section 10 - Air Intake System - Group 10
Procedure Number	56-010-035-tr (/qs3/pubsys2/xml/en/procedures/56/56-010-035-tr.html)
Procedure Title	Turbocharger, Low Pressure
Update Reason	
Date	27-Jan-2004
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-008-002-shopds (/qs3/pubsys2/xml/en/procedures/56/56-008-002-shopds.html)
Procedure Title	Drive Belt, Cooling Fan
Update Reason	
Date	27-Jan-2004
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-008-040-shopds (/qs3/pubsys2/xml/en/procedures/56/56-008-040-shopds.html)
Procedure Title	Fan, Cooling
Update Reason	

Date	27-Jan-2004
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-008-040-shopas (/qs3/pubsys2/xml/en/procedures/56/56-008-040-shopas.html)
Procedure Title	Fan, Cooling
Update Reason	
Date	27-Jan-2004
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-008-002-shopas (/qs3/pubsys2/xml/en/procedures/56/56-008-002-shopas.html)
Procedure Title	Drive Belt, Cooling Fan
Update Reason	
Date	27-Jan-2004
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-002-tr (/qs3/pubsys2/xml/en/procedures/56/56-008-002-tr.html)
Procedure Title	Drive Belt, Cooling Fan
Update Reason	
Date	27-Jan-2004
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-040-tr (/qs3/pubsys2/xml/en/procedures/56/56-008-040-tr.html)
Procedure Title	Fan, Cooling
Update Reason	
Date	27-Jan-2004
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-042 (/qs3/pubsys2/xml/en/procedures/56/56-008-042.html)
Procedure Title	Radiator
Update Reason	

Date	28-Jan-2004
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-008-006-shopds (/qs3/pubsys2/xml/en/procedures/56/56-008-006-shopds.html)
Procedure Title	Coolant Filter
Update Reason	
Date	28-Jan-2004
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-008-006-shopas (/qs3/pubsys2/xml/en/procedures/56/56-008-006-shopas.html)
Procedure Title	Coolant Filter
Update Reason	
Date	28-Jan-2004
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-004 (/qs3/pubsys2/xml/en/procedures/56/56-008-004.html)
Procedure Title	Coolant Temperature Gauge
Update Reason	
Date	28-Jan-2004
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-006-tr (/qs3/pubsys2/xml/en/procedures/56/56-008-006-tr.html)
Procedure Title	Coolant Filter
Update Reason	
Date	28-Jan-2004
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-016 (/qs3/pubsys2/xml/en/procedures/56/56-008-016.html)
Procedure Title	Coolant Thermostat Seal
Update Reason	

Date	28-Jan-2004
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-019 (/qs3/pubsys2/xml/en/procedures/56/56-008-019.html)
Procedure Title	Cooling System - Air or Combustion Gas Test
Update Reason	
Date	28-Jan-2004
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-047-tr (/qs3/pubsys2/xml/en/procedures/56/56-008-047-tr.html)
Procedure Title	Radiator Pressure Cap
Update Reason	
Date	28-Jan-2004
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-051 (/qs3/pubsys2/xml/en/procedures/56/56-008-051.html)
Procedure Title	Radiator Top Tank
Update Reason	
Date	29-Jan-2004
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-038-tr (/qs3/pubsys2/xml/en/procedures/56/56-008-038-tr.html)
Procedure Title	Fan Shroud Assembly
Update Reason	
Date	03-Feb-2004
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-020 (/qs3/pubsys2/xml/en/procedures/56/56-008-020.html)
Procedure Title	Cooling System Diagnostics
Update Reason	

Date	03-Feb-2004
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	56-012-003 (/qs3/pubsys2/xml/en/procedures/56/56-012-003.html)
Procedure Title	Air Compressor Carbon Buildup
Update Reason	
Date	05-Feb-2004
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-045-tr (/qs3/pubsys2/xml/en/procedures/56/56-008-045-tr.html)
Procedure Title	Radiator Hoses
Update Reason	
Date	03-Mar-2004
Section	Section V - Specifications
Procedure Number	99-018-010 (/qs3/pubsys2/xml/en/procedures/99/99-018-010.html)
Procedure Title	Fraction, Decimal, Millimeter Conversions
Update Reason	
Date	03-Mar-2004
Section	Section V - Specifications
Procedure Number	99-018-014 (/qs3/pubsys2/xml/en/procedures/99/99-018-014.html)
Procedure Title	Weight and Measures - Conversion Factors
Update Reason	
Date	03-Mar-2004
Section	Section V - Specifications
Procedure Number	99-018-011 (/qs3/pubsys2/xml/en/procedures/99/99-018-011.html)
Procedure Title	Newton-Meter to Foot-Pound Conversions
Update Reason	

Date	03-Mar-2004
Section	Section V - Specifications
Procedure Number	99-018-012 (/qs3/pubsys2/xml/en/procedures/99/99-018-012.html)
Procedure Title	Pipe Plug Torque Values
Update Reason	
Date	03-Mar-2004
Section	Section V - Specifications
Procedure Number	99-018-013 (/qs3/pubsys2/xml/en/procedures/99/99-018-013.html)
Procedure Title	Tap-Drill Chart - U.S. Customary and Metric
Update Reason	
Date	19-Mar-2004
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-060 (/qs3/pubsys2/xml/en/procedures/56/56-008-060.html)
Procedure Title	Supplemental Coolant Additive (SCA)
Update Reason	
Date	29-Mar-2004
Section	Section 14 - Engine Testing - Group 14
Procedure Number	00-014-012 (/qs3/pubsys2/xml/en/procedures/00/00-014-012.html)
Procedure Title	Engine Compression
Update Reason	
Date	20-Apr-2004
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-008-015-shopds (/qs3/pubsys2/xml/en/procedures/56/56-008-015-shopds.html)
Procedure Title	Coolant Thermostat Housing Support
Update Reason	

Date	20-Apr-2004
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-008-015-shopas (/qs3/pubsys2/xml/en/procedures/56/56-008-015-shopas.html)
Procedure Title	Coolant Thermostat Housing Support
Update Reason	
Date	20-Apr-2004
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-015-tr (/qs3/pubsys2/xml/en/procedures/56/56-008-015-tr.html)
Procedure Title	Coolant Thermostat Housing Support
Update Reason	
Date	20-Apr-2004
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-017 (/qs3/pubsys2/xml/en/procedures/56/56-008-017.html)
Procedure Title	Coolant Vent Lines
Update Reason	
Date	22-Apr-2004
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-013-020-shopds (/qs3/pubsys2/xml/en/procedures/56/56-013-020-shopds.html)
Procedure Title	Starting Motor
Update Reason	
Date	22-Apr-2004
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-013-020-shopas (/qs3/pubsys2/xml/en/procedures/56/56-013-020-shopas.html)
Procedure Title	Starting Motor
Update Reason	

Date	22-Apr-2004
Section	Section 10 - Air Intake System - Group 10
Procedure Number	56-010-008 (/qs3/pubsys2/xml/en/procedures/56/56-010-008.html)
Procedure Title	Aftercooler Element
Update Reason	
Date	22-Apr-2004
Section	Section 11 - Exhaust System - Group 11
Procedure Number	56-011-009 (/qs3/pubsys2/xml/en/procedures/56/56-011-009.html)
Procedure Title	Exhaust Restriction
Update Reason	
Date	22-Apr-2004
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	56-013-020-tr (/qs3/pubsys2/xml/en/procedures/56/56-013-020-tr.html)
Procedure Title	Starter Motor
Update Reason	
Date	26-Apr-2004
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-041-tr (/qs3/pubsys2/xml/en/procedures/56/56-008-041-tr.html)
Procedure Title	Marine Gear Oil Cooler
Update Reason	
Date	01-Apr-2005
Section	Section F - Familiarization
Procedure Number	56-012-999 (/qs3/pubsys2/xml/en/procedures/56/56-012-999.html)
Procedure Title	Compressed Air System - Overview
Update Reason	

Date	30-Jun-2005
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-001-052-shopds (/qs3/pubsys2/xml/en/procedures/56/56-001-052-shopds.html)
Procedure Title	Vibration Damper, Viscous
Update Reason	
Date	30-Jun-2005
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-001-089-shopds (/qs3/pubsys2/xml/en/procedures/56/56-001-089-shopds.html)
Procedure Title	Block Stiffener Plate
Update Reason	
Date	30-Jun-2005
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-001-089-shopas (/qs3/pubsys2/xml/en/procedures/56/56-001-089-shopas.html)
Procedure Title	Block Stiffener Plate
Update Reason	
Date	30-Jun-2005
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-001-052-shopas (/qs3/pubsys2/xml/en/procedures/56/56-001-052-shopas.html)
Procedure Title	Vibration Damper, Viscous
Update Reason	
Date	30-Jun-2005
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-052-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-052-tr.html)
Procedure Title	Vibration Damper, Viscous
Update Reason	

Date	30-Jun-2005
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-055 (/qs3/pubsys2/xml/en/procedures/56/56-001-055.html)
Procedure Title	Gear Train Backlash, Front
Update Reason	
Date	30-Jun-2005
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-056 (/qs3/pubsys2/xml/en/procedures/56/56-001-056.html)
Procedure Title	Camshaft Thrust Bearing
Update Reason	
Date	30-Jun-2005
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-089-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-089-tr.html)
Procedure Title	Block Stiffener Plate
Update Reason	
Date	30-Jun-2005
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-022-001_07-tr (/qs3/pubsys2/xml/en/procedures/56/56-022-001_07-tr.html)
Procedure Title	Service Tools
Update Reason	
Date	30-Jun-2005
Section	Section 9 - Drive Units - Group 09
Procedure Number	56-022-001_09-tr (/qs3/pubsys2/xml/en/procedures/56/56-022-001_09-tr.html)
Procedure Title	Service Tools
Update Reason	

Date	30-Jun-2005
Section	Section 11 - Exhaust System - Group 11
Procedure Number	56-022-001_11 (/qs3/pubsys2/xml/en/procedures/56/56-022-001_11.html)
Procedure Title	Service Tools
Update Reason	
Date	30-Jun-2005
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	56-022-001_12-tr (/qs3/pubsys2/xml/en/procedures/56/56-022-001_12-tr.html)
Procedure Title	Service Tools
Update Reason	
Date	30-Jun-2005
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	56-022-001_13 (/qs3/pubsys2/xml/en/procedures/56/56-022-001_13.html)
Procedure Title	Service Tools
Update Reason	
Date	30-Jun-2005
Section	Section 14 - Engine Testing - Group 14
Procedure Number	56-022-001_14-tr (/qs3/pubsys2/xml/en/procedures/56/56-022-001_14-tr.html)
Procedure Title	Service Tools
Update Reason	
Date	30-Jun-2005
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	56-022-001_16-tr (/qs3/pubsys2/xml/en/procedures/56/56-022-001_16-tr.html)
Procedure Title	Service Tools
Update Reason	

Date	08-Jul-2005
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-001-010-shopds (/qs3/pubsys2/xml/en/procedures/56/56-001-010-shopds.html)
Procedure Title	Camshaft Bushings
Update Reason	
Date	08-Jul-2005
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-013-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-013-tr.html)
Procedure Title	Camshaft Gear (Camshaft Removed)
Update Reason	
Date	15-Jul-2005
Section	Section E - Engine and System Identification
Procedure Number	56-100-001 (/qs3/pubsys2/xml/en/procedures/56/56-100-001.html)
Procedure Title	Engine Identification
Update Reason	
Date	20-Jul-2005
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-007-025-shopds (/qs3/pubsys2/xml/en/procedures/56/56-007-025-shopds.html)
Procedure Title	Lubricating Oil Pan
Update Reason	
Date	20-Jul-2005
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-007-007-shopds (/qs3/pubsys2/xml/en/procedures/56/56-007-007-shopds.html)
Procedure Title	Lubricating Oil Cooler Element
Update Reason	

Date	20-Jul-2005
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-007-011-shopds (/qs3/pubsys2/xml/en/procedures/56/56-007-011-shopds.html)
Procedure Title	Lubricating Oil Dipstick Tube
Update Reason	
Date	20-Jul-2005
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-007-011-shopas (/qs3/pubsys2/xml/en/procedures/56/56-007-011-shopas.html)
Procedure Title	Lubricating Oil Dipstick Tube
Update Reason	
Date	20-Jul-2005
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-007-007-shopas (/qs3/pubsys2/xml/en/procedures/56/56-007-007-shopas.html)
Procedure Title	Lubricating Oil Cooler Element
Update Reason	
Date	20-Jul-2005
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-007-025-shopas (/qs3/pubsys2/xml/en/procedures/56/56-007-025-shopas.html)
Procedure Title	Lubricating Oil Pan
Update Reason	
Date	20-Jul-2005
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-007-tr (/qs3/pubsys2/xml/en/procedures/56/56-007-007-tr.html)
Procedure Title	Lubricating Oil Cooler Element
Update Reason	

Date	20-Jul-2005
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-009-tr (/qs3/pubsys2/xml/en/procedures/56/56-007-009-tr.html)
Procedure Title	Lubricating Oil Dipstick
Update Reason	
Date	20-Jul-2005
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-011-tr (/qs3/pubsys2/xml/en/procedures/56/56-007-011-tr.html)
Procedure Title	Lubricating Oil Dipstick Tube
Update Reason	
Date	20-Jul-2005
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-018 (/qs3/pubsys2/xml/en/procedures/56/56-007-018.html)
Procedure Title	Lubricating Oil Filter Head Adapter
Update Reason	
Date	20-Jul-2005
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-025-tr (/qs3/pubsys2/xml/en/procedures/56/56-007-025-tr.html)
Procedure Title	Lubricating Oil Pan
Update Reason	
Date	21-Jul-2005
Section	Section F - Familiarization
Procedure Number	56-000-999 (/qs3/pubsys2/xml/en/procedures/56/56-000-999.html)
Procedure Title	Complete Engine - Overview
Update Reason	

Date	21-Jul-2005
Section	Section F - Familiarization
Procedure Number	56-002-999 (/qs3/pubsys2/xml/en/procedures/56/56-002-999.html)
Procedure Title	Cylinder Head - Overview
Update Reason	

Date	21-Jul-2005
Section	Section F - Familiarization
Procedure Number	56-003-999 (/qs3/pubsys2/xml/en/procedures/56/56-003-999.html)
Procedure Title	Rocker Levers - Overview
Update Reason	

Date	21-Jul-2005
Section	Section F - Familiarization
Procedure Number	56-004-999 (/qs3/pubsys2/xml/en/procedures/56/56-004-999.html)
Procedure Title	Cam Followers/Tappets - Overview
Update Reason	

Date	21-Jul-2005
Section	Section F - Familiarization
Procedure Number	56-013-999 (/qs3/pubsys2/xml/en/procedures/56/56-013-999.html)
Procedure Title	Electrical Equipment - Overview
Update Reason	

Date	21-Jul-2005
Section	Section F - Familiarization
Procedure Number	56-014-999 (/qs3/pubsys2/xml/en/procedures/56/56-014-999.html)
Procedure Title	Engine Testing - Overview
Update Reason	

Date	21-Jul-2005
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-007-026-shopds (/qs3/pubsys2/xml/en/procedures/56/56-007-026-shopds.html)
Procedure Title	Lubricating Oil Pan Adapter Cover Plate
Update Reason	
Date	21-Jul-2005
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-007-027-shopds (/qs3/pubsys2/xml/en/procedures/56/56-007-027-shopds.html)
Procedure Title	Lubricating Oil Pan Adapter
Update Reason	
Date	21-Jul-2005
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-007-035-shopds (/qs3/pubsys2/xml/en/procedures/56/56-007-035-shopds.html)
Procedure Title	Lubricating Oil Suction Tube (Block-Mounted)
Update Reason	
Date	21-Jul-2005
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-007-035-shopas (/qs3/pubsys2/xml/en/procedures/56/56-007-035-shopas.html)
Procedure Title	Lubricating Oil Suction Tube (Block-Mounted)
Update Reason	
Date	21-Jul-2005
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-007-027-shopas (/qs3/pubsys2/xml/en/procedures/56/56-007-027-shopas.html)
Procedure Title	Lubricating Oil Pan Adapter
Update Reason	

Date	21-Jul-2005
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-007-026-shopas (/qs3/pubsys2/xml/en/procedures/56/56-007-026-shopas.html)
Procedure Title	Lubricating Oil Pan Adapter Cover Plate
Update Reason	
Date	21-Jul-2005
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-026-tr (/qs3/pubsys2/xml/en/procedures/56/56-007-026-tr.html)
Procedure Title	Lubricating Oil Pan Adapter Cover Plate
Update Reason	
Date	21-Jul-2005
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-027-tr (/qs3/pubsys2/xml/en/procedures/56/56-007-027-tr.html)
Procedure Title	Lubricating Oil Pan Adapter
Update Reason	
Date	21-Jul-2005
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-028 (/qs3/pubsys2/xml/en/procedures/56/56-007-028.html)
Procedure Title	Lubricating Oil Pressure Gauge
Update Reason	
Date	21-Jul-2005
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-035-tr (/qs3/pubsys2/xml/en/procedures/56/56-007-035-tr.html)
Procedure Title	Lubricating Oil Suction Tube (Block-Mounted)
Update Reason	

Date	21-Jul-2005
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-038 (/qs3/pubsys2/xml/en/procedures/56/56-007-038.html)
Procedure Title	Lubricating Oil Temperature Gauge
Update Reason	
Date	22-Jul-2005
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-024 (/qs3/pubsys2/xml/en/procedures/56/56-007-024.html)
Procedure Title	Lubricating Oil Leaks
Update Reason	
Date	29-Aug-2005
Section	Section F - Familiarization
Procedure Number	56-006-999-tr (/qs3/pubsys2/xml/en/procedures/56/56-006-999-tr.html)
Procedure Title	Injectors and Fuel Lines - Overview
Update Reason	
Date	08-Sep-2005
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-006-010-shopds (/qs3/pubsys2/xml/en/procedures/56/56-006-010-shopds.html)
Procedure Title	Fuel Connection Block (Manifold-Mounted)
Update Reason	
Date	08-Sep-2005
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-006-010-shopas (/qs3/pubsys2/xml/en/procedures/56/56-006-010-shopas.html)
Procedure Title	Fuel Connection Block (Manifold-Mounted)
Update Reason	

Date	08-Sep-2005
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	56-006-003 (/qs3/pubsys2/xml/en/procedures/56/56-006-003.html)
Procedure Title	Air in Fuel
Update Reason	
Date	08-Sep-2005
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	56-006-010-tr (/qs3/pubsys2/xml/en/procedures/56/56-006-010-tr.html)
Procedure Title	Fuel Connection Block (Manifold-Mounted)
Update Reason	
Date	08-Sep-2005
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	56-006-012 (/qs3/pubsys2/xml/en/procedures/56/56-006-012.html)
Procedure Title	Fuel Drain Line Restriction
Update Reason	
Date	26-Sep-2005
Section	Section F - Familiarization
Procedure Number	56-007-999 (/qs3/pubsys2/xml/en/procedures/56/56-007-999.html)
Procedure Title	Lubricating Oil System - Overview
Update Reason	
Date	26-Sep-2005
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-003-009-shopds (/qs3/pubsys2/xml/en/procedures/56/56-003-009-shopds.html)
Procedure Title	Rocker Lever Assembly
Update Reason	

Date	26-Sep-2005
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-004-014-shopds (/qs3/pubsys2/xml/en/procedures/56/56-004-014-shopds.html)
Procedure Title	Push Rods or Tubes
Update Reason	
Date	26-Sep-2005
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-003-013-shopds (/qs3/pubsys2/xml/en/procedures/56/56-003-013-shopds.html)
Procedure Title	Rocker Lever Housing
Update Reason	
Date	26-Sep-2005
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-004-002-shopds (/qs3/pubsys2/xml/en/procedures/56/56-004-002-shopds.html)
Procedure Title	Cam Follower Cover
Update Reason	
Date	26-Sep-2005
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-004-001-shopds (/qs3/pubsys2/xml/en/procedures/56/56-004-001-shopds.html)
Procedure Title	Cam Follower Assembly
Update Reason	
Date	26-Sep-2005
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-004-001-shopas (/qs3/pubsys2/xml/en/procedures/56/56-004-001-shopas.html)
Procedure Title	Cam Follower Assembly
Update Reason	

Date	26-Sep-2005
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-003-013-shopas (/qs3/pubsys2/xml/en/procedures/56/56-003-013-shopas.html)
Procedure Title	Rocker Lever Housing
Update Reason	
Date	26-Sep-2005
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-004-002-shopas (/qs3/pubsys2/xml/en/procedures/56/56-004-002-shopas.html)
Procedure Title	Cam Follower Cover
Update Reason	
Date	26-Sep-2005
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-004-014-shopas (/qs3/pubsys2/xml/en/procedures/56/56-004-014-shopas.html)
Procedure Title	Push Rods and Tubes
Update Reason	
Date	26-Sep-2005
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-003-009-shopas (/qs3/pubsys2/xml/en/procedures/56/56-003-009-shopas.html)
Procedure Title	Rocker Lever Assembly
Update Reason	
Date	26-Sep-2005
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-064 (/qs3/pubsys2/xml/en/procedures/56/56-001-064.html)
Procedure Title	Cylinder Liner Protrusion
Update Reason	

Date	26-Sep-2005
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	56-003-009-tr (/qs3/pubsys2/xml/en/procedures/56/56-003-009-tr.html)
Procedure Title	Rocker Lever Assembly
Update Reason	
Date	26-Sep-2005
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	56-003-013-tr (/qs3/pubsys2/xml/en/procedures/56/56-003-013-tr.html)
Procedure Title	Rocker Lever Housing
Update Reason	
Date	26-Sep-2005
Section	Section 4 - Cam Followers/Tappets - Group 04
Procedure Number	56-004-001-tr (/qs3/pubsys2/xml/en/procedures/56/56-004-001-tr.html)
Procedure Title	Cam Follower Assembly
Update Reason	
Date	26-Sep-2005
Section	Section 4 - Cam Followers/Tappets - Group 04
Procedure Number	56-004-002-tr (/qs3/pubsys2/xml/en/procedures/56/56-004-002-tr.html)
Procedure Title	Cam Follower Cover
Update Reason	
Date	26-Sep-2005
Section	Section 4 - Cam Followers/Tappets - Group 04
Procedure Number	56-004-014-tr (/qs3/pubsys2/xml/en/procedures/56/56-004-014-tr.html)
Procedure Title	Push Rods or Tubes
Update Reason	

Date	26-Sep-2005
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-130 (/qs3/pubsys2/xml/en/procedures/56/56-008-130.html)
Procedure Title	ECM Cooling Plate Lines
Update Reason	
Date	10-Oct-2005
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-044 (/qs3/pubsys2/xml/en/procedures/56/56-007-044.html)
Procedure Title	Lubricating Oil Contamination
Update Reason	
Date	10-Oct-2005
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-050 (/qs3/pubsys2/xml/en/procedures/56/56-007-050.html)
Procedure Title	Cylinder Smokes (Blue Smoke)
Update Reason	
Date	10-Oct-2005
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-061-tr (/qs3/pubsys2/xml/en/procedures/56/56-007-061-tr.html)
Procedure Title	Oil Transfer Connection
Update Reason	
Date	02-Nov-2005
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-009-001-shopds (/qs3/pubsys2/xml/en/procedures/56/56-009-001-shopds.html)
Procedure Title	Accessory Drive
Update Reason	

Date	02-Nov-2005
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-009-001-shopas (/qs3/pubsys2/xml/en/procedures/56/56-009-001-shopas.html)
Procedure Title	Accessory Drive
Update Reason	
Date	02-Nov-2005
Section	Section 9 - Drive Units - Group 09
Procedure Number	56-009-001-tr (/qs3/pubsys2/xml/en/procedures/56/56-009-001-tr.html)
Procedure Title	Accessory Drive
Update Reason	
Date	04-Nov-2005
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-022-001_01-tr (/qs3/pubsys2/xml/en/procedures/56/56-022-001_01-tr.html)
Procedure Title	Service Tools
Update Reason	
Date	04-Nov-2005
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	56-022-001_03-tr (/qs3/pubsys2/xml/en/procedures/56/56-022-001_03-tr.html)
Procedure Title	Service Tools
Update Reason	
Date	04-Nov-2005
Section	Section 10 - Air Intake System - Group 10
Procedure Number	56-010-129-tr (/qs3/pubsys2/xml/en/procedures/56/56-010-129-tr.html)
Procedure Title	Aftercooler Heat Shield
Update Reason	

Date	17-Nov-2005
Section	Section 10 - Air Intake System - Group 10
Procedure Number	56-022-001_10-tr (/qs3/pubsys2/xml/en/procedures/56/56-022-001_10-tr.html)
Procedure Title	Service Tools
Update Reason	
Date	29-Nov-2005
Section	Section 10 - Air Intake System - Group 10
Procedure Number	56-010-024 (/qs3/pubsys2/xml/en/procedures/56/56-010-024.html)
Procedure Title	Air Leaks, Air Intake and Exhaust Systems
Update Reason	
Date	20-Dec-2005
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-006-049-shopds (/qs3/pubsys2/xml/en/procedures/56/56-006-049-shopds.html)
Procedure Title	Fuel Control Valve Body Assembly
Update Reason	
Date	20-Dec-2005
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-009-029-shopds (/qs3/pubsys2/xml/en/procedures/56/56-009-029-shopds.html)
Procedure Title	Water Pump Drive
Update Reason	
Date	20-Dec-2005
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-001-031-shopds (/qs3/pubsys2/xml/en/procedures/56/56-001-031-shopds.html)
Procedure Title	Gear Cover, Front
Update Reason	

Date	20-Dec-2005
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-001-031-shopas (/qs3/pubsys2/xml/en/procedures/56/56-001-031-shopas.html)
Procedure Title	Gear Cover, Front
Update Reason	
Date	20-Dec-2005
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-006-025-shopas (/qs3/pubsys2/xml/en/procedures/56/56-006-025-shopas.html)
Procedure Title	Static Injection Timing
Update Reason	
Date	20-Dec-2005
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-009-029-shopas (/qs3/pubsys2/xml/en/procedures/56/56-009-029-shopas.html)
Procedure Title	Water Pump Drive
Update Reason	
Date	20-Dec-2005
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-006-049-shopas (/qs3/pubsys2/xml/en/procedures/56/56-006-049-shopas.html)
Procedure Title	Fuel Control Valve Body Assembly
Update Reason	
Date	20-Dec-2005
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-031-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-031-tr.html)
Procedure Title	Gear Cover, Front
Update Reason	

Date	20-Dec-2005
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	56-006-025-tr (/qs3/pubsys2/xml/en/procedures/56/56-006-025-tr.html)
Procedure Title	Static Injection Timing
Update Reason	
Date	20-Dec-2005
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	56-006-049-tr (/qs3/pubsys2/xml/en/procedures/56/56-006-049-tr.html)
Procedure Title	Fuel Control Valve Body Assembly
Update Reason	
Date	20-Dec-2005
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	56-006-062-tr (/qs3/pubsys2/xml/en/procedures/56/56-006-062-tr.html)
Procedure Title	Fuel Cooler
Update Reason	
Date	20-Dec-2005
Section	Section 9 - Drive Units - Group 09
Procedure Number	56-009-029-tr (/qs3/pubsys2/xml/en/procedures/56/56-009-029-tr.html)
Procedure Title	Water Pump Drive
Update Reason	
Date	23-Dec-2005
Section	Section F - Familiarization
Procedure Number	56-009-999 (/qs3/pubsys2/xml/en/procedures/56/56-009-999.html)
Procedure Title	Drive Units - Overview
Update Reason	

Date	23-Dec-2005
Section	Section 5 - Fuel System - Group 05
Procedure Number	56-005-010 (/qs3/pubsys2/xml/en/procedures/56/56-005-010.html)
Procedure Title	Fuel Consumption
Update Reason	
Date	23-Dec-2005
Section	Section 5 - Fuel System - Group 05
Procedure Number	56-005-025 (/qs3/pubsys2/xml/en/procedures/56/56-005-025.html)
Procedure Title	Fuel Pump Gear Pump
Update Reason	
Date	23-Dec-2005
Section	Section 5 - Fuel System - Group 05
Procedure Number	56-005-043-tr (/qs3/pubsys2/xml/en/procedures/56/56-005-043-tr.html)
Procedure Title	Fuel Shutoff Valve
Update Reason	
Date	02-Jan-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-007-065-shopds (/qs3/pubsys2/xml/en/procedures/56/56-007-065-shopds.html)
Procedure Title	Lubricating Oil Fill Tube
Update Reason	
Date	02-Jan-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-007-065-shopas (/qs3/pubsys2/xml/en/procedures/56/56-007-065-shopas.html)
Procedure Title	Lubricating Oil Fill Tube
Update Reason	

Date	02-Jan-2006
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-065-tr (/qs3/pubsys2/xml/en/procedures/56/56-007-065-tr.html)
Procedure Title	Lubricating Oil Fill Tube
Update Reason	
Date	02-Jan-2006
Section	Section 11 - Exhaust System - Group 11
Procedure Number	56-011-002 (/qs3/pubsys2/xml/en/procedures/56/56-011-002.html)
Procedure Title	Exhaust Connection Pipe (Turbocharger to Turbocharger)
Update Reason	
Date	09-Jan-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-022-001_00-shopds (/qs3/pubsys2/xml/en/procedures/56/56-022-001_00-shopds.html)
Procedure Title	Service Tools
Update Reason	
Date	09-Jan-2006
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-019-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-019-tr.html)
Procedure Title	Crankshaft Gear, Front (Crankshaft Removed)
Update Reason	
Date	09-Jan-2006
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-022-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-022-tr.html)
Procedure Title	Crankshaft Pulley
Update Reason	

Date	09-Jan-2006
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	56-006-021-tr (/qs3/pubsys2/xml/en/procedures/56/56-006-021-tr.html)
Procedure Title	Fuel Manifold (Drain)
Update Reason	
Date	09-Jan-2006
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	56-013-003-tr (/qs3/pubsys2/xml/en/procedures/56/56-013-003-tr.html)
Procedure Title	Alternator, Bracket
Update Reason	
Date	09-Jan-2006
Section	Back
Procedure Number	4021530-backcover (/qs3/pubsys2/xml/en/manual/4021530/4021530-backcover.html)
Procedure Title	Backcover
Update Reason	
Date	10-Jan-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-010-082-shopds (/qs3/pubsys2/xml/en/procedures/56/56-010-082-shopds.html)
Procedure Title	Frame, Two-Stage Turbocharger
Update Reason	
Date	10-Jan-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-010-082-shopas (/qs3/pubsys2/xml/en/procedures/56/56-010-082-shopas.html)
Procedure Title	Frame, Two-Stage Turbocharger
Update Reason	

Date	10-Jan-2006
Section	Section 10 - Air Intake System - Group 10
Procedure Number	56-010-082-tr (/qs3/pubsys2/xml/en/procedures/56/56-010-082-tr.html)
Procedure Title	Frame, Two-Stage Turbocharger
Update Reason	
Date	01-Feb-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-007-037-shopds (/qs3/pubsys2/xml/en/procedures/56/56-007-037-shopds.html)
Procedure Title	Lubricating Oil System
Update Reason	
Date	01-Feb-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-003-001-shopds (/qs3/pubsys2/xml/en/procedures/56/56-003-001-shopds.html)
Procedure Title	Crankcase Breather (External)
Update Reason	
Date	01-Feb-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-001-035-shopds (/qs3/pubsys2/xml/en/procedures/56/56-001-035-shopds.html)
Procedure Title	Hand Hole Cover
Update Reason	
Date	01-Feb-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-001-035-shopas (/qs3/pubsys2/xml/en/procedures/56/56-001-035-shopas.html)
Procedure Title	Hand Hole Cover
Update Reason	

Date	01-Feb-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-003-001-shopas (/qs3/pubsys2/xml/en/procedures/56/56-003-001-shopas.html)
Procedure Title	Crankcase Breather (External)
Update Reason	
Date	01-Feb-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-007-037-shopas (/qs3/pubsys2/xml/en/procedures/56/56-007-037-shopas.html)
Procedure Title	Lubricating Oil System
Update Reason	
Date	01-Feb-2006
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-035-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-035-tr.html)
Procedure Title	Hand Hole Cover
Update Reason	
Date	01-Feb-2006
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	56-003-001-tr (/qs3/pubsys2/xml/en/procedures/56/56-003-001-tr.html)
Procedure Title	Crankcase Breather (External)
Update Reason	
Date	01-Feb-2006
Section	Section 5 - Fuel System - Group 05
Procedure Number	56-022-001_05-tr (/qs3/pubsys2/xml/en/procedures/56/56-022-001_05-tr.html)
Procedure Title	Service Tools
Update Reason	

Date	01-Feb-2006
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-037-tr (/qs3/pubsys2/xml/en/procedures/56/56-007-037-tr.html)
Procedure Title	Lubricating Oil System
Update Reason	
Date	06-Feb-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021530-t004-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t004-tr.html)
Procedure Title	Air Compressor Air Pressure Rises Slowly
Update Reason	
Date	06-Feb-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021530-t006-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t006-tr.html)
Procedure Title	Air Compressor Noise is Excessive
Update Reason	
Date	06-Feb-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021530-t007-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t007-tr.html)
Procedure Title	Air Compressor Pumping Excess Lubricating Oil into the Air System
Update Reason	
Date	06-Feb-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021530-t008-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t008-tr.html)
Procedure Title	Air Compressor will Not Maintain Adequate Air Pressure (Not Pumping Continuously)
Update Reason	

Date	06-Feb-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021530-t009-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t009-tr.html)
Procedure Title	Air Compressor Will Not Pump Air
Update Reason	
Date	06-Feb-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021530-t010-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t010-tr.html)
Procedure Title	Air Compressor Will Not Stop Pumping
Update Reason	
Date	06-Feb-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021530-t013-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t013-tr.html)
Procedure Title	Alternator Not Charging or Insufficient Charging
Update Reason	
Date	06-Feb-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021530-t014-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t014-tr.html)
Procedure Title	Alternator Overcharging
Update Reason	
Date	06-Feb-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021530-t020-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t020-tr.html)
Procedure Title	Coolant Loss - External
Update Reason	

Date	06-Feb-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021530-t021-225-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t021-225-tr.html)
Procedure Title	Coolant Pressure Low
Update Reason	
Date	06-Feb-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021530-t047-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t047-tr.html)
Procedure Title	Engine Noise Excessive
Update Reason	
Date	06-Feb-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021530-t048-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t048-tr.html)
Procedure Title	Engine Noise Excessive - Combustion Knocks
Update Reason	
Date	06-Feb-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021530-t049-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t049-tr.html)
Procedure Title	Engine Noise Excessive - Connecting Rod
Update Reason	
Date	06-Feb-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021530-t050-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t050-tr.html)
Procedure Title	Engine Noise Excessive - Main Bearing
Update Reason	

Date	06-Feb-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021530-t051-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t051-tr.html)
Procedure Title	Engine Noise Excessive - Piston
Update Reason	
Date	06-Feb-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021530-t052-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t052-tr.html)
Procedure Title	Engine Noise Excessive - Turbocharger
Update Reason	
Date	06-Feb-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021530-t077-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t077-tr.html)
Procedure Title	Engine Will Not Crank or Cranks Slowly (Air Starter)
Update Reason	
Date	06-Feb-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021530-t078-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t078-tr.html)
Procedure Title	Engine Will Not Crank or Cranks Slowly (Electric Starter)
Update Reason	
Date	06-Feb-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021530-t081-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t081-tr.html)
Procedure Title	Engine Will Not Shut Off
Update Reason	

Date	06-Feb-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021530-t087-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t087-tr.html)
Procedure Title	Fuel Consumption Excessive
Update Reason	
Date	06-Feb-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021530-t089-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t089-tr.html)
Procedure Title	Fuel Temperature Above Normal Operating Range
Update Reason	
Date	06-Feb-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021530-t091-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t091-tr.html)
Procedure Title	Fuel in Coolant
Update Reason	
Date	06-Feb-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021530-t092-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t092-tr.html)
Procedure Title	Fuel in the Lubricating Oil
Update Reason	
Date	06-Feb-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021530-t092-5-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t092-5-tr.html)
Procedure Title	Fuel Leak - External
Update Reason	

Date	06-Feb-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021530-t096-20-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t096-20-tr.html)
Procedure Title	Intake Manifold Air Temperature Is High (Rapid Rise)
Update Reason	

Date	06-Feb-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021530-t096-55-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t096-55-tr.html)
Procedure Title	Intake Manifold Pressure is High
Update Reason	

Date	06-Feb-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021530-t104-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t104-tr.html)
Procedure Title	Lubricating Oil Pressure High
Update Reason	

Date	06-Feb-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021530-t106-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t106-tr.html)
Procedure Title	Lubricating Oil Sludge in the Crankcase Excessive
Update Reason	

Date	06-Feb-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021530-t107-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t107-tr.html)
Procedure Title	Lubricating Oil Temperature Above Specifications
Update Reason	
Date	06-Feb-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021530-t108-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t108-tr.html)
Procedure Title	Lubricating or Transmission Oil in the Coolant
Update Reason	
Date	06-Feb-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021530-t122-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t122-tr.html)
Procedure Title	Turbocharger Leaks Engine Oil or Fuel
Update Reason	
Date	27-Feb-2006
Section	Section F - Familiarization
Procedure Number	56-200-001 (/qs3/pubsys2/xml/en/procedures/56/56-200-001.html)
Procedure Title	Flow Diagram, Fuel System
Update Reason	
Date	27-Feb-2006
Section	Section F - Familiarization
Procedure Number	56-200-004 (/qs3/pubsys2/xml/en/procedures/56/56-200-004.html)
Procedure Title	Flow Diagram, Air Intake System
Update Reason	

Date	27-Feb-2006
Section	Section F - Familiarization
Procedure Number	56-200-006 (/qs3/pubsys2/xml/en/procedures/56/56-200-006.html)
Procedure Title	Flow Diagram, Compressed Air System
Update Reason	
Date	20-Apr-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-003-011-shopds (/qs3/pubsys2/xml/en/procedures/56/56-003-011-shopds.html)
Procedure Title	Rocker Lever Cover
Update Reason	
Date	20-Apr-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-003-011-shopas (/qs3/pubsys2/xml/en/procedures/56/56-003-011-shopas.html)
Procedure Title	Rocker Lever Cover
Update Reason	
Date	20-Apr-2006
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	56-003-011-tr (/qs3/pubsys2/xml/en/procedures/56/56-003-011-tr.html)
Procedure Title	Rocker Lever Cover
Update Reason	
Date	08-May-2006
Section	Section TT - Troubleshooting Symptoms (New Format)
Procedure Number	56-ttqsk60 (/qs3/pubsys2/xml/en/procedures/56/56-ttqsk60.html)
Procedure Title	Engine Performance Troubleshooting Tree
Update Reason	

Date	22-May-2006
Section	Front
Procedure Number	shopds-frwd (/qs3/pubsys2/xml/en/manual/preface/shopds-frwd.html)
Procedure Title	Foreword
Update Reason	
Date	27-Jun-2006
Section	Section L - Service Literature
Procedure Number	99-205-002 (/qs3/pubsys2/xml/en/procedures/99/99-205-002.html)
Procedure Title	Service Literature Ordering Location
Update Reason	
Date	08-Aug-2006
Section	Section F - Familiarization
Procedure Number	56-200-005 (/qs3/pubsys2/xml/en/procedures/56/56-200-005.html)
Procedure Title	Flow Diagram, Exhaust System - Overview
Update Reason	
Date	17-Aug-2006
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	56-006-020 (/qs3/pubsys2/xml/en/procedures/56/56-006-020.html)
Procedure Title	Fuel Inlet Restriction
Update Reason	
Date	24-Oct-2006
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	102-006-061 (/qs3/pubsys2/xml/en/procedures/102/102-006-061.html)
Procedure Title	Fuel Pressure Relief Valve
Update Reason	

Date	21-Nov-2006
Section	Section 5 - Fuel System - Group 05
Procedure Number	56-005-045-tr (/qs3/pubsys2/xml/en/procedures/56/56-005-045-tr.html)
Procedure Title	Fuel Lift Pump
Update Reason	
Date	09-Feb-2007
Section	Section 11 - Exhaust System - Group 11
Procedure Number	56-011-001-tr (/qs3/pubsys2/xml/en/procedures/56/56-011-001-tr.html)
Procedure Title	Exhaust Connection Pipe
Update Reason	
Date	07-May-2007
Section	Section 14 - Engine Testing - Group 14
Procedure Number	56-014-006-tr (/qs3/pubsys2/xml/en/procedures/56/56-014-006-tr.html)
Procedure Title	Engine Run-in (Engine Dynamometer)
Update Reason	
Date	08-May-2007
Section	Section 17 - Miscellaneous - Group 17
Procedure Number	56-017-011-tr (/qs3/pubsys2/xml/en/procedures/56/56-017-011-tr.html)
Procedure Title	Straight Thread Plug
Update Reason	
Date	17-May-2007
Section	Section V - Specifications
Procedure Number	56-018-018 (/qs3/pubsys2/xml/en/procedures/56/56-018-018.html)
Procedure Title	Cooling System
Update Reason	

Date	17-May-2007
Section	Section V - Specifications
Procedure Number	56-018-019 (/qs3/pubsys2/xml/en/procedures/56/56-018-019.html)
Procedure Title	Air Intake System
Update Reason	
Date	17-May-2007
Section	Section V - Specifications
Procedure Number	56-018-020 (/qs3/pubsys2/xml/en/procedures/56/56-018-020.html)
Procedure Title	Exhaust System
Update Reason	
Date	17-May-2007
Section	Section V - Specifications
Procedure Number	56-018-021 (/qs3/pubsys2/xml/en/procedures/56/56-018-021.html)
Procedure Title	Electrical System
Update Reason	
Date	17-May-2007
Section	Section V - Specifications
Procedure Number	56-018-022 (/qs3/pubsys2/xml/en/procedures/56/56-018-022.html)
Procedure Title	Compressed Air System
Update Reason	
Date	24-May-2007
Section	Front
Procedure Number	4021530-titlepage (/qs3/pubsys2/xml/en/manual/4021530/4021530-titlepage.html)
Procedure Title	Titlepage
Update Reason	

Date	11-Jul-2007
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-022-001_08-tr (/qs3/pubsys2/xml/en/procedures/56/56-022-001_08-tr.html)
Procedure Title	Service Tools
Update Reason	
Date	23-Jul-2007
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021530-t021-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t021-tr.html)
Procedure Title	Coolant Loss - Internal
Update Reason	
Date	23-Jul-2007
Section	Section TS - Troubleshooting Symptoms
Procedure Number	56-t00-004 (/qs3/pubsys2/xml/en/procedures/56/56-t00-004.html)
Procedure Title	Troubleshooting Overview
Update Reason	
Date	24-Jul-2007
Section	Section i - Introduction
Procedure Number	99-204-008 (/qs3/pubsys2/xml/en/procedures/99/99-204-008.html)
Procedure Title	General Cleaning Instructions
Update Reason	
Date	27-Jul-2007
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-003-006-shopas (/qs3/pubsys2/xml/en/procedures/56/56-003-006-shopas.html)
Procedure Title	Overhead Set (OBC)
Update Reason	

Date	30-Jul-2007
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	56-003-006-tr (/qs3/pubsys2/xml/en/procedures/56/56-003-006-tr.html)
Procedure Title	Overhead Set (OBC)
Update Reason	
Date	04-Sep-2007
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021530-t022-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t022-tr.html)
Procedure Title	Coolant Temperature Above Normal - Gradual Overheat
Update Reason	
Date	04-Sep-2007
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021530-t023-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t023-tr.html)
Procedure Title	Coolant Temperature Above Normal - Sudden Overheat
Update Reason	
Date	04-Sep-2007
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021530-t024-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t024-tr.html)
Procedure Title	Coolant Temperature is Below Normal
Update Reason	

Date	04-Sep-2007
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021530-t096-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t096-tr.html)
Procedure Title	Intake Manifold Air Temperature Above Specification
Update Reason	
Date	02-Nov-2007
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	56-022-001_06 (/qs3/pubsys2/xml/en/procedures/56/56-022-001_06.html)
Procedure Title	Service Tools
Update Reason	
Date	18-Mar-2008
Section	Section V - Specifications
Procedure Number	56-018-017 (/qs3/pubsys2/xml/en/procedures/56/56-018-017.html)
Procedure Title	Lubricating Oil System
Update Reason	
Date	19-Mar-2008
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-002-001-shopds (/qs3/pubsys2/xml/en/procedures/56/56-002-001-shopds.html)
Procedure Title	Crosshead
Update Reason	
Date	19-Mar-2008
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-002-001-shopas (/qs3/pubsys2/xml/en/procedures/56/56-002-001-shopas.html)
Procedure Title	Crosshead
Update Reason	

Date	19-Mar-2008
Section	Section 2 - Cylinder Head - Group 02
Procedure Number	56-002-001-tr (/qs3/pubsys2/xml/en/procedures/56/56-002-001-tr.html)
Procedure Title	Crosshead
Update Reason	
Date	13-May-2008
Section	Section 14 - Engine Testing - Group 14
Procedure Number	56-014-004-tr (/qs3/pubsys2/xml/en/procedures/56/56-014-004-tr.html)
Procedure Title	Engine Run-in (Without Dynamometer)
Update Reason	
Date	20-Jun-2008
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-001-023-shopds (/qs3/pubsys2/xml/en/procedures/56/56-001-023-shopds.html)
Procedure Title	Crankshaft Seal, Front
Update Reason	
Date	20-Jun-2008
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-001-024-shopds (/qs3/pubsys2/xml/en/procedures/56/56-001-024-shopds.html)
Procedure Title	Crankshaft Seal, Rear
Update Reason	
Date	20-Jun-2008
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-001-024-shopas (/qs3/pubsys2/xml/en/procedures/56/56-001-024-shopas.html)
Procedure Title	Crankshaft Seal, Rear
Update Reason	

Date	20-Jun-2008
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-001-023-shopas (/qs3/pubsys2/xml/en/procedures/56/56-001-023-shopas.html)
Procedure Title	Crankshaft Seal, Front
Update Reason	
Date	20-Jun-2008
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-023-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-023-tr.html)
Procedure Title	Crankshaft Seal, Front
Update Reason	
Date	20-Jun-2008
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-024-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-024-tr.html)
Procedure Title	Crankshaft Seal, Rear
Update Reason	
Date	23-Jun-2008
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-001-008-shopds (/qs3/pubsys2/xml/en/procedures/56/56-001-008-shopds.html)
Procedure Title	Camshaft
Update Reason	
Date	23-Jun-2008
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-001-008-shopas (/qs3/pubsys2/xml/en/procedures/56/56-001-008-shopas.html)
Procedure Title	Camshaft
Update Reason	

Date	23-Jun-2008
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-008-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-008-tr.html)
Procedure Title	Camshaft
Update Reason	
Date	11-Jul-2008
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-001-028-shopds (/qs3/pubsys2/xml/en/procedures/56/56-001-028-shopds.html)
Procedure Title	Cylinder Liner
Update Reason	
Date	11-Jul-2008
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-028-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-028-tr.html)
Procedure Title	Cylinder Liner
Update Reason	
Date	23-Jul-2008
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-007-013-shopds (/qs3/pubsys2/xml/en/procedures/56/56-007-013-shopds.html)
Procedure Title	Lubricating Oil Filter (Spin-On)
Update Reason	
Date	23-Jul-2008
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-007-013-shopas (/qs3/pubsys2/xml/en/procedures/56/56-007-013-shopas.html)
Procedure Title	Lubricating Oil Filter (Spin-On)
Update Reason	

Date	23-Jul-2008
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-013-tr (/qs3/pubsys2/xml/en/procedures/56/56-007-013-tr.html)
Procedure Title	Lubricating Oil Filter (Spin-On)
Update Reason	
Date	30-Jul-2008
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-001-046-shopds (/qs3/pubsys2/xml/en/procedures/56/56-001-046-shopds.html)
Procedure Title	Piston Cooling Nozzle
Update Reason	
Date	30-Jul-2008
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-001-046-shopas (/qs3/pubsys2/xml/en/procedures/56/56-001-046-shopas.html)
Procedure Title	Piston Cooling Nozzle
Update Reason	
Date	30-Jul-2008
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-046-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-046-tr.html)
Procedure Title	Piston Cooling Nozzle
Update Reason	
Date	13-Aug-2008
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	102-007-068 (/qs3/pubsys2/xml/en/procedures/102/102-007-068.html)
Procedure Title	Fleetguard® Centrifuge
Update Reason	

Date	28-Aug-2008
Section	Section F - Familiarization
Procedure Number	56-001-999 (/qs3/pubsys2/xml/en/procedures/56/56-001-999.html)
Procedure Title	Engine Block - Overview
Update Reason	
Date	28-Aug-2008
Section	Section 14 - Engine Testing - Group 14
Procedure Number	56-014-005-tr (/qs3/pubsys2/xml/en/procedures/56/56-014-005-tr.html)
Procedure Title	Engine Testing (Engine Dynamometer)
Update Reason	
Date	06-Oct-2008
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-008-018-shopds (/qs3/pubsys2/xml/en/procedures/56/56-008-018-shopds.html)
Procedure Title	Cooling System
Update Reason	
Date	06-Oct-2008
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-019-043-shopds (/qs3/pubsys2/xml/en/procedures/56/56-019-043-shopds.html)
Procedure Title	Engine Wiring Harness
Update Reason	
Date	06-Oct-2008
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-019-031-shopds (/qs3/pubsys2/xml/en/procedures/56/56-019-031-shopds.html)
Procedure Title	Electronic Control Module (ECM)
Update Reason	

Date	06-Oct-2008
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-019-031-shopas (/qs3/pubsys2/xml/en/procedures/56/56-019-031-shopas.html)
Procedure Title	Electronic Control Module (ECM)
Update Reason	
Date	06-Oct-2008
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-019-043-shopas (/qs3/pubsys2/xml/en/procedures/56/56-019-043-shopas.html)
Procedure Title	Engine Wiring Harness
Update Reason	
Date	06-Oct-2008
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-008-018-shopas (/qs3/pubsys2/xml/en/procedures/56/56-008-018-shopas.html)
Procedure Title	Cooling System
Update Reason	
Date	06-Oct-2008
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-018-tr (/qs3/pubsys2/xml/en/procedures/56/56-008-018-tr.html)
Procedure Title	Cooling System
Update Reason	
Date	06-Oct-2008
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-052-tr (/qs3/pubsys2/xml/en/procedures/56/56-008-052-tr.html)
Procedure Title	Expansion Tank
Update Reason	

Date	06-Oct-2008
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-053-tr (/qs3/pubsys2/xml/en/procedures/56/56-008-053-tr.html)
Procedure Title	Heat Exchanger
Update Reason	
Date	06-Oct-2008
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-057-tr (/qs3/pubsys2/xml/en/procedures/56/56-008-057-tr.html)
Procedure Title	Sea Water Pump
Update Reason	
Date	06-Oct-2008
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-061-tr (/qs3/pubsys2/xml/en/procedures/56/56-008-061-tr.html)
Procedure Title	Water Manifold
Update Reason	
Date	10-Oct-2008
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-043-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-043-tr.html)
Procedure Title	Piston
Update Reason	
Date	27-Oct-2008
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	56-006-073 (/qs3/pubsys2/xml/en/procedures/56/56-006-073.html)
Procedure Title	Delta Pressure Indicator
Update Reason	

Date	13-Nov-2008
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	00-016-010 (/qs3/pubsys2/xml/en/procedures/00/00-016-010.html)
Procedure Title	Engine Mounts
Update Reason	
Date	18-Nov-2008
Section	Section F - Familiarization
Procedure Number	56-005-999 (/qs3/pubsys2/xml/en/procedures/56/56-005-999.html)
Procedure Title	Fuel System - Overview
Update Reason	
Date	18-Nov-2008
Section	Section F - Familiarization
Procedure Number	56-200-002 (/qs3/pubsys2/xml/en/procedures/56/56-200-002.html)
Procedure Title	Flow Diagram, Lubricating Oil System
Update Reason	
Date	18-Nov-2008
Section	Section F - Familiarization
Procedure Number	56-008-999-tr (/qs3/pubsys2/xml/en/procedures/56/56-008-999-tr.html)
Procedure Title	Cooling System - Overview
Update Reason	
Date	18-Nov-2008
Section	Section F - Familiarization
Procedure Number	56-010-999-tr (/qs3/pubsys2/xml/en/procedures/56/56-010-999-tr.html)
Procedure Title	Air Intake System - Overview
Update Reason	

Date	18-Nov-2008
Section	Section F - Familiarization
Procedure Number	56-011-999-tr (/qs3/pubsys2/xml/en/procedures/56/56-011-999-tr.html)
Procedure Title	Exhaust System - Overview
Update Reason	
Date	18-Nov-2008
Section	Section 0 - Complete Engine - Group 00
Procedure Number	56-000-001 (/qs3/pubsys2/xml/en/procedures/56/56-000-001.html)
Procedure Title	Engine Removal
Update Reason	
Date	20-Nov-2008
Section	Section 11 - Exhaust System - Group 11
Procedure Number	56-011-015-tr (/qs3/pubsys2/xml/en/procedures/56/56-011-015-tr.html)
Procedure Title	Exhaust Manifold Heat Shield
Update Reason	
Date	21-Nov-2008
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-010-034-shopds (/qs3/pubsys2/xml/en/procedures/56/56-010-034-shopds.html)
Procedure Title	Turbocharger, High Pressure
Update Reason	
Date	21-Nov-2008
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-006-022-shopds (/qs3/pubsys2/xml/en/procedures/56/56-006-022-shopds.html)
Procedure Title	Fuel Manifold (Supply)
Update Reason	

Date	21-Nov-2008
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-006-022-shopas (/qs3/pubsys2/xml/en/procedures/56/56-006-022-shopas.html)
Procedure Title	Fuel Manifold (Supply)
Update Reason	
Date	21-Nov-2008
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-010-034-shopas (/qs3/pubsys2/xml/en/procedures/56/56-010-034-shopas.html)
Procedure Title	Turbocharger, High Pressure
Update Reason	
Date	21-Nov-2008
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	56-006-022-tr (/qs3/pubsys2/xml/en/procedures/56/56-006-022-tr.html)
Procedure Title	Fuel Manifold (Supply)
Update Reason	
Date	21-Nov-2008
Section	Section 10 - Air Intake System - Group 10
Procedure Number	56-010-034-tr (/qs3/pubsys2/xml/en/procedures/56/56-010-034-tr.html)
Procedure Title	Turbocharger, High Pressure
Update Reason	
Date	21-Nov-2008
Section	Section 10 - Air Intake System - Group 10
Procedure Number	56-010-076-tr (/qs3/pubsys2/xml/en/procedures/56/56-010-076-tr.html)
Procedure Title	Turbocharger Heat Shield
Update Reason	

Date	21-Nov-2008
Section	Section 10 - Air Intake System - Group 10
Procedure Number	56-010-130-tr (/qs3/pubsys2/xml/en/procedures/56/56-010-130-tr.html)
Procedure Title	Turbocharger Inlet Connections
Update Reason	
Date	24-Nov-2008
Section	Section 10 - Air Intake System - Group 10
Procedure Number	56-010-013-tr (/qs3/pubsys2/xml/en/procedures/56/56-010-013-tr.html)
Procedure Title	Air Cleaner Assembly (Engine-Mounted)
Update Reason	
Date	17-Dec-2008
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-001-037-shopds (/qs3/pubsys2/xml/en/procedures/56/56-001-037-shopds.html)
Procedure Title	Idler Gear, Camshaft (Left Bank)
Update Reason	
Date	17-Dec-2008
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-001-038-shopds (/qs3/pubsys2/xml/en/procedures/56/56-001-038-shopds.html)
Procedure Title	Idler Gear, Camshaft (Right Bank)
Update Reason	
Date	17-Dec-2008
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-001-039-shopds (/qs3/pubsys2/xml/en/procedures/56/56-001-039-shopds.html)
Procedure Title	Idler Gear, Hydraulic Pump
Update Reason	

Date	17-Dec-2008
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-001-040-shopds (/qs3/pubsys2/xml/en/procedures/56/56-001-040-shopds.html)
Procedure Title	Idler Gear, Water Pump
Update Reason	
Date	17-Dec-2008
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-001-040-shopas (/qs3/pubsys2/xml/en/procedures/56/56-001-040-shopas.html)
Procedure Title	Idler Gear, Water Pump
Update Reason	
Date	17-Dec-2008
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-001-039-shopas (/qs3/pubsys2/xml/en/procedures/56/56-001-039-shopas.html)
Procedure Title	Idler Gear, Hydraulic Pump
Update Reason	
Date	17-Dec-2008
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-001-038-shopas (/qs3/pubsys2/xml/en/procedures/56/56-001-038-shopas.html)
Procedure Title	Idler Gear, Camshaft (Right Bank)
Update Reason	
Date	17-Dec-2008
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-001-037-shopas (/qs3/pubsys2/xml/en/procedures/56/56-001-037-shopas.html)
Procedure Title	Idler Gear, Camshaft (Left Bank)
Update Reason	

Date	17-Dec-2008
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-037-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-037-tr.html)
Procedure Title	Idler Gear, Camshaft (Left Bank)
Update Reason	
Date	17-Dec-2008
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-038-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-038-tr.html)
Procedure Title	Idler Gear, Camshaft (Right Bank)
Update Reason	
Date	17-Dec-2008
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-039-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-039-tr.html)
Procedure Title	Idler Gear, Hydraulic Pump
Update Reason	
Date	17-Dec-2008
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-040-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-040-tr.html)
Procedure Title	Idler Gear, Water Pump
Update Reason	
Date	05-Jan-2009
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	56-012-019 (/qs3/pubsys2/xml/en/procedures/56/56-012-019.html)
Procedure Title	Air Leaks, Compressed Air System
Update Reason	

Date	30-Jan-2009
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-006-013-shopds (/qs3/pubsys2/xml/en/procedures/56/56-006-013-shopds.html)
Procedure Title	Fuel Drain Lines
Update Reason	
Date	30-Jan-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-006-013-shopas (/qs3/pubsys2/xml/en/procedures/56/56-006-013-shopas.html)
Procedure Title	Fuel Drain Lines
Update Reason	
Date	30-Jan-2009
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	56-006-013-tr (/qs3/pubsys2/xml/en/procedures/56/56-006-013-tr.html)
Procedure Title	Fuel Drain Lines
Update Reason	
Date	09-Feb-2009
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-001-033-shopds (/qs3/pubsys2/xml/en/procedures/56/56-001-033-shopds.html)
Procedure Title	Gear Housing, Front
Update Reason	
Date	09-Feb-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-001-033-shopas (/qs3/pubsys2/xml/en/procedures/56/56-001-033-shopas.html)
Procedure Title	Gear Housing, Front
Update Reason	

Date	09-Feb-2009
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-033-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-033-tr.html)
Procedure Title	Gear Housing, Front
Update Reason	
Date	16-Feb-2009
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-030 (/qs3/pubsys2/xml/en/procedures/56/56-001-030.html)
Procedure Title	Gear Cover Trunion Sleeve
Update Reason	
Date	26-Mar-2009
Section	Section TT - Troubleshooting Symptoms (New Format)
Procedure Number	105-t02-1005a (/qs3/pubsys2/xml/en/procedures/105/105-t02-1005a.html)
Procedure Title	Vibration Excessive
Update Reason	
Date	27-Mar-2009
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-006-024-shopds (/qs3/pubsys2/xml/en/procedures/56/56-006-024-shopds.html)
Procedure Title	Fuel Supply Lines
Update Reason	
Date	27-Mar-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-006-024-shopas (/qs3/pubsys2/xml/en/procedures/56/56-006-024-shopas.html)
Procedure Title	Fuel Supply Lines
Update Reason	

Date	27-Mar-2009
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	56-006-024-tr (/qs3/pubsys2/xml/en/procedures/56/56-006-024-tr.html)
Procedure Title	Fuel Supply Lines
Update Reason	
Date	20-Apr-2009
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-010-002-shopds (/qs3/pubsys2/xml/en/procedures/56/56-010-002-shopds.html)
Procedure Title	Aftercooler Assembly
Update Reason	
Date	20-Apr-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-010-002-shopas (/qs3/pubsys2/xml/en/procedures/56/56-010-002-shopas.html)
Procedure Title	Aftercooler Assembly
Update Reason	
Date	20-Apr-2009
Section	Section 10 - Air Intake System - Group 10
Procedure Number	56-010-002-tr (/qs3/pubsys2/xml/en/procedures/56/56-010-002-tr.html)
Procedure Title	Aftercooler Assembly
Update Reason	
Date	24-Apr-2009
Section	Section V - Specifications
Procedure Number	56-018-015-tr (/qs3/pubsys2/xml/en/procedures/56/56-018-015-tr.html)
Procedure Title	General Engine
Update Reason	

Date	30-Apr-2009
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-016-006-shopds (/qs3/pubsys2/xml/en/procedures/56/56-016-006-shopds.html)
Procedure Title	Flywheel Housing
Update Reason	

Date	30-Apr-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-016-006-shopas (/qs3/pubsys2/xml/en/procedures/56/56-016-006-shopas.html)
Procedure Title	Flywheel Housing
Update Reason	

Date	30-Apr-2009
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	56-016-006-tr (/qs3/pubsys2/xml/en/procedures/56/56-016-006-tr.html)
Procedure Title	Flywheel Housing
Update Reason	

Date	15-Jun-2009
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-007-045-shopds (/qs3/pubsys2/xml/en/procedures/56/56-007-045-shopds.html)
Procedure Title	Lubricating Oil Cooler Cover
Update Reason	

Date	15-Jun-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-007-045-shopas (/qs3/pubsys2/xml/en/procedures/56/56-007-045-shopas.html)
Procedure Title	Lubricating Oil Cooler Cover
Update Reason	

Date	15-Jun-2009
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-045-tr (/qs3/pubsys2/xml/en/procedures/56/56-007-045-tr.html)
Procedure Title	Lubricating Oil Cooler Cover
Update Reason	
Date	25-Jun-2009
Section	Section TS - Troubleshooting Symptoms
Procedure Number	99-t00-001-tr (/qs3/pubsys2/xml/en/procedures/99/99-t00-001-tr.html)
Procedure Title	Troubleshooting Procedures and Techniques
Update Reason	
Date	22-Jul-2009
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-005-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-005-tr.html)
Procedure Title	Bearings, Connecting Rod
Update Reason	
Date	22-Jul-2009
Section	Section L - Service Literature
Procedure Number	99-205-004 (/qs3/pubsys2/xml/en/procedures/99/99-205-004.html)
Procedure Title	Cummins Customized Parts Catalog
Update Reason	
Date	04-Aug-2009
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	56-016-001 (/qs3/pubsys2/xml/en/procedures/56/56-016-001.html)
Procedure Title	Engine Lifting Brackets
Update Reason	

Date	07-Aug-2009
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-006-017-shopds (/qs3/pubsys2/xml/en/procedures/56/56-006-017-shopds.html)
Procedure Title	Fuel Filter Head
Update Reason	
Date	07-Aug-2009
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-002-004-shopds (/qs3/pubsys2/xml/en/procedures/56/56-002-004-shopds.html)
Procedure Title	Cylinder Head
Update Reason	
Date	07-Aug-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-006-017-shopas (/qs3/pubsys2/xml/en/procedures/56/56-006-017-shopas.html)
Procedure Title	Fuel Filter Head
Update Reason	
Date	07-Aug-2009
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	56-006-017-tr (/qs3/pubsys2/xml/en/procedures/56/56-006-017-tr.html)
Procedure Title	Fuel Filter Head
Update Reason	
Date	19-Aug-2009
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-008-036-shopds (/qs3/pubsys2/xml/en/procedures/56/56-008-036-shopds.html)
Procedure Title	Fan Hub, Belt Driven
Update Reason	

Date	19-Aug-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-008-036-shopas (/qs3/pubsys2/xml/en/procedures/56/56-008-036-shopas.html)
Procedure Title	Fan Hub, Belt Driven
Update Reason	
Date	19-Aug-2009
Section	Section 2 - Cylinder Head - Group 02
Procedure Number	56-022-001_02 (/qs3/pubsys2/xml/en/procedures/56/56-022-001_02.html)
Procedure Title	Service Tools
Update Reason	
Date	19-Aug-2009
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-036-tr (/qs3/pubsys2/xml/en/procedures/56/56-008-036-tr.html)
Procedure Title	Fan Hub, Belt Driven
Update Reason	
Date	19-Aug-2009
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-128 (/qs3/pubsys2/xml/en/procedures/56/56-008-128.html)
Procedure Title	ECM Cooling Plate
Update Reason	
Date	10-Sep-2009
Section	Section i - Introduction
Procedure Number	99-204-002-shopds (/qs3/pubsys2/xml/en/procedures/99/99-204-002-shopds.html)
Procedure Title	About the Manual
Update Reason	

Date	10-Sep-2009
Section	Section i - Introduction
Procedure Number	99-204-003-shopds (/qs3/pubsys2/xml/en/procedures/99/99-204-003-shopds.html)
Procedure Title	How to Use the Manual
Update Reason	
Date	14-Sep-2009
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-021-tr (/qs3/pubsys2/xml/en/procedures/56/56-007-021-tr.html)
Procedure Title	Lubricating Oil High Pressure Relief Valve
Update Reason	
Date	14-Sep-2009
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-029 (/qs3/pubsys2/xml/en/procedures/56/56-007-029.html)
Procedure Title	Lubricating Oil Pressure Regulator (Main Rifle)
Update Reason	
Date	16-Sep-2009
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	56-016-004-tr (/qs3/pubsys2/xml/en/procedures/56/56-016-004-tr.html)
Procedure Title	Flexplate
Update Reason	
Date	18-Sep-2009
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-007-067-shopds (/qs3/pubsys2/xml/en/procedures/56/56-007-067-shopds.html)
Procedure Title	Eliminator™ Filter
Update Reason	

Date	18-Sep-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-007-067-shopas (/qs3/pubsys2/xml/en/procedures/56/56-007-067-shopas.html)
Procedure Title	Eliminator™ Filter
Update Reason	
Date	24-Sep-2009
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-007-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-007-tr.html)
Procedure Title	Bearings, Thrust
Update Reason	
Date	08-Oct-2009
Section	Section i - Introduction
Procedure Number	99-204-007-tr (/qs3/pubsys2/xml/en/procedures/99/99-204-007-tr.html)
Procedure Title	General Repair Instructions
Update Reason	
Date	09-Oct-2009
Section	Section 0 - Complete Engine - Group 00
Procedure Number	99-000-005-tr (/qs3/pubsys2/xml/en/procedures/99/99-000-005-tr.html)
Procedure Title	Engine Storage - Long Term
Update Reason	
Date	20-Oct-2009
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-007-031-shopds (/qs3/pubsys2/xml/en/procedures/56/56-007-031-shopds.html)
Procedure Title	Lubricating Oil Pump
Update Reason	

Date	20-Oct-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-007-031-shopas (/qs3/pubsys2/xml/en/procedures/56/56-007-031-shopas.html)
Procedure Title	Lubricating Oil Pump
Update Reason	
Date	20-Oct-2009
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-031-tr (/qs3/pubsys2/xml/en/procedures/56/56-007-031-tr.html)
Procedure Title	Lubricating Oil Pump
Update Reason	
Date	30-Oct-2009
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-001-054-shopds (/qs3/pubsys2/xml/en/procedures/56/56-001-054-shopds.html)
Procedure Title	Piston and Connecting Rod Assembly
Update Reason	
Date	30-Oct-2009
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-001-045-shopds (/qs3/pubsys2/xml/en/procedures/56/56-001-045-shopds.html)
Procedure Title	Piston and Cylinder Liner
Update Reason	
Date	08-Nov-2009
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-007-015-shopds (/qs3/pubsys2/xml/en/procedures/56/56-007-015-shopds.html)
Procedure Title	Lubricating Oil Filter Head
Update Reason	

Date	08-Nov-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-007-015-shopas (/qs3/pubsys2/xml/en/procedures/56/56-007-015-shopas.html)
Procedure Title	Lubricating Oil Filter Head
Update Reason	
Date	08-Nov-2009
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-015-tr (/qs3/pubsys2/xml/en/procedures/56/56-007-015-tr.html)
Procedure Title	Lubricating Oil Filter Head
Update Reason	
Date	10-Nov-2009
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-001-003-shopds (/qs3/pubsys2/xml/en/procedures/56/56-001-003-shopds.html)
Procedure Title	Accessory Drive Seal
Update Reason	
Date	10-Nov-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-001-003-shopas (/qs3/pubsys2/xml/en/procedures/56/56-001-003-shopas.html)
Procedure Title	Accessory Drive Seal
Update Reason	
Date	10-Nov-2009
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-001 (/qs3/pubsys2/xml/en/procedures/56/56-001-001.html)
Procedure Title	Alternator Drive Seal
Update Reason	

Date	10-Nov-2009
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-003-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-003-tr.html)
Procedure Title	Accessory Drive Seal
Update Reason	
Date	10-Nov-2009
Section	Section 10 - Air Intake System - Group 10
Procedure Number	56-010-041 (/qs3/pubsys2/xml/en/procedures/56/56-010-041.html)
Procedure Title	Turbocharger Coolant Hoses
Update Reason	
Date	10-Nov-2009
Section	Section 10 - Air Intake System - Group 10
Procedure Number	56-010-045-tr (/qs3/pubsys2/xml/en/procedures/56/56-010-045-tr.html)
Procedure Title	Turbocharger Oil Drain Line
Update Reason	
Date	10-Nov-2009
Section	Section 10 - Air Intake System - Group 10
Procedure Number	56-010-046-tr (/qs3/pubsys2/xml/en/procedures/56/56-010-046-tr.html)
Procedure Title	Turbocharger Oil Supply Line
Update Reason	
Date	17-Nov-2009
Section	Section L - Service Literature
Procedure Number	56-205-001-tr (/qs3/pubsys2/xml/en/procedures/56/56-205-001-tr.html)
Procedure Title	Additional Service Literature
Update Reason	

Date	24-Nov-2009
Section	Section V - Specifications
Procedure Number	56-018-016 (/qs3/pubsys2/xml/en/procedures/56/56-018-016.html)
Procedure Title	Fuel System
Update Reason	
Date	03-Dec-2009
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021530-t105-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t105-tr.html)
Procedure Title	Lubricating Oil Pressure Low
Update Reason	
Date	09-Dec-2009
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-011-007-shopds (/qs3/pubsys2/xml/en/procedures/56/56-011-007-shopds.html)
Procedure Title	Exhaust Manifold, Dry
Update Reason	
Date	09-Dec-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-011-007-shopas (/qs3/pubsys2/xml/en/procedures/56/56-011-007-shopas.html)
Procedure Title	Exhaust Manifold, Dry
Update Reason	
Date	09-Dec-2009
Section	Section 11 - Exhaust System - Group 11
Procedure Number	56-011-007-tr (/qs3/pubsys2/xml/en/procedures/56/56-011-007-tr.html)
Procedure Title	Exhaust Manifold, Dry
Update Reason	

Date	15-Dec-2009
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-014 (/qs3/pubsys2/xml/en/procedures/56/56-001-014.html)
Procedure Title	Connecting Rod
Update Reason	
Date	06-Jan-2010
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-007-030-shopds (/qs3/pubsys2/xml/en/procedures/56/56-007-030-shopds.html)
Procedure Title	Lubricating Oil Pressure Regulator (Piston Cooling)
Update Reason	
Date	06-Jan-2010
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-007-030-shopas (/qs3/pubsys2/xml/en/procedures/56/56-007-030-shopas.html)
Procedure Title	Lubricating Oil Pressure Regulator (Piston Cooling)
Update Reason	
Date	06-Jan-2010
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-006-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-006-tr.html)
Procedure Title	Bearings, Main
Update Reason	
Date	06-Jan-2010
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-012 (/qs3/pubsys2/xml/en/procedures/56/56-001-012.html)
Procedure Title	Camshaft Gear (Camshaft Installed)
Update Reason	

Date	06-Jan-2010
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-030-tr (/qs3/pubsys2/xml/en/procedures/56/56-007-030-tr.html)
Procedure Title	Lubricating Oil Pressure Regulator (Piston Cooling)
Update Reason	
Date	06-Jan-2010
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-067-tr (/qs3/pubsys2/xml/en/procedures/56/56-007-067-tr.html)
Procedure Title	Eliminator™ Filter
Update Reason	
Date	18-Jan-2010
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-022-001_00-shopas (/qs3/pubsys2/xml/en/procedures/56/56-022-001_00-shopas.html)
Procedure Title	Service Tools
Update Reason	
Date	18-Jan-2010
Section	Section 0 - Complete Engine - Group 00
Procedure Number	56-022-001_00-tr (/qs3/pubsys2/xml/en/procedures/56/56-022-001_00-tr.html)
Procedure Title	Service Tools
Update Reason	
Date	21-Jan-2010
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-007-063-shopds (/qs3/pubsys2/xml/en/procedures/56/56-007-063-shopds.html)
Procedure Title	Pre-Lubricating Oil Pump
Update Reason	

Date	21-Jan-2010
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-001-016-shopds (/qs3/pubsys2/xml/en/procedures/56/56-001-016-shopds.html)
Procedure Title	Crankshaft
Update Reason	
Date	21-Jan-2010
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-001-016-shopas (/qs3/pubsys2/xml/en/procedures/56/56-001-016-shopas.html)
Procedure Title	Crankshaft
Update Reason	
Date	21-Jan-2010
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-007-063-shopas (/qs3/pubsys2/xml/en/procedures/56/56-007-063-shopas.html)
Procedure Title	Pre-Lubricating Oil Pump
Update Reason	
Date	21-Jan-2010
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-016-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-016-tr.html)
Procedure Title	Crankshaft
Update Reason	
Date	21-Jan-2010
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-063-tr (/qs3/pubsys2/xml/en/procedures/56/56-007-063-tr.html)
Procedure Title	Pre-Lubricating Oil Pump
Update Reason	

Date	22-Jan-2010
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-013-tr (/qs3/pubsys2/xml/en/procedures/56/56-008-013-tr.html)
Procedure Title	Coolant Thermostat
Update Reason	
Date	25-Jan-2010
Section	Section i - Introduction
Procedure Number	99-204-006-tr (/qs3/pubsys2/xml/en/procedures/99/99-204-006-tr.html)
Procedure Title	General Safety Instructions
Update Reason	
Date	25-Jan-2010
Section	Section V - Specifications
Procedure Number	99-018-005 (/qs3/pubsys2/xml/en/procedures/99/99-018-005.html)
Procedure Title	Drive Belt Tension
Update Reason	
Date	25-Jan-2010
Section	Section V - Specifications
Procedure Number	99-018-009 (/qs3/pubsys2/xml/en/procedures/99/99-018-009.html)
Procedure Title	Capscrew Markings and Torque Values
Update Reason	
Date	01-Feb-2010
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-001-010-shopas (/qs3/pubsys2/xml/en/procedures/56/56-001-010-shopas.html)
Procedure Title	Camshaft Bushings
Update Reason	

Date	01-Feb-2010
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-010-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-010-tr.html)
Procedure Title	Camshaft Bushings
Update Reason	
Date	11-Feb-2010
Section	Section E - Engine and System Identification
Procedure Number	56-100-002-tr (/qs3/pubsys2/xml/en/procedures/56/56-100-002-tr.html)
Procedure Title	Engine Diagrams
Update Reason	
Date	11-Feb-2010
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-008-062-shopds (/qs3/pubsys2/xml/en/procedures/56/56-008-062-shopds.html)
Procedure Title	Water Pump
Update Reason	
Date	11-Feb-2010
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-008-109-shopds (/qs3/pubsys2/xml/en/procedures/56/56-008-109-shopds.html)
Procedure Title	Low-Temperature Aftercooler (LTA) Water Pump
Update Reason	
Date	11-Feb-2010
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-008-109-shopas (/qs3/pubsys2/xml/en/procedures/56/56-008-109-shopas.html)
Procedure Title	Low-Temperature Aftercooler (LTA) Water Pump
Update Reason	

Date	11-Feb-2010
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-008-062-shopas (/qs3/pubsys2/xml/en/procedures/56/56-008-062-shopas.html)
Procedure Title	Water Pump
Update Reason	
Date	11-Feb-2010
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-062-tr (/qs3/pubsys2/xml/en/procedures/56/56-008-062-tr.html)
Procedure Title	Water Pump
Update Reason	
Date	11-Feb-2010
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-109-tr (/qs3/pubsys2/xml/en/procedures/56/56-008-109-tr.html)
Procedure Title	Low-Temperature Aftercooler (LTA) Water Pump
Update Reason	
Date	11-Feb-2010
Section	Section 10 - Air Intake System - Group 10
Procedure Number	56-010-033-tr (/qs3/pubsys2/xml/en/procedures/56/56-010-033-tr.html)
Procedure Title	Turbocharger
Update Reason	
Date	11-Feb-2010
Section	Section 10 - Air Intake System - Group 10
Procedure Number	56-010-143-tr (/qs3/pubsys2/xml/en/procedures/56/56-010-143-tr.html)
Procedure Title	Air Shutoff Valve
Update Reason	

Date	15-Feb-2010
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-016-005-shopds (/qs3/pubsys2/xml/en/procedures/56/56-016-005-shopds.html)
Procedure Title	Flywheel
Update Reason	
Date	15-Feb-2010
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-016-005-shopas (/qs3/pubsys2/xml/en/procedures/56/56-016-005-shopas.html)
Procedure Title	Flywheel
Update Reason	
Date	15-Feb-2010
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	56-016-005-tr (/qs3/pubsys2/xml/en/procedures/56/56-016-005-tr.html)
Procedure Title	Flywheel
Update Reason	
Date	18-Feb-2010
Section	Section 5 - Fuel System - Group 05
Procedure Number	102-005-232 (/qs3/pubsys2/xml/en/procedures/102/102-005-232.html)
Procedure Title	Fuel Pump Pressurizing Assembly
Update Reason	
Date	22-Feb-2010
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-001-054-shopas (/qs3/pubsys2/xml/en/procedures/56/56-001-054-shopas.html)
Procedure Title	Piston and Connecting Rod Assembly
Update Reason	

Date	22-Feb-2010
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-001-045-shopas (/qs3/pubsys2/xml/en/procedures/56/56-001-045-shopas.html)
Procedure Title	Piston and Cylinder Liner
Update Reason	
Date	22-Feb-2010
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-045-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-045-tr.html)
Procedure Title	Piston and Cylinder Liner
Update Reason	
Date	22-Feb-2010
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-054-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-054-tr.html)
Procedure Title	Piston and Connecting Rod Assembly
Update Reason	
Date	25-Feb-2010
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021530-t102-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t102-tr.html)
Procedure Title	Lubricating Oil Consumption Excessive
Update Reason	
Date	24-Mar-2010
Section	Section i - Introduction
Procedure Number	99-204-009 (/qs3/pubsys2/xml/en/procedures/99/99-204-009.html)
Procedure Title	Acronyms and Abbreviations
Update Reason	

Date	05-Apr-2010
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021530-t027-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t027-tr.html)
Procedure Title	Crankcase Gases (Blowby) Excessive
Update Reason	
Date	08-Apr-2010
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-002-004-shopas (/qs3/pubsys2/xml/en/procedures/56/56-002-004-shopas.html)
Procedure Title	Cylinder Head
Update Reason	
Date	08-Apr-2010
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	102-001-026 (/qs3/pubsys2/xml/en/procedures/102/102-001-026.html)
Procedure Title	Cylinder Block
Update Reason	
Date	08-Apr-2010
Section	Section 2 - Cylinder Head - Group 02
Procedure Number	56-002-004-tr (/qs3/pubsys2/xml/en/procedures/56/56-002-004-tr.html)
Procedure Title	Cylinder Head
Update Reason	
Date	14-Apr-2010
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-005-016-shopds (/qs3/pubsys2/xml/en/procedures/56/56-005-016-shopds.html)
Procedure Title	Fuel Pump
Update Reason	

Date	14-Apr-2010
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-005-016-shopas (/qs3/pubsys2/xml/en/procedures/56/56-005-016-shopas.html)
Procedure Title	Fuel Pump
Update Reason	
Date	14-Apr-2010
Section	Section 5 - Fuel System - Group 05
Procedure Number	56-005-016-tr (/qs3/pubsys2/xml/en/procedures/56/56-005-016-tr.html)
Procedure Title	Fuel Pump
Update Reason	
Date	27-Apr-2010
Section	Section 0 - Complete Engine - Group 00
Procedure Number	56-000-002 (/qs3/pubsys2/xml/en/procedures/56/56-000-002.html)
Procedure Title	Engine Installation
Update Reason	
Date	30-Apr-2010
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-001-047-shopds (/qs3/pubsys2/xml/en/procedures/56/56-001-047-shopds.html)
Procedure Title	Piston Rings
Update Reason	
Date	30-Apr-2010
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-001-047-shopas (/qs3/pubsys2/xml/en/procedures/56/56-001-047-shopas.html)
Procedure Title	Piston Rings
Update Reason	

Date	30-Apr-2010
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-047-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-047-tr.html)
Procedure Title	Piston Rings
Update Reason	
Date	05-May-2010
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	56-006-051-tr (/qs3/pubsys2/xml/en/procedures/56/56-006-051-tr.html)
Procedure Title	Injector Supply Lines (High Pressure)
Update Reason	
Date	11-May-2010
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-030-tr (/qs3/pubsys2/xml/en/procedures/56/56-008-030-tr.html)
Procedure Title	Fan Drive Idler Pulley Assembly
Update Reason	
Date	14-May-2010
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-007-040-shopds (/qs3/pubsys2/xml/en/procedures/56/56-007-040-shopds.html)
Procedure Title	Lubricating Oil Transfer Tube
Update Reason	
Date	14-May-2010
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-007-040-shopas (/qs3/pubsys2/xml/en/procedures/56/56-007-040-shopas.html)
Procedure Title	Lubricating Oil Transfer Tube
Update Reason	

Date	14-May-2010
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-040-tr (/qs3/pubsys2/xml/en/procedures/56/56-007-040-tr.html)
Procedure Title	Lubricating Oil Transfer Tube
Update Reason	
Date	19-May-2010
Section	Section F - Familiarization
Procedure Number	56-200-003 (/qs3/pubsys2/xml/en/procedures/56/56-200-003.html)
Procedure Title	Flow Diagram, Cooling System
Update Reason	
Date	21-May-2010
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-008-029-shopds (/qs3/pubsys2/xml/en/procedures/56/56-008-029-shopds.html)
Procedure Title	Fan Drive Idler Arm Assembly
Update Reason	
Date	21-May-2010
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-008-029-shopas (/qs3/pubsys2/xml/en/procedures/56/56-008-029-shopas.html)
Procedure Title	Fan Drive Idler Arm Assembly
Update Reason	
Date	21-May-2010
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-029-tr (/qs3/pubsys2/xml/en/procedures/56/56-008-029-tr.html)
Procedure Title	Fan Drive Idler Arm Assembly
Update Reason	

Date	27-May-2010
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-006-026-shopds (/qs3/pubsys2/xml/en/procedures/56/56-006-026-shopds.html)
Procedure Title	Injector
Update Reason	

Date	27-May-2010
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-006-026-shopas (/qs3/pubsys2/xml/en/procedures/56/56-006-026-shopas.html)
Procedure Title	Injector
Update Reason	

Date	27-May-2010
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	56-006-026-tr (/qs3/pubsys2/xml/en/procedures/56/56-006-026-tr.html)
Procedure Title	Injector
Update Reason	

Date	23-Jun-2010
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-006-015-shopds (/qs3/pubsys2/xml/en/procedures/56/56-006-015-shopds.html)
Procedure Title	Fuel Filter (Spin-On Type)
Update Reason	

Date	23-Jun-2010
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-006-015-shopas (/qs3/pubsys2/xml/en/procedures/56/56-006-015-shopas.html)
Procedure Title	Fuel Filter (Spin-On Type)
Update Reason	

Date	23-Jun-2010
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	56-006-015-tr (/qs3/pubsys2/xml/en/procedures/56/56-006-015-tr.html)
Procedure Title	Fuel Filter (Spin-On Type)
Update Reason	
Date	25-Aug-2010
Section	Section 5 - Fuel System - Group 05
Procedure Number	101-005-232 (/qs3/pubsys2/xml/en/procedures/101/101-005-232.html)
Procedure Title	Fuel Pump Pressurizing Assembly
Update Reason	
Date	27-Sep-2010
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-027 (/qs3/pubsys2/xml/en/procedures/56/56-001-027.html)
Procedure Title	Cylinder Block and Liner Seats
Update Reason	Revised machining specifications for inserting an upper counterbore salvage sleeve and added additional final machine step.
Date	23-Jun-2010
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	56-006-026-tr (/qs3/pubsys2/xml/en/procedures/56/56-006-026-tr.html)
Procedure Title	Injector
Update Reason	Updated Initial Check section with new service tool.

Date	27-Sep-2010
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-045-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-045-tr.html)
Procedure Title	Piston and Cylinder Liner
Update Reason	Added procedure reference to the Remove and Install sections.

Date	15-Jan-2004
Section	Section 2 - Cylinder Head - Group 02
Procedure Number	56-002-004-tr (/qs3/pubsys2/xml/en/procedures/56/56-002-004-tr.html)
Procedure Title	Cylinder Head
Update Reason	Updated technical content of Vacuum Test section.

Date	23-Jun-2010
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	56-022-001_06 (/qs3/pubsys2/xml/en/procedures/56/56-022-001_06.html)
Procedure Title	Service Tools
Update Reason	Updated service tools with injector tester.10

Date	8-Dec-2010
Section	Section 2 - Cylinder Head - Group 02
Procedure Number	56-002-004-tr (/qs3/pubsys2/xml/en/procedures/56/56-002-004-tr.html)
Procedure Title	Cylinder Head
Update Reason	Updated procedure to include inspection steps for new bolt coating.

Date	10-Dec-2010
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	56-003-006-tr (/qs3/pubsys2/xml/en/procedures/56/56-003-006-tr.html)
Procedure Title	Overhead Set (OBC)
Update Reason	Updated torque specifications for removing the feeler gauge.

Date	19-Nov-2010
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-008 (/qs3/pubsys2/xml/en/procedures/56/56-001-008.html)
Procedure Title	Camshaft
Update Reason	Updated procedure to indicate that the run-out specification applies to all journals individually.

Date	28-Jan-2011
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-006 (/qs3/pubsys2/xml/en/procedures/56/56-001-006.html)
Procedure Title	Bearings, Main
Update Reason	Updated lubrication of capscrew head and threads instructions.

Date	07-Jan-2011
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-016-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-016-tr.html)
Procedure Title	Crankshaft
Update Reason	Added note on usage of QSK45 tungsten counterweighted crankshaft in the Install section.

Date	10-Feb-2011
Section	Section 16 - Mounting Adaptations- Group 16
Procedure Number	56-016-002-tr (/qs3/pubsys2/xml/en/procedures/56/56-016-002-tr.html)
Procedure Title	Engine Support Bracket Front
Update Reason	Added statement in the Install section to direct the user to the OEM service manual for torque specifications.

Date	10-Feb-2011
Section	Section 16 - Mounting Adaptations- Group 16
Procedure Number	56-016-006-tr (/qs3/pubsys2/xml/en/procedures/56/56-016-006-tr.html)
Procedure Title	Flywheel Housing
Update Reason	Note added to the Install step to clarify small and large flywheel housing assemblies.

Date	10-March-2011
Section	Section 2 - Cylinder Head
Procedure Number	15-002-004-tr (/qs3/pubsys2/xml/en/procedures/15/15-002-004-tr.html)
Procedure Title	Cylinder Head
Update Reason	Updated procedure to include instructions to remove and install a tamper proof seal in the cylinder head procedure.

Date	10-Mar-2011
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-033-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-033-tr.html)
Procedure Title	Gear Housing, Front
Update Reason	Addition of Loctite™ on mounting capscrew in Install section.

Date	21-Mar-2011
Section	Section 9 - Drive Units - Group 09
Procedure Number	56-009-016-tr (/qs3/pubsys2/xml/en/procedures/56/56-009-016-tr.html)
Procedure Title	Hydraulic Pump Drive
Update Reason	Updated the Remove, Disassemble, Clean and Inspect for Reuse, Assemble, and Install sections.

Date	21-Mar-2011
Section	Section 9 - Drive Units - Group 09
Procedure Number	56-009-019-tr (/qs3/pubsys2/xml/en/procedures/56/56-009-019-tr.html)
Procedure Title	Hydraulic Pump Drive Gear and Shaft
Update Reason	Added procedure to outline.

Date	05-Apr-2011
Section	Section 1 - Cylinder Block
Procedure Number	56-001-005-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-005-tr.html)
Procedure Title	Bearings, Connecting Rod
Update Reason	Added Note to Preparatory Steps and added, lubricate the capscrew flange and threads.

Date	12-Apr-2011
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-040-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-040-tr.html)
Procedure Title	Idler Gear, Water Pump
Update Reason	Added idler gear end clearance specifications in the Install step.

Date	25-Apr-2011
Section	Section 9 - Drive Units - Group 09
Procedure Number	56-009-004-tr (/qs3/pubsys2/xml/en/procedures/56/56-009-004-tr.html)
Procedure Title	Accessory Drive Pulley
Update Reason	Corrected adapter part number and added the adapter tool to corresponding stepblock graphic.

Date	01-Jun-2011
Section	Section 5 - Fuel System - Group 05
Procedure Number	56-005-016-tr (/qs3/pubsys2/xml/en/procedures/56/56-005-016-tr.html)
Procedure Title	Fuel Pump
Update Reason	Added General Information Section.

Date	08-Jun-2011
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-022-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-022-tr.html)
Procedure Title	Crankshaft Pulley
Update Reason	Updated procedure to include inspection process for wear on the crankshaft pulley.

Date	11-July-2011
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-007-tr (/qs3/pubsys2/xml/en/procedures/56/56-008-007-tr.html)
Procedure Title	Coolant Filter Head
Update Reason	Added step to drain coolant before removing the filter head.

Date	25-Jul-2011
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	56-003-006-tr (/qs3/pubsys2/xml/en/procedures/56/56-003-006-tr.html)
Procedure Title	Overhead Set (OBC)
Update Reason	Updated torque specifications for tightening the locknut, as well as updating the corresponding stepblock graphic.
Date	25-Oct-2011
Section	Section 5 - Fuel System - Group 05
Procedure Number	56-005-016-tr (/qs3/pubsys2/xml/en/procedures/56/56-005-016-tr.html)
Procedure Title	Fuel Pump
Update Reason	Update procedure links in the Clean and Inspect for Reuse section.
Date	25-Oct-2011
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021530-t108-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t108-tr.html)
Procedure Title	Lubricating or Transmission Oil in the Coolant
Update Reason	Revised turbocharger bearing housing is cracked or porous step.
Date	07-Nov-2011
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-006-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-006-tr.html)
Procedure Title	Bearings, Main
Update Reason	Revise reference for crankshaft end clearance specification.

Date	07-Nov-2011
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-007-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-007-tr.html)
Procedure Title	Bearings, Thrust
Update Reason	Added end clearance measurement techniques once engine is installed into an application.

Date	14-Nov-2011
Section	Section 5 - Fuel System - Group 05
Procedure Number	56-005-016-tr (/qs3/pubsys2/xml/en/procedures/56/56-005-016-tr.html)
Procedure Title	Fuel Pump
Update Reason	Revised fuel rail pressure sensor torque value.

Date	07-Dec-2011
Section	Section 1 - Cylinder Block
Procedure Number	56-001-045-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-045-tr.html)
Procedure Title	Piston and Cylinder Liner
Update Reason	Install Step added: Note added when using straight split connecting rod and angle split connecting rods.

Date	07-Dec-2011
Section	Section 1 - Cylinder Block
Procedure Number	56-001-054-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-054-tr.html)
Procedure Title	Piston and Connecting Rod Assembly
Update Reason	Install Steps added: Note added when using straight split connecting rod and angle split connecting rods.

Date	05-Dec-2011
Section	Section 08 - Cooling System
Procedure Number	56-008-062-tr (/qs3/pubsys2/xml/en/procedures/56/56-008-062-tr.html)
Procedure Title	Water Pump
Update Reason	Assemble Step, revised text to install the oil seal with the stepped lip facing down towards the impeller.

Date	01-Feb-2012
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	56-003-006-tr (/qs3/pubsys2/xml/en/procedures/56/56-003-006-tr.html)
Procedure Title	Overhead Set (OBC)
Update Reason	Updated to include torque value for setting injector adjusting screw when using adapter service tool.

Date	20-Feb-2012
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021530-t021-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t021-tr.html)
Procedure Title	Coolant Loss - Internal
Update Reason	Add node: Transmission oil cooler or torque converter cooler is leaking.

Date	08-Mar-2012
Section	Section 3 - Rocker Lever Housing
Procedure Number	56-003-013-tr (/qs3/pubsys2/xml/en/procedures/56/56-003-013-tr.html)
Procedure Title	Rocker Lever Housing
Update Reason	Revised Remove Step, adding the use of the Water Tube Driver, ST-1319.

Date	22-Mar-2012
Section	Section V - Maintenance Guidelines
Procedure Number	50-018-017 (/qs3/pubsys2/xml/en/procedures/50/50-018-017.html)
Procedure Title	Lubricating Oil System
Update Reason	Added specifications: Sump Configuration - System Capacity.
Date	26-Apr-2012
Section	Section 2 - Cylinder Head - Group 02
Procedure Number	56-002-004-tr (/qs3/pubsys2/xml/en/procedures/56/56-002-004-tr.html)
Procedure Title	Cylinder Head
Update Reason	Added valve designation in the Grind Step and drop gauge testing and repair of valve guide in Assembly Step.
Date	30-Apr-2012
Section	Section 5 - Fuel System - Group 05
Procedure Number	56-005-016-tr (/qs3/pubsys2/xml/en/procedures/56/56-005-016-tr.html)
Procedure Title	Fuel Pump
Update Reason	Added information to General Information section about relieving rail pressure before removing parts from the fuel pump.
Date	02-May-2012
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-028-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-028-tr.html)
Procedure Title	Cylinder Liner
Update Reason	Added tightening specifications for the liner installation tool, Part Number 3163329.

Date	23-May-2012
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-016-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-016-tr.html)
Procedure Title	Crankshaft
Update Reason	Updated procedure by adding information to clarify the use of Scotch-Brite™ pads or crocus cloth in the Clean and Inspect section.

Date	05-Jun-2012
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-007-tr (/qs3/pubsys2/xml/en/procedures/56/56-007-007-tr.html)
Procedure Title	Lubricating Oil Cooler Element
Update Reason	Revised Clean and Inspect for Reuse step

Date	27-Jun-2012
Section	Section 6 - Injectors and Fuel Lines
Procedure Number	56-006-025-tr (/qs3/pubsys2/xml/en/procedures/56/56-006-025-tr.html)
Procedure Title	Static Injection Timing
Update Reason	Changed Control Part List (CPL) Manual, Bulletin to 4021328, added refer to Procedure 99-850-013.

Date	05-Jul-2012
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-028-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-028-tr.html)
Procedure Title	Cylinder Liner
Update Reason	Updated the Remove step to add instruction that liner seals must be discarded if removed from the liner.

Date	21-Jul-2012
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	102-001-026 (/qs3/pubsys2/xml/en/procedures/102/102-001-026.html)
Procedure Title	Cylinder Block
Update Reason	Recalculated and standardized engine block height specifications.

Date	15-Jul-2005
Section	Section E - Engine and System Identification
Procedure Number	56-100-001 (/qs3/pubsys2/xml/en/procedures/56/56-100-001.html)
Procedure Title	Engine Identification
Update Reason	Revised engine dataplate location information. The location is presently on the left bank side of the front gear cover.

Date	23-Jul-2012
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-043-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-043-tr.html)
Procedure Title	Cylinder Block
Update Reason	Added General Information stepblock with new piston information.

Date	23-Jul-2012
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-047-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-047-tr.html)
Procedure Title	Cylinder Block
Update Reason	Added new piston information.

Date	14-Aug-2012
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-016-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-016-tr.html)
Procedure Title	Crankshaft
Update Reason	Updated Magnetic Crack Inspection to current standard.

Date	20-Aug-2012
Section	Section TS - Troubleshooting System
Procedure Number	4021530-t102-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t102-tr.html)
Procedure Title	Lubricating Oil Consumption Excessive
Update Reason	Changed first step to include inspection of OEM components for external oil leaks.

Date	20-Aug-2012
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-022-001_08-tr (/qs3/pubsys2/xml/en/procedures/56/56-022-001_08-tr.html)
Procedure Title	Service Tools
Update Reason	Update service tool list.

Date	20-Aug-2012
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-062-tr (/qs3/pubsys2/xml/en/procedures/56/56-008-062-tr.html)
Procedure Title	Water Pump
Update Reason	Update service tool part numbers.

Date	04-Sep-2012
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-062-tr (/qs3/pubsys2/xml/en/procedures/56/56-008-062-tr.html)
Procedure Title	Water Pump
Update Reason	Added water pump weep hole tube and filter information.

Date	24-Oct-2012
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	56-003-011-tr (/qs3/pubsys2/xml/en/procedures/56/56-003-011-tr.html)
Procedure Title	Rocker Lever Cover
Update Reason	In the electronically actuated injector section, a statement is added to discard the o-ring after removing it from the rocker lever cover plate.

Date	28-Nov-2012
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-062-tr (/qs3/pubsys2/xml/en/procedures/56/56-008-062-tr.html)
Procedure Title	Water Pump
Update Reason	Updated procedure on oil seal installation instructions to account for the new seal and difficulties installing it.

Date	03-Dec-2012
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-054-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-054-tr.html)
Procedure Title	Piston and Connecting Rod Assembly
Update Reason	Updated the text and graphic in the Remove and the Install steps to match present component configuration.

Date	03-Dec-2012
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-040-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-040-tr.html)
Procedure Title	Idler Gear, Water Pump
Update Reason	Updated the text and a graphic in the Install step to match present component configuration.
Date	06-Jan-2013
Section	Section 6 - Injectors
Procedure Number	56-022-001_06 (/qs3/pubsys2/xml/en/procedures/56/56-022-001_06.html)
Procedure Title	Fuel System Tester
Update Reason	Added Service Tool Part Number 4918612.
Date	11-Jan-2013
Section	Section 10 - Air Intake System - Group 10
Procedure Number	56-010-033-tr (/qs3/pubsys2/xml/en/procedures/56/56-010-033-tr.html)
Procedure Title	Turbocharger
Update Reason	Updated specifications and details in procedure.
Date	30-Jan-2013
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-062-tr (/qs3/pubsys2/xml/en/procedures/56/56-008-062-tr.html)
Procedure Title	Water Pump
Update Reason	Updated text and graphic in the Assemble Step to improve oil seal installation.

Date	30-Jan-2013
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-040-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-040-tr.html)
Procedure Title	Idler Gear, Water Pump
Update Reason	Added a new Caution statement and graphic related to the importance of the idler shaft orientation.

Date	30-Jan-2013
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-045-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-045-tr.html)
Procedure Title	Piston and Cylinder Liner
Update Reason	Updated text and graphic to improve the identification of the two connecting rod configurations.

Date	30-Jan-2013
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-054-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-054-tr.html)
Procedure Title	Piston and Connecting Rod Assembly
Update Reason	Updated text and graphic to improve the identification of the two connecting rod configurations.

Date	03-Feb-2013
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-007-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-007-tr.html)
Procedure Title	Bearings, Thrust
Update Reason	Install Step updated to specify installation and protrusion of dowel pin positioning thrust bearings on the main bearing cap and the saddle in the block.

Date	19-Apr-2013
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	56-006-020-tr (/qs3/pubsys2/xml/en/procedures/56/56-006-020-tr.html)
Procedure Title	Fuel Inlet Restriction
Update Reason	Revised the Fuel Inlet Restriction to included maximum OEM restriction at Stage 1 inlet.
Date	22-Apr-2013
Section	Section 5 - Fuel System - Group 05
Procedure Number	56-005-016-tr (/qs3/pubsys2/xml/en/procedures/56/56-005-016-tr.html)
Procedure Title	Fuel Pump
Update Reason	Added Flush section to procedure.
Date	03-May-2013
Section	Section 14 - Engine Testing - Group 14
Procedure Number	56-014-005-tr (/qs3/pubsys2/xml/en/procedures/56/56-014-005-tr.html)
Procedure Title	Engine Testing (Engine Dynamometer)
Update Reason	Corrected instructions to check and measure blowby gases on QSK45 and QSK60 engines.
Date	07-May-2013
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-607-tr (/qs3/pubsys2/xml/en/procedures/56/56-007-607-tr.html)
Procedure Title	Eliminator™ Filter
Update Reason	Updated procedure to conform with the suppliers method for the maintenance procedure.

Date	18-May-2013
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-022-001_07-tr (/qs3/pubsys2/xml/en/procedures/56/56-022-001_07-tr.html)
Procedure Title	Service Tools
Update Reason	The nylon strap has been added to the service tool page in Section 7.
Date	13-May-2013
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	56-003-001-tr (/qs3/pubsys2/xml/en/procedures/56/56-003-001-tr.html)
Procedure Title	Crankcase Breather (External)
Update Reason	Note is added to designate the correct position and direction of the blowby sensor during installation.
Date	13-May-2013
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	56-003-001-tr (/qs3/pubsys2/xml/en/procedures/56/56-003-001-tr.html)
Procedure Title	Crankcase Breather (External)
Update Reason	A statement is added to designate the correct position and direction of the blowby sensor during installation.
Date	13-May-2013
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	56-003-001-shopas (/qs3/pubsys2/xml/en/procedures/56/56-003-001-shopas.html)
Procedure Title	Crankcase Breather (External)
Update Reason	A statement is added to designate the correct position and direction of the blowby sensor during installation.

Date	07-May-2013
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-028-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-028-tr.html)
Procedure Title	Cylinder Liner
Update Reason	Updated the Measure step to revise the inside and outside diameter specifications for the cylinder liner.

Date	05-Jun-2013
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-013 (/qs3/pubsys2/xml/en/procedures/56/56-007-013.html)
Procedure Title	Lubricating Oil Filter (Spin-On)
Update Reason	Add information to entire procedure about the oil filter Power Gen oil bypass.

Date	01-Jul-2013
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-007-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-007-tr.html)
Procedure Title	Bearings, Thrust
Update Reason	Finishing Step added

Date	23-Jul-2013
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-027 (/qs3/pubsys2/xml/en/procedures/56/56-001-027.html)
Procedure Title	Cylinder Block and Liner Seats
Update Reason	Updated procedure with oversize cylinder liner specifications and installation requirements.

Date	23-Jul-2013
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-028-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-028-tr.html)
Procedure Title	Cylinder Liner
Update Reason	Updated procedure with oversize cylinder liner specifications and installation requirements.
Date	06-Aug-2013
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	56-006-020-tr (/qs3/pubsys2/xml/en/procedures/56/56-006-020-tr.html)
Procedure Title	Fuel Inlet Restriction
Update Reason	Revised the Maximum Fuel Inlet Restriction values for Stage 1 and Stage 2 filters.
Date	06-Aug-2013
Section	Section V - Maintenance Guidelines
Procedure Number	56-018-024 (/qs3/pubsys2/xml/en/procedures/56/56-018-024.html)
Procedure Title	Cummins®/Fleetguard® Filter Specifications
Update Reason	Updated filter specifications and part numbers.
Date	05-Aug-2013
Section	Section TT - Troubleshooting Performance Troubleshooting Tree - New Format)
Procedure Number	56-ttqsk60 (/qs3/pubsys2/xml/en/procedures/56/56-ttqsk60.html)
Procedure Title	Engine Performance Troubleshooting Tree
Update Reason	Guided Step 3H: Added, Repair fuel rail or leaking component to YES.

Date	13-Aug-2013
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	56-006-075-tr (/qs3/pubsys2/xml/en/procedures/56/56-006-075-tr.html)
Procedure Title	Fuel Filter (Stage 1)
Update Reason	Added information and illustration for FH239 fuel filter.
Date	26-Aug-2013
Section	Section 14 - Engine Testing - Group 14
Procedure Number	00-014-012 (/qs3/pubsys2/xml/en/procedures/00/00-014-012.html)
Procedure Title	Engine Compression
Update Reason	Updated Preparatory Step and Finishing Step procedure links.
Date	28-Aug-2013
Section	Section V - Maintenance Guidelines
Procedure Number	56-018-016 (/qs3/pubsys2/xml/en/procedures/56/56-018-016.html)
Procedure Title	Fuel System
Update Reason	Updated fuel inlet maximum restriction.
Date	06-Sep-2013
Section	Section 9 - Drive Units - Group 09
Procedure Number	56-009-001-tr (/qs3/pubsys2/xml/en/procedures/56/56-009-001-tr.html)
Procedure Title	Accessory Drive
Update Reason	The procedure contained the incorrect thermal specification for heating the gear in the oven before installation on the drive shaft.

Date	16-Sep-2013
Section	Section 5 - Fuel System - Group 05
Procedure Number	56-005-016 (/qs3/pubsys2/xml/en/procedures/56/56-005-016.html)
Procedure Title	Fuel Pump
Update Reason	The procedure was revised by adding a clear explanation how to orientate the gear on the shaft during pump assembly.
Date	10-Sep-2013
Section	Section 9 - Drive Units - Group 09
Procedure Number	56-009-029-tr (/qs3/pubsys2/xml/en/procedures/56/56-009-029-tr.html)
Procedure Title	Water Pump Drive
Update Reason	Updated the end clearance specification for the water pump drive. Max value changed from .33 mm [0.013 in] to 0.21 mm [0.008 in].
Date	05-Nov-2013
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	102-016-008 (/qs3/pubsys2/xml/en/procedures/102/102-016-008.html)
Procedure Title	Flywheel Ring Gear
Update Reason	Updated procedure for improved clarity and safety.
Date	16-Dec-2013
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-005-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-005-tr.html)
Procedure Title	Bearings, Connecting Rod
Update Reason	Added information about visual inspection of the bearings in the Clean and Inspect for Reuse step.

Date	16-Dec-2013
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-006-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-006-tr.html)
Procedure Title	Bearings, Main
Update Reason	Added information about visual inspection of the bearings in the Clean and Inspect for Reuse step.
Date	08-Jan-2014
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	56-006-020-tr (/qs3/pubsys2/xml/en/procedures/56/56-006-020-tr.html)
Procedure Title	Fuel Inlet Restriction
Update Reason	Correction to the Initial Check section.
Date	14-Jan-2014
Section	Section TS - Troubleshooting System
Procedure Number	4021530-t102-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t102-tr.html)
Procedure Title	Lubricating Oil Consumption Excessive
Update Reason	Added step three to TS tree. Verifying original equipment manufacturer (OEM) lubricating oil system components.
Date	03-Feb-2014
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-047-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-047-tr.html)
Procedure Title	Piston Rings
Update Reason	Added note to Measure Step.

Date	17-Mar-2014
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	102-006-061 (/qs3/pubsys2/xml/en/procedures/102/102-006-061.html)
Procedure Title	Fuel Pressure Relief Valve
Update Reason	Added the Fuel Pressure Valve Return Flow Test

Date	05-May-2014
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-023-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-023-tr.html)
Procedure Title	Crankshaft Seal, Front
Update Reason	The procedures has been revised by adding a requirement to discard the removed crankshaft seal.

Date	05-May-2014
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-024-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-024-tr.html)
Procedure Title	Crankshaft Seal, Rear
Update Reason	The procedures has been revised by adding a requirement to discard the removed crankshaft seal.

Date	23-Apr-2014
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-010-002-shopds (/qs3/pubsys2/xml/en/procedures/56/56-010-002-shopds.html)
Procedure Title	Aftercooler Assembly
Update Reason	Commonized pressure sensor names to 'intake manifold temperature' and 'intake manifold pressure'. Also corrected torque value for capscrews used for connection between front and rear aftercooler.

Date	23-Apr-2014
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-010-002-shopds (/qs3/pubsys2/xml/en/procedures/56/56-010-002-shopds.html)
Procedure Title	Aftercooler Assembly
Update Reason	Commonized pressure sensor names to 'intake manifold temperature' and 'intake manifold pressure'. Also corrected torque value for capscrews used for connection between front and rear aftercooler.

Date	23-Apr-2014
Section	Section 10 -Air Intake System - Group 10
Procedure Number	56-010-002-tr (/qs3/pubsys2/xml/en/procedures/56/56-010-002-tr.html)
Procedure Title	Aftercooler Assembly
Update Reason	Commonized pressure sensor names to 'intake manifold temperature' and 'intake manifold pressure'. Also corrected torque value for capscrews used for connection between front and rear aftercooler.

Date	28-Apr-2014
Section	Section 10 - Air Intake System - Group 10
Procedure Number	56-010-033-tr (/qs3/pubsys2/xml/en/procedures/56/56-010-033-tr.html)
Procedure Title	Turbocharger
Update Reason	Holset® turbocharger number HE851 is being added to the Compressor Impeller Axial Endplay specification table and to the Compressor Impeller Radial Endplay specification table.

Date	10-Jul-2014
Section	Section 11 - Exhaust System - Group 11
Procedure Number	56-011-001-tr (/qs3/pubsys2/xml/en/procedures/56/56-011-001-tr.html)
Procedure Title	Exhaust Connection Pipe
Update Reason	Updated exhaust connection to bellows torque values.

Date	10-July-2014
Section	Section 9 - Drive Units - Group 09
Procedure Number	56-009-011 (/qs3/pubsys2/xml/en/procedures/56/56-009-011.html)
Procedure Title	Fuel Pump Drive
Update Reason	Added electronically actuated injectors to procedure for technicians clarification.

Date	04-Sep-2014
Section	Section 3 Rocker Levers - Group 03
Procedure Number	56-003-011-tr (/qs3/pubsys2/xml/en/procedures/56/56-003-011-tr.html)
Procedure Title	Rocker Lever Cover
Update Reason	Added instructions to pry evenly on the rocker lever cover.

Date	08-Oct-2014
Section	Section TS - Troubleshooting Symptoms - Group t00
Procedure Number	4021530-t107-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t107-tr.html)
Procedure Title	Lubricating Oil Temperature Above Specification
Update Reason	Updated TS tree with correct wording for field service on lubricating oil above or below specification.

Date	24-Oct-2014
Section	Section 9 - Drive Units - Group 09
Procedure Number	56-009-035-tr (/qs3/pubsys2/xml/en/procedures/56/56-009-035-tr.html)
Procedure Title	Engine Barring Device
Update Reason	Added reuse criteria to procedure.
Date	10-Sep-2014
Section	Section F - Familiarization
Procedure Number	56-200-002 (/qs3/pubsys2/xml/en/procedures/56/56-200-002.html)
Procedure Title	Flow Diagram, Lubricating Oil System
Update Reason	Revised oil flow to and through the fuel pump accessory drive.
Date	27-Oct-2014
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	56-016-004-tr (/qs3/pubsys2/xml/en/procedures/56/56-016-004-tr.html)
Procedure Title	Flexplate
Update Reason	Corrected the Clean and Inspect for Reuse section to reflect changing the ring gear instead of entire flexplate.
Date	17-Sep-2014
Section	Section 1 - Cylinder Block
Procedure Number	56-001-028-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-028-tr.html)
Procedure Title	Cylinder Liner
Update Reason	New specifications for Cylinder Liner Inside Diameter.

Date	10-Sep-2014
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-054-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-054-tr.html)
Procedure Title	Piston and Connecting Rod Assembly
Update Reason	Added text and graphics to Assembly section to improve accuracy of piston and connecting rod assembly.

Date	06-Jan-2015
Section	Section 9 - Drive Units - Group 09
Procedure Number	56-009-011 (/qs3/pubsys2/xml/en/procedures/56/56-009-011.html)
Procedure Title	Fuel Pump Drive
Update Reason	Corrected fuel pump drive shaft and accessory drive shaft measurements in the Clean and Inspect for Reuse steps.

Date	29-Jan-2015
Section	Section 14 Engine Testing - Group 14
Procedure Number	56-014-002 (/qs3/pubsys2/xml/en/procedures/56/56-014-002.html)
Procedure Title	Engine Testing (Chassis Dynamometer)
Update Reason	Added new section for engine blowby testing.

Date	29-Jan-2015
Section	Section 14 Engine Testing - Group 14
Procedure Number	56-014-005-tr (/qs3/pubsys2/xml/en/procedures/56/56-014-005-tr.html)
Procedure Title	Engine Testing (Engine Dynamometer)
Update Reason	Added new section for engine blowby testing.

Date	16-Feb-2015
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	56-006-012 (/qs3/pubsys2/xml/en/procedures/56/56-006-012.html)
Procedure Title	Fuel Drain Line Restriction
Update Reason	Defined instructions specifically for electronically controlled injectors.
Date	13-Feb-2015
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	56-006-020-tr (/qs3/pubsys2/xml/en/procedures/56/56-006-020-tr.html)
Procedure Title	Fuel Inlet Restriction
Update Reason	Added QSK60 graphics to clarify instructions.
Date	19-Feb-2015
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-016-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-016-tr.html)
Procedure Title	Crankshaft
Update Reason	Corrected the toqure specification for the 12.9 capscrews used to secure the crankshaft counterweights to the crankshaft.
Date	26-Feb-2015
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-011-007-shopas (/qs3/pubsys2/xml/en/procedures/56/56-011-007-shopas.html)
Procedure Title	Exhaust Manifold, Dry
Update Reason	Corrected the torque specifications for the exhaust bellows.

Date	26-Feb-2015
Section	Section 11 - Exhaust System - Group 11
Procedure Number	56-011-007-tr (/qs3/pubsys2/xml/en/procedures/56/56-011-007-tr.html)
Procedure Title	Exhaust Manifold, Dry
Update Reason	Corrected the torque specifications for the exhaust bellows.

Date	04-Mar-2015
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-045-tr (/qs3/pubsys2/xml/en/procedures/56/56-007-045-tr.html)
Procedure Title	Lubricating Oil Cooler Cover
Update Reason	Information about difference between old and new gaskets has been added to the procedure.

Date	05-Feb-2015
Section	Section 10 - Air Intake System
Procedure Number	56-010-031 (/qs3/pubsys2/xml/en/procedures/56/56-010-031.html)
Procedure Title	Ain Intake Restriction
Update Reason	Added Note: For containerized generator set application the air intake restriction measurement must be take relative to ambient pressure outside the container.

Date	25-Mar-2015
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-047-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-047-tr.html)
Procedure Title	Piston Rings
Update Reason	Corrected the Oil Ring gap for the Mechanically Actuated Injectors.

Date	Not Available
Section	front
Procedure Number	3666013-toc (/qs3/pubsys2/xml/en/manual/3666013/3666013-toc.html)
Procedure Title	Table of Contents
Update Reason	
Date	12-Mar-2002
Section	Section i - Introduction
Procedure Number	99-204-004 (/qs3/pubsys2/xml/en/procedures/99/99-204-004.html)
Procedure Title	Symbols
Update Reason	
Date	12-Mar-2002
Section	Section i - Introduction
Procedure Number	99-204-005 (/qs3/pubsys2/xml/en/procedures/99/99-204-005.html)
Procedure Title	Illustrations
Update Reason	
Date	14-Mar-2002
Section	Section 3 - Maintenance Procedures at Daily Interval
Procedure Number	99-103-999 (/qs3/pubsys2/xml/en/procedures/99/99-103-999.html)
Procedure Title	Daily Maintenance Procedures
Update Reason	
Date	14-Mar-2002
Section	Section 3 - Maintenance Procedures at Daily Interval
Procedure Number	99-006-043 (/qs3/pubsys2/xml/en/procedures/99/99-006-043.html)
Procedure Title	Fuel-Water Separator
Update Reason	

Date	14-Mar-2002
Section	Section 4 - Maintenance Procedures at Weekly Interval
Procedure Number	99-999-999 (/qs3/pubsys2/xml/en/procedures/99/99-999-999.html)
Procedure Title	Maintenance Procedures
Update Reason	
Date	14-Mar-2002
Section	Section 4 - Maintenance Procedures at Weekly Interval
Procedure Number	99-010-058 (/qs3/pubsys2/xml/en/procedures/99/99-010-058.html)
Procedure Title	Air Intake Piping
Update Reason	
Date	14-Mar-2002
Section	Section 4 - Maintenance Procedures at Weekly Interval
Procedure Number	99-012-021 (/qs3/pubsys2/xml/en/procedures/99/99-012-021.html)
Procedure Title	Air Tanks and Reservoirs
Update Reason	
Date	14-Mar-2002
Section	Section 5 - Maintenance Procedures at 250 Hours or 6 Months
Procedure Number	99-999-999 (/qs3/pubsys2/xml/en/procedures/99/99-999-999.html)
Procedure Title	Maintenance Procedures - Overview
Update Reason	

Date	14-Mar-2002
Section	Section 5 - Maintenance Procedures at 250 Hours or 6 Months
Procedure Number	99-003-018 (/qs3/pubsys2/xml/en/procedures/99/99-003-018.html)
Procedure Title	Crankcase Breather
Update Reason	
Date	14-Mar-2002
Section	Section 6 - Maintenance Procedures at 1500 Hours or 1 Year
Procedure Number	99-999-999 (/qs3/pubsys2/xml/en/procedures/99/99-999-999.html)
Procedure Title	Maintenance Procedures - Overview
Update Reason	
Date	14-Mar-2002
Section	Section 7 - Maintenance Procedures at 6000 Hours or 2 Years
Procedure Number	99-999-999 (/qs3/pubsys2/xml/en/procedures/99/99-999-999.html)
Procedure Title	Maintenance Procedure
Update Reason	
Date	14-Mar-2002
Section	Section 7 - Maintenance Procedures at 6000 Hours or 2 Years
Procedure Number	99-012-015 (/qs3/pubsys2/xml/en/procedures/99/99-012-015.html)
Procedure Title	Air Compressor Discharger Lines
Update Reason	

Date	03-Apr-2002
Section	Section TS - Troubleshooting Symptoms
Procedure Number	99-t00-002 (/qs3/pubsys2/xml/en/procedures/99/99-t00-002.html)
Procedure Title	Troubleshooting Symptom Charts
Update Reason	
Date	08-Oct-2002
Section	Section 5 - Maintenance Procedures at 250 Hours or 6 Months
Procedure Number	99-008-040 (/qs3/pubsys2/xml/en/procedures/99/99-008-040.html)
Procedure Title	Fan, Cooling
Update Reason	
Date	31-Oct-2002
Section	Section 1 - Operating Instructions
Procedure Number	00-101-014 (/qs3/pubsys2/xml/en/procedures/00/00-101-014.html)
Procedure Title	Normal Starting Procedure
Update Reason	
Date	13-Feb-2003
Section	Section 3 - Maintenance Procedures at Daily Interval
Procedure Number	99-010-015 (/qs3/pubsys2/xml/en/procedures/99/99-010-015.html)
Procedure Title	Air Cleaner Precleaner
Update Reason	
Date	21-Apr-2003
Section	Section D - System Diagrams
Procedure Number	00-200-999 (/qs3/pubsys2/xml/en/procedures/00/00-200-999.html)
Procedure Title	System Diagrams - Overview
Update Reason	

Date	26-Aug-2003
Section	Section 6 - Maintenance Procedures at 1500 Hours or 1 Year
Procedure Number	99-013-007 (/qs3/pubsys2/xml/en/procedures/99/99-013-007.html)
Procedure Title	Batteries
Update Reason	
Date	26-Aug-2003
Section	Section A - Adjustment, Repair, and Replacement
Procedure Number	99-013-009 (/qs3/pubsys2/xml/en/procedures/99/99-013-009.html)
Procedure Title	Battery Cables and Connections
Update Reason	
Date	29-Jan-2004
Section	Section 3 - Maintenance Procedures at Daily Interval
Procedure Number	99-008-067 (/qs3/pubsys2/xml/en/procedures/99/99-008-067.html)
Procedure Title	Seawater Strainer
Update Reason	
Date	02-Mar-2004
Section	Section 4 - Maintenance Procedures at Weekly Interval
Procedure Number	102-010-061 (/qs3/pubsys2/xml/en/procedures/102/102-010-061.html)
Procedure Title	Air Cleaner Element, Single Heavy-Duty Dry Type
Update Reason	

Date	02-Mar-2004
Section	Section 4 - Maintenance Procedures at Weekly Interval
Procedure Number	102-010-062 (/qs3/pubsys2/xml/en/procedures/102/102-010-062.html)
Procedure Title	Air Cleaner Element, Dual Heavy Duty Dry Type
Update Reason	
Date	02-Mar-2004
Section	Section 4 - Maintenance Procedures at Weekly Interval
Procedure Number	102-010-063 (/qs3/pubsys2/xml/en/procedures/102/102-010-063.html)
Procedure Title	Air Cleaner Element, Cartridge Type
Update Reason	
Date	02-Mar-2004
Section	Section A - Adjustment, Repair, and Replacement
Procedure Number	102-012-022 (/qs3/pubsys2/xml/en/procedures/102/102-012-022.html)
Procedure Title	Air Starting Motor
Update Reason	
Date	02-Mar-2004
Section	Section V - Maintenance Specifications
Procedure Number	102-018-004 (/qs3/pubsys2/xml/en/procedures/102/102-018-004.html)
Procedure Title	Coolant Recommendations and Specifications
Update Reason	

Date	03-Mar-2004
Section	Section V - Maintenance Specifications
Procedure Number	99-018-010 (/qs3/pubsys2/xml/en/procedures/99/99-018-010.html)
Procedure Title	Fraction, Decimal, Millimeter Conversions
Update Reason	
Date	03-Mar-2004
Section	Section V - Maintenance Specifications
Procedure Number	99-018-011 (/qs3/pubsys2/xml/en/procedures/99/99-018-011.html)
Procedure Title	Newton-Meter to Foot-Pound Conversions
Update Reason	
Date	03-Mar-2004
Section	Section V - Maintenance Specifications
Procedure Number	99-018-012 (/qs3/pubsys2/xml/en/procedures/99/99-018-012.html)
Procedure Title	Pipe Plug Torque Values
Update Reason	
Date	03-Mar-2004
Section	Section V - Maintenance Specifications
Procedure Number	99-018-013 (/qs3/pubsys2/xml/en/procedures/99/99-018-013.html)
Procedure Title	Tap-Drill Chart - U.S. Customary and Metric
Update Reason	
Date	03-Mar-2004
Section	Section V - Maintenance Specifications
Procedure Number	99-018-014 (/qs3/pubsys2/xml/en/procedures/99/99-018-014.html)
Procedure Title	Weights and Measures - Conversion Factors
Update Reason	

Date	06-Oct-2004
Section	Section E - Engine Identification
Procedure Number	18-100-001 (/qs3/pubsys2/xml/en/procedures/18/18-100-001.html)
Procedure Title	Engine Identification
Update Reason	
Date	19-Oct-2004
Section	Section 6 - Maintenance Procedures at 1500 Hours or 1 Year
Procedure Number	18-003-001 (/qs3/pubsys2/xml/en/procedures/18/18-003-001.html)
Procedure Title	Crankcase Breather, External
Update Reason	
Date	28-Sep-2005
Section	Section SS - Seasonal Storage (Marine Only)
Procedure Number	99-000-014 (/qs3/pubsys2/xml/en/procedures/99/99-000-014.html)
Procedure Title	Seasonal Storage
Update Reason	
Date	15-Feb-2006
Section	front
Procedure Number	refno (/qs3/pubsys2/xml/en/procedures//refno.html)
Procedure Title	Important Reference Numbers
Update Reason	
Date	20-Apr-2006
Section	Section 6 - Maintenance Procedures at 1500 Hours or 1 Year
Procedure Number	00-008-059 (/qs3/pubsys2/xml/en/procedures/00/00-008-059.html)
Procedure Title	Zinc Anode
Update Reason	

Date	04-May-2006
Section	Section i - Introduction
Procedure Number	99-204-001 (/qs3/pubsys2/xml/en/procedures/99/99-204-001.html)
Procedure Title	To the Owner and Operator
Update Reason	
Date	22-May-2006
Section	front
Procedure Number	om-frwd (/qs3/pubsys2/xml/en/manual/preface/om-frwd.html)
Procedure Title	Foreword
Update Reason	
Date	31-May-2006
Section	Section S - Service Assistance
Procedure Number	99-202-005 (/qs3/pubsys2/xml/en/procedures/99/99-202-005.html)
Procedure Title	Division and Regional Offices
Update Reason	
Date	27-Jun-2006
Section	Section L - Service Literature
Procedure Number	99-205-002 (/qs3/pubsys2/xml/en/procedures/99/99-205-002.html)
Procedure Title	Service Literature Ordering Location
Update Reason	
Date	14-Jul-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666013-t024-om (/qs3/pubsys2/xml/en/manual/3666013/3666013-t024-om.html)
Procedure Title	Coolant Temperature is Below Normal
Update Reason	

Date	14-Jul-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666013-t026-om (/qs3/pubsys2/xml/en/manual/3666013/3666013-t026-om.html)
Procedure Title	Coolant Temperature Above Normal
Update Reason	
Date	14-Jul-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666013-t026-155-om (/qs3/pubsys2/xml/en/manual/3666013/3666013-t026-155-om.html)
Procedure Title	Coolant Temperature Above Normal (Marine)
Update Reason	
Date	14-Jul-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666013-t043-om (/qs3/pubsys2/xml/en/manual/3666013/3666013-t043-om.html)
Procedure Title	Engine Hard to Start or Will Not Start (Exhaust Smoke)
Update Reason	
Date	14-Jul-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666013-t044-om (/qs3/pubsys2/xml/en/manual/3666013/3666013-t044-om.html)
Procedure Title	Engine Difficult to Start or Will Not Start (No Exhaust Smoke)
Update Reason	
Date	14-Jul-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666013-t061-011-om (/qs3/pubsys2/xml/en/manual/3666013/3666013-t061-011-om.html)
Procedure Title	Engine Runs Rough at Idle, Warm Engine
Update Reason	

Date	14-Jul-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666013-t072-om (/qs3/pubsys2/xml/en/manual/3666013/3666013-t072-om.html)
Procedure Title	Engine Starts But Will Not Keep Runnings
Update Reason	

Date	14-Jul-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666013-t077-om (/qs3/pubsys2/xml/en/manual/3666013/3666013-t077-om.html)
Procedure Title	Engine Will Not Crank or Cranks Slowly (Air Starter)
Update Reason	

Date	14-Jul-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666013-t078-om (/qs3/pubsys2/xml/en/manual/3666013/3666013-t078-om.html)
Procedure Title	Engine Will Not Crank
Update Reason	

Date	14-Jul-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666013-t080-om (/qs3/pubsys2/xml/en/manual/3666013/3666013-t080-om.html)
Procedure Title	Engine Will Not Reach Rated Speed (RPM)
Update Reason	

Date	14-Jul-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666013-t081-om (/qs3/pubsys2/xml/en/manual/3666013/3666013-t081-om.html)
Procedure Title	Engine Will Not Shut Off
Update Reason	

Date	14-Jul-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666013-t081-006-om (/qs3/pubsys2/xml/en/manual/3666013/3666013-t081-006-om.html)
Procedure Title	Exhaust Smoke Excessive Under Load
Update Reason	
Date	14-Jul-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666013-t105-om (/qs3/pubsys2/xml/en/manual/3666013/3666013-t105-om.html)
Procedure Title	Lubricating Oil Pressure Low
Update Reason	
Date	14-Jul-2006
Section	back
Procedure Number	3666013-backcover (/qs3/pubsys2/xml/en/manual/3666013/3666013-backcover.html)
Procedure Title	Backcover
Update Reason	
Date	19-Jul-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666013-t057-om (/qs3/pubsys2/xml/en/manual/3666013/3666013-t057-om.html)
Procedure Title	Engine Power Output Low
Update Reason	
Date	24-Jul-2006
Section	Section S - Service Assistance
Procedure Number	99-202-008 (/qs3/pubsys2/xml/en/procedures/99/99-202-008.html)
Procedure Title	Distributors - International
Update Reason	

Date	28-Jul-2006
Section	Section 1 - Operating Instructions
Procedure Number	18-101-019 (/qs3/pubsys2/xml/en/procedures/18/18-101-019.html)
Procedure Title	Step Timing Control (STC)
Update Reason	
Date	28-Jul-2006
Section	Section 2 - Maintenance Guidelines
Procedure Number	18-102-004 (/qs3/pubsys2/xml/en/procedures/18/18-102-004.html)
Procedure Title	Tool Requirements
Update Reason	
Date	28-Jul-2006
Section	Section 3 - Maintenance Procedures at Daily Interval
Procedure Number	18-103-001 (/qs3/pubsys2/xml/en/procedures/18/18-103-001.html)
Procedure Title	Engine Operation Report
Update Reason	
Date	28-Jul-2006
Section	Section 3 - Maintenance Procedures at Daily Interval
Procedure Number	18-103-004 (/qs3/pubsys2/xml/en/procedures/18/18-103-004.html)
Procedure Title	Unusual Engine Noise
Update Reason	

Date	28-Jul-2006
Section	Section 4 - Maintenance Procedures at Weekly Interval
Procedure Number	18-010-086 (/qs3/pubsys2/xml/en/procedures/18/18-010-086.html)
Procedure Title	Air Cleaner Restriction Indicator
Update Reason	
Date	28-Jul-2006
Section	Section 4 - Maintenance Procedures at Weekly Interval
Procedure Number	18-010-014 (/qs3/pubsys2/xml/en/procedures/18/18-010-014.html)
Procedure Title	Air Cleaner Element
Update Reason	
Date	28-Jul-2006
Section	Section 5 - Maintenance Procedures at 250 Hours or 6 Months
Procedure Number	18-006-015-om-ind (/qs3/pubsys2/xml/en/procedures/18/18-006-015-om-ind.html)
Procedure Title	Fuel Filter (Spin-On)
Update Reason	
Date	28-Jul-2006
Section	Section 5 - Maintenance Procedures at 250 Hours or 6 Months
Procedure Number	18-007-002 (/qs3/pubsys2/xml/en/procedures/18/18-007-002.html)
Procedure Title	Lubricating Oil and Filters
Update Reason	

Date	28-Jul-2006
Section	Section 5 - Maintenance Procedures at 250 Hours or 6 Months
Procedure Number	18-007-013-om-ind (/qs3/pubsys2/xml/en/procedures/18/18-007-013-om-ind.html)
Procedure Title	Lubricating Oil Filter (Spin-On)
Update Reason	
Date	28-Jul-2006
Section	Section 5 - Maintenance Procedures at 250 Hours or 6 Months
Procedure Number	18-008-006-om-ind (/qs3/pubsys2/xml/en/procedures/18/18-008-006-om-ind.html)
Procedure Title	Coolant Filter
Update Reason	
Date	28-Jul-2006
Section	Section 5 - Maintenance Procedures at 250 Hours or 6 Months
Procedure Number	18-012-001 (/qs3/pubsys2/xml/en/procedures/18/18-012-001.html)
Procedure Title	Air Compressor Air Cleaner Element
Update Reason	
Date	28-Jul-2006
Section	Section 5 - Maintenance Procedures at 250 Hours or 6 Months
Procedure Number	18-008-002-om-rep (/qs3/pubsys2/xml/en/procedures/18/18-008-002-om-rep.html)
Procedure Title	Drive Belt, Cooling Fan
Update Reason	

Date	28-Jul-2006
Section	Section 6 - Maintenance Procedures at 1500 Hours or 1 Year
Procedure Number	18-003-006-om-ind (/qs3/pubsys2/xml/en/procedures/18/18-003-006-om-ind.html)
Procedure Title	Overhead Set (OBC)
Update Reason	
Date	28-Jul-2006
Section	Section 6 - Maintenance Procedures at 1500 Hours or 1 Year
Procedure Number	18-003-007-om-ind (/qs3/pubsys2/xml/en/procedures/18/18-003-007-om-ind.html)
Procedure Title	Overhead Set (Dial Indicator)
Update Reason	
Date	28-Jul-2006
Section	Section 6 - Maintenance Procedures at 1500 Hours or 1 Year
Procedure Number	18-008-045-om-ind (/qs3/pubsys2/xml/en/procedures/18/18-008-045-om-ind.html)
Procedure Title	Radiator Hoses
Update Reason	
Date	28-Jul-2006
Section	Section 6 - Maintenance Procedures at 1500 Hours or 1 Year
Procedure Number	18-008-029-om-ind (/qs3/pubsys2/xml/en/procedures/18/18-008-029-om-ind.html)
Procedure Title	Fan Drive Idler Arm Assembly
Update Reason	

Date	28-Jul-2006
Section	Section 6 - Maintenance Procedures at 1500 Hours or 1 Year
Procedure Number	18-016-002-om-ind (/qs3/pubsys2/xml/en/procedures/18/18-016-002-om-ind.html)
Procedure Title	Engine Support Bracket, Front
Update Reason	
Date	28-Jul-2006
Section	Section A - Adjustment, Repair, and Replacement
Procedure Number	18-008-002-om-ind (/qs3/pubsys2/xml/en/procedures/18/18-008-002-om-ind.html)
Procedure Title	Drive Belt, Cooling Fan
Update Reason	
Date	31-Jul-2006
Section	Section 7 - Maintenance Procedures at 6000 Hours or 2 Years
Procedure Number	18-005-016-om-ind (/qs3/pubsys2/xml/en/procedures/18/18-005-016-om-ind.html)
Procedure Title	Fuel Pump
Update Reason	
Date	31-Jul-2006
Section	Section 7 - Maintenance Procedures at 6000 Hours or 2 Years
Procedure Number	18-006-026-om-ind (/qs3/pubsys2/xml/en/procedures/18/18-006-026-om-ind.html)
Procedure Title	Injectors
Update Reason	

Date	31-Jul-2006
Section	Section 7 - Maintenance Procedures at 6000 Hours or 2 Years
Procedure Number	18-008-018-om-ind (/qs3/pubsys2/xml/en/procedures/18/18-008-018-om-ind.html)
Procedure Title	Cooling System
Update Reason	
Date	31-Jul-2006
Section	Section 7 - Maintenance Procedures at 6000 Hours or 2 Years
Procedure Number	18-008-036-om-ind (/qs3/pubsys2/xml/en/procedures/18/18-008-036-om-ind.html)
Procedure Title	Fan Hub, Belt Driven
Update Reason	
Date	31-Jul-2006
Section	Section 7 - Maintenance Procedures at 6000 Hours or 2 Years
Procedure Number	18-008-037-om-ind (/qs3/pubsys2/xml/en/procedures/18/18-008-037-om-ind.html)
Procedure Title	Fan Hub, Gear Driven
Update Reason	
Date	31-Jul-2006
Section	Section 7 - Maintenance Procedures at 6000 Hours or 2 Years
Procedure Number	18-008-030-om-ind (/qs3/pubsys2/xml/en/procedures/18/18-008-030-om-ind.html)
Procedure Title	Fan Drive Idler Pulley Assembly
Update Reason	

Date	31-Jul-2006
Section	Section 7 - Maintenance Procedures at 6000 Hours or 2 Years
Procedure Number	18-008-062-om-ind (/qs3/pubsys2/xml/en/procedures/18/18-008-062-om-ind.html)
Procedure Title	Water Pump
Update Reason	
Date	31-Jul-2006
Section	Section 7 - Maintenance Procedures at 6000 Hours or 2 Years
Procedure Number	18-010-033-om-ind (/qs3/pubsys2/xml/en/procedures/18/18-010-033-om-ind.html)
Procedure Title	Turbocharger
Update Reason	
Date	31-Jul-2006
Section	Section 7 - Maintenance Procedures at 6000 Hours or 2 Years
Procedure Number	18-012-014-om-ind (/qs3/pubsys2/xml/en/procedures/18/18-012-014-om-ind.html)
Procedure Title	Air Compressor
Update Reason	
Date	31-Jul-2006
Section	Section 7 - Maintenance Procedures at 6000 Hours or 2 Years
Procedure Number	18-012-013 (/qs3/pubsys2/xml/en/procedures/18/18-012-013.html)
Procedure Title	Air Compressor Unloader and Valve Assembly
Update Reason	

Date	31-Jul-2006
Section	Section A - Adjustment, Repair, and Replacement
Procedure Number	18-013-005-om-ind (/qs3/pubsys2/xml/en/procedures/18/18-013-005-om-ind.html)
Procedure Title	Drive Belt, Alternator
Update Reason	
Date	31-Jul-2006
Section	Section L - Service Literature
Procedure Number	18-205-001-om (/qs3/pubsys2/xml/en/procedures/18/18-205-001-om.html)
Procedure Title	Additional Service Literature
Update Reason	
Date	31-Jul-2006
Section	Section V - Maintenance Specifications
Procedure Number	18-018-024 (/qs3/pubsys2/xml/en/procedures/18/18-018-024.html)
Procedure Title	Cummins/Fleetguard® Filter Specifications
Update Reason	
Date	31-Jul-2006
Section	Section V - Maintenance Specifications
Procedure Number	18-018-006 (/qs3/pubsys2/xml/en/procedures/18/18-018-006.html)
Procedure Title	Engine Component Torque Values
Update Reason	
Date	17-Aug-2006
Section	Section A - Adjustment, Repair, and Replacement
Procedure Number	18-003-011-om-ind (/qs3/pubsys2/xml/en/procedures/18/18-003-011-om-ind.html)
Procedure Title	Rocker Lever Cover
Update Reason	

Date	03-Oct-2006
Section	Section E - Engine Identification
Procedure Number	18-100-002 (/qs3/pubsys2/xml/en/procedures/18/18-100-002.html)
Procedure Title	Engine Diagrams
Update Reason	
Date	03-Oct-2006
Section	Section D - System Diagrams
Procedure Number	18-200-001 (/qs3/pubsys2/xml/en/procedures/18/18-200-001.html)
Procedure Title	Flow Diagram, Fuel System
Update Reason	
Date	03-Oct-2006
Section	Section D - System Diagrams
Procedure Number	18-200-002 (/qs3/pubsys2/xml/en/procedures/18/18-200-002.html)
Procedure Title	Flow Diagram, Lubricating Oil System
Update Reason	
Date	03-Oct-2006
Section	Section D - System Diagrams
Procedure Number	18-200-003 (/qs3/pubsys2/xml/en/procedures/18/18-200-003.html)
Procedure Title	Flow Diagram, Cooling System
Update Reason	
Date	03-Oct-2006
Section	Section D - System Diagrams
Procedure Number	18-200-004 (/qs3/pubsys2/xml/en/procedures/18/18-200-004.html)
Procedure Title	Flow Diagram, Air Intake System
Update Reason	

Date	03-Oct-2006
Section	Section D - System Diagrams
Procedure Number	18-200-005 (/qs3/pubsys2/xml/en/procedures/18/18-200-005.html)
Procedure Title	Flow Diagram, Exhaust System
Update Reason	
Date	03-Oct-2006
Section	Section D - System Diagrams
Procedure Number	18-200-006 (/qs3/pubsys2/xml/en/procedures/18/18-200-006.html)
Procedure Title	Flow Diagram, Compressed Air System
Update Reason	
Date	10-Oct-2006
Section	front
Procedure Number	3666013-titlepage (/qs3/pubsys2/xml/en/manual/3666013/3666013-titlepage.html)
Procedure Title	Titlepage
Update Reason	
Date	10-Oct-2006
Section	Section 2 - Maintenance Guidelines
Procedure Number	18-102-002-om-ind (/qs3/pubsys2/xml/en/procedures/18/18-102-002-om-ind.html)
Procedure Title	Maintenance Schedule
Update Reason	
Date	31-Jan-2007
Section	Section V - Maintenance Specifications
Procedure Number	102-018-002 (/qs3/pubsys2/xml/en/procedures/102/102-018-002.html)
Procedure Title	Fuel Recommendations and Specifications
Update Reason	

Date	23-Apr-2007
Section	Section W - Warranty
Procedure Number	3381322 (/qs3/pubsys2/xml/en/warranty/3381322.html)
Procedure Title	All Engines International Industrial (Off-Highway)
Update Reason	
Date	08-May-2007
Section	Section V - Maintenance Specifications
Procedure Number	102-018-003 (/qs3/pubsys2/xml/en/procedures/102/102-018-003.html)
Procedure Title	Lubricating Oil Recommendations and Specifications
Update Reason	
Date	16-May-2007
Section	Section V - Maintenance Specifications
Procedure Number	18-018-015 (/qs3/pubsys2/xml/en/procedures/18/18-018-015.html)
Procedure Title	General Specifications
Update Reason	
Date	16-May-2007
Section	Section V - Maintenance Specifications
Procedure Number	18-018-018 (/qs3/pubsys2/xml/en/procedures/18/18-018-018.html)
Procedure Title	Cooling System
Update Reason	
Date	16-May-2007
Section	Section V - Maintenance Specifications
Procedure Number	18-018-019 (/qs3/pubsys2/xml/en/procedures/18/18-018-019.html)
Procedure Title	Air Intake System
Update Reason	

Date	16-May-2007
Section	Section V - Maintenance Specifications
Procedure Number	18-018-020 (/qs3/pubsys2/xml/en/procedures/18/18-018-020.html)
Procedure Title	Exhaust System
Update Reason	
Date	16-May-2007
Section	Section V - Maintenance Specifications
Procedure Number	18-018-021 (/qs3/pubsys2/xml/en/procedures/18/18-018-021.html)
Procedure Title	Electrical System
Update Reason	
Date	16-May-2007
Section	Section V - Maintenance Specifications
Procedure Number	18-018-022 (/qs3/pubsys2/xml/en/procedures/18/18-018-022.html)
Procedure Title	Compressed Air System
Update Reason	
Date	24-May-2007
Section	Section V - Maintenance Specifications
Procedure Number	18-018-016 (/qs3/pubsys2/xml/en/procedures/18/18-018-016.html)
Procedure Title	Fuel System
Update Reason	
Date	20-Jun-2007
Section	Section W - Warranty
Procedure Number	3381321 (/qs3/pubsys2/xml/en/warranty/3381321.html)
Procedure Title	All Engines United States and Canada Industrial (Off-Highway)
Update Reason	

Date	24-Jul-2007
Section	Section i - Introduction
Procedure Number	99-204-008 (/qs3/pubsys2/xml/en/procedures/99/99-204-008.html)
Procedure Title	General Cleaning Instructions
Update Reason	
Date	22-Oct-2007
Section	Section 7 - Maintenance Procedures at 6000 Hours or 2 Years
Procedure Number	99-001-052 (/qs3/pubsys2/xml/en/procedures/99/99-001-052.html)
Procedure Title	Vibration Damper, Viscous
Update Reason	
Date	27-Mar-2008
Section	Section W - Warranty
Procedure Number	3381310 (/qs3/pubsys2/xml/en/warranty/3381310.html)
Procedure Title	K19 Engines Australia and New Zealand Automotive
Update Reason	
Date	24-Apr-2008
Section	Section S - Service Assistance
Procedure Number	99-202-007 (/qs3/pubsys2/xml/en/procedures/99/99-202-007.html)
Procedure Title	Regional Offices - International
Update Reason	
Date	02-Dec-2008
Section	Section V - Maintenance Specifications
Procedure Number	18-018-017 (/qs3/pubsys2/xml/en/procedures/18/18-018-017.html)
Procedure Title	Lubricating Oil System
Update Reason	

Date	04-Dec-2008
Section	Section S - Service Assistance
Procedure Number	99-202-006 (/qs3/pubsys2/xml/en/procedures/99/99-202-006.html)
Procedure Title	Distributors and Branches
Update Reason	
Date	12-Dec-2008
Section	Section 7 - Maintenance Procedures at 6000 Hours or 2 Years
Procedure Number	18-010-037-om-ind (/qs3/pubsys2/xml/en/procedures/18/18-010-037-om-ind.html)
Procedure Title	Turbocharger, Water Cooled
Update Reason	
Date	09-Jan-2009
Section	Section 1 - Operating Instructions
Procedure Number	00-101-018 (/qs3/pubsys2/xml/en/procedures/00/00-101-018.html)
Procedure Title	Starting Procedure After Extended Shutdown or Oil Change
Update Reason	
Date	25-Feb-2009
Section	Section S - Service Assistance
Procedure Number	99-202-003 (/qs3/pubsys2/xml/en/procedures/99/99-202-003.html)
Procedure Title	Emergency and Technical Service
Update Reason	

Date	01-Apr-2009
Section	Section 7 - Maintenance Procedures at 6000 Hours or 2 Years
Procedure Number	18-008-057-om-ind (/qs3/pubsys2/xml/en/procedures/18/18-008-057-om-ind.html)
Procedure Title	Seawater Pump
Update Reason	
Date	12-May-2009
Section	Section W - Warranty
Procedure Number	3381775 (/qs3/pubsys2/xml/en/warranty/3381775.html)
Procedure Title	All Engines Worldwide Marine/Commercial Propulsion and Auxiliary Products
Update Reason	
Date	25-Jun-2009
Section	Section TS - Troubleshooting Symptoms
Procedure Number	99-t00-001-om (/qs3/pubsys2/xml/en/procedures/99/99-t00-001-om.html)
Procedure Title	Troubleshooting Procedures and Techniques
Update Reason	
Date	22-Jul-2009
Section	Section L - Service Literature
Procedure Number	99-205-004 (/qs3/pubsys2/xml/en/procedures/99/99-205-004.html)
Procedure Title	Cummins Customized Part Catalog
Update Reason	
Date	25-Aug-2009
Section	Section W - Warranty
Procedure Number	3381307 (/qs3/pubsys2/xml/en/warranty/3381307.html)
Procedure Title	All Diesel Engines Worldwide Generator Drive
Update Reason	

Date	10-Sep-2009
Section	Section i - Introduction
Procedure Number	99-204-002-om-indmar (/qs3/pubsys2/xml/en/procedures/99/99-204-002-om-indmar.html)
Procedure Title	About the Manual
Update Reason	
Date	16-Sep-2009
Section	Section 1 - Operating Instructions
Procedure Number	99-101-009-om-indmar (/qs3/pubsys2/xml/en/procedures/99/99-101-009-om-indmar.html)
Procedure Title	Engine Shutdown
Update Reason	
Date	08-Oct-2009
Section	Section i - Introduction
Procedure Number	99-204-007-om-indmar (/qs3/pubsys2/xml/en/procedures/99/99-204-007-om-indmar.html)
Procedure Title	General Repair Instructions
Update Reason	
Date	09-Oct-2009
Section	Section ES - Engine Storage
Procedure Number	99-000-005-om-ind (/qs3/pubsys2/xml/en/procedures/99/99-000-005-om-ind.html)
Procedure Title	Engine Storage - Long Term
Update Reason	
Date	13-Oct-2009
Section	Section 2 - Maintenance Guidelines
Procedure Number	99-102-001 (/qs3/pubsys2/xml/en/procedures/99/99-102-001.html)
Procedure Title	Maintenance Record Form
Update Reason	

Date	14-Oct-2009
Section	Section 3 - Maintenance Procedures at Daily Interval
Procedure Number	99-007-043-om-indmar (/qs3/pubsys2/xml/en/procedures/99/99-007-043-om-indmar.html)
Procedure Title	Lubricating Oil Level
Update Reason	
Date	15-Oct-2009
Section	Section 4 - Maintenance Procedures at Weekly Interval
Procedure Number	99-008-045 (/qs3/pubsys2/xml/en/procedures/99/99-008-045.html)
Procedure Title	Radiator Hoses
Update Reason	
Date	03-Nov-2009
Section	Section 5 - Maintenance Procedures at 250 Hours or 6 Months
Procedure Number	99-008-046 (/qs3/pubsys2/xml/en/procedures/99/99-008-046.html)
Procedure Title	Supplemental Coolant Additive (SCA) and Antifreeze Concentration
Update Reason	
Date	04-Nov-2009
Section	Section 6 - Maintenance Procedures at 1500 Hours or 1 Year
Procedure Number	102-016-010-om (/qs3/pubsys2/xml/en/procedures/102/102-016-010-om.html)
Procedure Title	Engine Mounts
Update Reason	

Date	13-Nov-2009
Section	Section 1 - Operating Instructions
Procedure Number	00-101-004-om (/qs3/pubsys2/xml/en/procedures/00/00-101-004-om.html)
Procedure Title	Cold Weather Starting
Update Reason	
Date	17-Nov-2009
Section	Section 2 - Maintenance Guidelines
Procedure Number	99-102-999 (/qs3/pubsys2/xml/en/procedures/99/99-102-999.html)
Procedure Title	Maintenance Guidelines - Overview
Update Reason	
Date	18-Nov-2009
Section	Section 7 - Maintenance Procedures at 6000 Hours or 2 Years
Procedure Number	99-001-051 (/qs3/pubsys2/xml/en/procedures/99/99-001-051.html)
Procedure Title	Vibration Damper, Rubber
Update Reason	
Date	19-Nov-2009
Section	Section 3 - Maintenance Procedures at Daily Interval
Procedure Number	99-008-066 (/qs3/pubsys2/xml/en/procedures/99/99-008-066.html)
Procedure Title	Coolant Level
Update Reason	
Date	19-Nov-2009
Section	Section S - Service Assistance
Procedure Number	99-202-002 (/qs3/pubsys2/xml/en/procedures/99/99-202-002.html)
Procedure Title	Routine Service and Parts
Update Reason	

Date	19-Nov-2009
Section	Section S - Service Assistance
Procedure Number	99-202-004 (/qs3/pubsys2/xml/en/procedures/99/99-202-004.html)
Procedure Title	Problem Solving
Update Reason	
Date	06-Jan-2010
Section	Section i - Introduction
Procedure Number	99-204-003-om-indmar (/qs3/pubsys2/xml/en/procedures/99/99-204-003-om-indmar.html)
Procedure Title	How to Use the Manual
Update Reason	
Date	25-Jan-2010
Section	Section i - Introduction
Procedure Number	99-204-006-om-indmar (/qs3/pubsys2/xml/en/procedures/99/99-204-006-om-indmar.html)
Procedure Title	General Safety Instructions
Update Reason	
Date	25-Jan-2010
Section	Section 1 - Operating Instructions
Procedure Number	99-101-999-om-indmar (/qs3/pubsys2/xml/en/procedures/99/99-101-999-om-indmar.html)
Procedure Title	Operating Instructions - Overview
Update Reason	
Date	25-Jan-2010
Section	Section 1 - Operating Instructions
Procedure Number	99-101-008-om-indmar (/qs3/pubsys2/xml/en/procedures/99/99-101-008-om-indmar.html)
Procedure Title	Engine Operating Range
Update Reason	

Date	25-Jan-2010
Section	Section 3 - Maintenance Procedures at Daily Interval
Procedure Number	99-103-002 (/qs3/pubsys2/xml/en/procedures/99/99-103-002.html)
Procedure Title	Drive Belts
Update Reason	
Date	25-Jan-2010
Section	Section V - Maintenance Specifications
Procedure Number	99-018-005 (/qs3/pubsys2/xml/en/procedures/99/99-018-005.html)
Procedure Title	Drive Belt Tension
Update Reason	
Date	25-Jan-2010
Section	Section V - Maintenance Specifications
Procedure Number	99-018-009 (/qs3/pubsys2/xml/en/procedures/99/99-018-009.html)
Procedure Title	Capscrew Markings and Torque Values
Update Reason	
Date	04-Feb-2010
Section	Section 1 - Operating Instructions
Procedure Number	99-101-015-om-indmar (/qs3/pubsys2/xml/en/procedures/99/99-101-015-om-indmar.html)
Procedure Title	Operating the Engine
Update Reason	
Date	18-Mar-2010
Section	Section A - Adjustment, Repair, and Replacement
Procedure Number	18-007-009 (/qs3/pubsys2/xml/en/procedures/18/18-007-009.html)
Procedure Title	Lubricating Oil Dipstick
Update Reason	

Date	24-Mar-2010
Section	Section i - Introduction
Procedure Number	99-204-009 (/qs3/pubsys2/xml/en/procedures/99/99-204-009.html)
Procedure Title	Acronyms and Abbreviations
Update Reason	
Date	07-Jan-2011
Section	Section A - Adjustment, Repair, and Replacement
Procedure Number	18-013-005-om-ind (/qs3/pubsys2/xml/en/procedures/18/18-013-005-om-ind.html)
Procedure Title	Drive Belt, Alternator
Update Reason	Added information for captive fasteners on alternator belt guard.
Date	07-Jan-2011
Section	Section A - Adjustment, Repair, and Replacement
Procedure Number	18-008-001-om-ind (/qs3/pubsys2/xml/en/procedures/18/18-008-001-om-ind.html)
Procedure Title	Belt Guard
Update Reason	Added to Section A.
Date	23-Mar-2011
Section	Section 2 - Maintenance Guidelines
Procedure Number	18-102-002-om-ind (/qs3/pubsys2/xml/en/procedures/18/18-102-002-om-ind.html)
Procedure Title	Maintenance Schedule
Update Reason	Updated to todays standards with minor edits.

Date	28-Sep-2011
Section	Section A - Adjustment, Repair, and Replacement
Procedure Number	18-008-087-om-ind (/qs3/pubsys2/xml/en/procedures/18/18-008-087-om-ind.html)
Procedure Title	Cooling Fan Belt Tensioner
Update Reason	Added procedure to outline and manual.
Date	20-Dec-2011
Section	Section V - Maintenance Specifications
Procedure Number	102-018-003 (/qs3/pubsys2/xml/en/procedures/102/102-018-003.html)
Procedure Title	Lubricating Oil Recommendations and Specifications
Update Reason	Edited to add the specific oils used in HHP Diesel engines, represented by CES (Cummins engineering standards) and API classification.
Date	25-May-2013
Section	Section 4 - Maintenance Procedures at Weekly Interval
Procedure Number	18-007-051 (/qs3/pubsys2/xml/en/procedures/18/18-007-051.html)
Procedure Title	Lubricating Oil Analysis
Update Reason	This procedure was added to the outline.
Date	28-Aug-2013
Section	Section V - Maintenance Specifications
Procedure Number	102-018-002 (/qs3/pubsys2/xml/en/procedures/102/102-018-002.html)
Procedure Title	Fuel Recommendations and Specifications
Update Reason	Updated fuel specifications.

Date	22-Oct-2013
Section	Section 2 - Maintenance Guidelines
Procedure Number	18-102-002-om-ind (/qs3/pubsys2/xml/en/procedures/18/18-102-002-om-ind.html)
Procedure Title	Maintenance Schedule
Update Reason	Changed typo on Maintenance Procedures at 5000 Hours or 2 Years to Maintenance Procedures at 6000 Hours or 2 Years.
Date	01-Apr-2015
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	56-016-002-tr (/qs3/pubsys2/xml/en/procedures/56/56-016-002-tr.html)
Procedure Title	Engine Support Bracket, Front
Update Reason	Procedure has been updated with currently available greases recommendations.
Date	08-Apr-2015
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-018-tr (/qs3/pubsys2/xml/en/procedures/56/56-008-018-tr.html)
Procedure Title	Cooling System
Update Reason	Added directions to allow the engine to cool before draining coolant.
Date	05-May-2015
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-067-tr (/qs3/pubsys2/xml/en/procedures/56/56-007-067-tr.html)
Procedure Title	Eliminator Filter
Update Reason	Disassemble, Clean, Inspect for Reuse, and Assemble Sections, have been replaced with hyperlinks to the Eliminator™ Filter, Bulletin 3666253.

Date	07-May-2015
Section	Section 8 - Cooling System
Procedure Number	56-008-029-tr (/qs3/pubsys2/xml/en/procedures/56/56-008-029-tr.html)
Procedure Title	Fan Drive Idler Arm Assembly
Update Reason	Updated grease(s) recommendations.
Date	07-May-2015
Section	Section 8 - Cooling System
Procedure Number	56-008-036-tr (/qs3/pubsys2/xml/en/procedures/56/56-008-036-tr.html)
Procedure Title	m AssemblyFan Drive Idler Ar
Update Reason	Updated grease(s) recommendations.
Date	18-May-2015
Section	Section 14 - Engine Testing - Group 14
Procedure Number	56-014-002 (/qs3/pubsys2/xml/en/procedures/56/56-014-002.html)
Procedure Title	Engine Testing (Chassis Dynamometer)
Update Reason	Changed task from Intake Manifold Air Temperature Control - Chassis Dynamometer test to Exhaust Air Restriction.
Date	20-May-2015
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	56-016-005-tr (/qs3/pubsys2/xml/en/procedures/56/56-016-005-tr.html)
Procedure Title	Flywheel
Update Reason	Added note for the QSK45 excavator applications that use the 12-point head capscrews, remove and discard the flywheel, capscrews, and spacer at end of every life rebuild.

Date	17-Jun-2015
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	102-001-026 (/qs3/pubsys2/xml/en/procedures/102/102-001-026.html)
Procedure Title	Cylinder Block
Update Reason	Updated the specifications for the main bearing cap press fit interference.

Date	22-Jun-2015
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-047-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-047-tr.html)
Procedure Title	Piston Rings
Update Reason	Corrected 0.03 mm [0.002 in] to 0.03 mm [0.001 in].

Date	27-Jul-2015
Section	Section 1 - Cylinder Block
Procedure Number	56-001-016-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-016-tr.html)
Procedure Title	Crankshaft
Update Reason	Torque for counterweight capscrew was changed to 12.9 Capscrews 40 N•m plus 90 degreee angle.

Date	29-Jul-2015
Section	Section 1 - Cylinder Block
Procedure Number	56-001-006 (/qs3/pubsys2/xml/en/procedures/56/56-001-006.html)
Procedure Title	Main Bearing
Update Reason	Updated inspection of galling around capscrew in main bearings

Date	14-Sep-2015
Section	Section 1 - Cylinder Block
Procedure Number	56-001-016-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-016-tr.html)
Procedure Title	Crankshaft
Update Reason	Updated torque values for 12.9 capscrews.
Date	02-Oct-2015
Section	Section 11 - Exhaust System - Group 11
Procedure Number	56-011-001-tr (/qs3/pubsys2/xml/en/procedures/56/56-011-001-tr.html)
Procedure Title	Exhaust Connection Pipe
Update Reason	The install step was revised and torque value has been corrected.
Date	13-Oct-2015
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	56-006-025-tr (/qs3/pubsys2/xml/en/procedures/56/56-006-025-tr.html)
Procedure Title	Static Injection Timing
Update Reason	Replaced the graphics at the end of the Measure section with text and tables.
Date	27-Oct-2015
Section	Section 14 - Engine Testing - Group 14
Procedure Number	56-014-008-tr (/qs3/pubsys2/xml/en/procedures/56/56-014-008-tr.html)
Procedure Title	Engine Testing (In Chassis)
Update Reason	Procedure has been commonized for all high horsepower engine families.

Date	16-Nov-2015
Section	Section 10 - Air Intake System - Group 10
Procedure Number	56-010-033-tr (/qs3/pubsys2/xml/en/procedures/56/56-010-033-tr.html)
Procedure Title	Turbocharger
Update Reason	Updated the torque value for the V-band clamp in the Assemble step.

Date	19-Nov-2015
Section	Section 9 - Drive Units - Group 09
Procedure Number	56-009-016-tr (/qs3/pubsys2/xml/en/procedures/56/56-009-016-tr.html)
Procedure Title	Hydraulic Pump Drive
Update Reason	Corrected component to be lubricated in the Install step.

Date	12-Jan-2016
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	56-003-009-tr (/qs3/pubsys2/xml/en/procedures/56/56-003-009-tr.html)
Procedure Title	Rocker Lever Assembly
Update Reason	Updated the art and instructions as to the orientation of the lever assembly bushing installation.

Date	22-Jan-2016
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	56-006-051-tr (/qs3/pubsys2/xml/en/procedures/56/56-006-051-tr.html)
Procedure Title	Injector Supply Lines (High Pressure)
Update Reason	Updated pressure relief warning in Leak Test section for C3 fuel systems.

Date	26-Jan-2016
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-023-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-023-tr.html)
Procedure Title	Crankshaft Seal, Front
Update Reason	Added lubricating rear rubber element in Install step.

Date	26-Jan-2016
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-024-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-024-tr.html)
Procedure Title	Crankshaft Seal, Rear
Update Reason	Added lubricating rear rubber element in Install step.

Date	24-Feb-2016
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-005-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-005-tr.html)
Procedure Title	Bearings, Connecting Rod
Update Reason	Thickness of bearing measurement was removed in Clean and Inspect for Reuse section.

Date	15-Mar-2016
Section	Section 9 - Drive Units
Procedure Number	56-009-001-tr (/qs3/pubsys2/xml/en/procedures/56/56-009-001-tr.html)
Procedure Title	Accessory Drive
Update Reason	Adjusted the imperial measurements to four decimal places.

Date	15-Mar-2016
Section	Section 9 - Drive Units
Procedure Number	56-009-004-tr (/qs3/pubsys2/xml/en/procedures/56/56-009-004-tr.html)
Procedure Title	Accessory Drive Pulley
Update Reason	Adjusted the imperial measurements to four decimal places.

Date	15-Mar-2016
Section	Section 9 - Drive Units
Procedure Number	56-009-011-tr (/qs3/pubsys2/xml/en/procedures/56/56-009-011-tr.html)
Procedure Title	Fuel Pump Drive
Update Reason	Adjusted the imperial measurements to four decimal places.

Date	15-Mar-2016
Section	Section 9 - Drive Units
Procedure Number	56-009-029-tr (/qs3/pubsys2/xml/en/procedures/56/56-009-029-tr.html)
Procedure Title	Water pump Drive
Update Reason	Adjusted the imperial measurements to four decimal places.

Date	17-Mar-2016
Section	Section 9 - Drive Units - Group 09
Procedure Number	56-009-010-tr (/qs3/pubsys2/xml/en/procedures/56/56-009-010-tr.html)
Procedure Title	Alternator Drive Pulley
Update Reason	Updated pulley reuse criteria.

Date	31-Mar-2016
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	56-006-075-tr (/qs3/pubsys2/xml/en/procedures/56/56-006-075-tr.html)
Procedure Title	Fuel Filter (Stage 1)
Update Reason	Updated to include instructions on the new FH240 Series Sea Pro units.
Date	26-Apr-2016
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-007-tr (/qs3/pubsys2/xml/en/procedures/56/56-007-007-tr.html)
Procedure Title	Lubricating Oil Cooler Element
Update Reason	Revised Clean and Inspect for Reuse step.
Date	27-Apr-2016
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-002-tr (/qs3/pubsys2/xml/en/procedures/56/56-008-002-tr.html)
Procedure Title	Drive Belt, Cooling Fan
Update Reason	Added information for "slide type" belt tensioner.
Date	27-Apr-2016
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-062-tr (/qs3/pubsys2/xml/en/procedures/56/56-008-062-tr.html)
Procedure Title	Water Pump
Update Reason	Updated the torque value in the Dual Impeller section of the Install step for installing water pump to the gear housing.

Date	04-May-2016
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-057-tr (/qs3/pubsys2/xml/en/procedures/56/56-008-057-tr.html)
Procedure Title	Sea Water Pump
Update Reason	The procedure was updated to include one instruction regarding a new sea water pump option.

Date	10-May-2016
Section	Section 5 - Fuel System - Group 05
Procedure Number	56-005-045-tr (/qs3/pubsys2/xml/en/procedures/56/56-005-045-tr.html)
Procedure Title	Fuel Lift Pump
Update Reason	Updated to include a new on-engine mounted fuel lift pump.

Date	09-Sep-2015
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-010-002-shopds (/qs3/pubsys2/xml/en/procedures/56/56-010-002-shopds.html)
Procedure Title	Aftercooler Assembly
Update Reason	Revised torque values for hose clamps to mount rubber T connections on aftercooler tubes.

Date	09-Sep-2015
Section	Section AS - Engine Assembly - Group 00
Procedure Number	56-010-002-shopas (/qs3/pubsys2/xml/en/procedures/56/56-010-002-shopas.html)
Procedure Title	Aftercooler Assembly
Update Reason	Revised torque values for hose clamps to mount rubber T connections on aftercooler tubes.

Date	09-Sep-2015
Section	Section 10 -Air Intake System - Group 10
Procedure Number	56-010-002-tr (/qs3/pubsys2/xml/en/procedures/56/56-010-002-tr.html)
Procedure Title	Aftercooler Assembly
Update Reason	Revised torque values for hose clamps to mount rubber T connections on aftercooler tubes.
Date	23-Jun-2016
Section	Section 5 - Fuel System - Group 05
Procedure Number	56-007-025-tr (/qs3/pubsys2/xml/en/procedures/56/56-007-025-tr.html)
Procedure Title	Lubricating Oil Pan
Update Reason	Updated capscrew torque value.
Date	06-Jul-2016
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	56-006-017-tr (/qs3/pubsys2/xml/en/procedures/56/56-006-017-tr.html)
Procedure Title	Fuel Filter Head
Update Reason	Torque values and service procedure has been updated to reflect heads which are currently being used.
Date	15-Jul-2016
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-002-tr (/qs3/pubsys2/xml/en/procedures/56/56-008-002-tr.html)
Procedure Title	Drive Belt, Cooling Fan
Update Reason	Added automatic type tensioner information.

Date	25-Jul-2016
Section	Section 11 - Exhaust System - Group 11
Procedure Number	56-011-001-tr (/qs3/pubsys2/xml/en/procedures/56/56-011-001-tr.html)
Procedure Title	Exhaust Connection Pipe
Update Reason	Updated torque value for exhaust connection pipes.

Date	07-Sep-2016
Section	Section 10 - Air Intake System - Group 10
Procedure Number	56-010-033-tr (/qs3/pubsys2/xml/en/procedures/56/56-010-033-tr.html)
Procedure Title	Turbocharger
Update Reason	Revised the inspection criteria in the Clean and Inspect for Reuse step.

Date	07-Sep-2016
Section	Section 10 - Air Intake System - Group 10
Procedure Number	56-010-034-tr (/qs3/pubsys2/xml/en/procedures/56/56-010-034-tr.html)
Procedure Title	Turbocharger, High Pressure
Update Reason	Updated the torque value for the flanged nuts.

Date	07-Sep-2016
Section	Section 10 - Air Intake System - Group 10
Procedure Number	56-010-035-tr (/qs3/pubsys2/xml/en/procedures/56/56-010-035-tr.html)
Procedure Title	Turbocharger, Low Pressure
Update Reason	Updated the torque value for the turbocharger mounting capscrews.

Date	28-Sep-2016
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	102-007-083 (/qs3/pubsys2/xml/en/procedures/102/102-007-083.html)
Procedure Title	Lubricating Oil and Filter Analysis
Update Reason	Added to outline.
Date	27Octp-2016
Section	Section 2 - Cylinder Head - Group 02
Procedure Number	56-002-004-tr (/qs3/pubsys2/xml/en/procedures/56/56-002-004-tr.html)
Procedure Title	Cylinder Head
Update Reason	The color coding reference for the exhaust port valve seat insert is being updated to reflect the current color.
Date	03-Jan-2017
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	56-006-026-tr (/qs3/pubsys2/xml/en/procedures/56/56-006-026-tr.html)
Procedure Title	Injector
Update Reason	A statement has been added to the Remove Section to discard the used hold down caspcrew,
Date	03-Jan-2017
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-045-tr (/qs3/pubsys2/xml/en/procedures/56/56-007-045-tr.html)
Procedure Title	Lubricating Oil Cooler Cover
Update Reason	The procedure was updated to correct the installation instructions.

Date	03-Jan-2017
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-037-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-037-tr.html)
Procedure Title	Idle Gear, Camshaft (Left Bank)
Update Reason	Addition to the procedure adds steps on using the new service tool to set in the correct position when installing the cam gears.
Date	16-Jan-2017
Section	Section 10 - Air Intake System
Procedure Number	56-010-033-tr (/qs3/pubsys2/xml/en/procedures/56/56-010-033-tr.html)
Procedure Title	Turbocharger
Update Reason	Compressor Impeller Radial Endplay, Holset HX55 Turbocharger, changed mm to 0.610.
Date	24-Mar-2017
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-002-tr (/qs3/pubsys2/xml/en/procedures/56/56-008-002-tr.html)
Procedure Title	Drive Belt, Cooling Fan
Update Reason	Updated to include an inspect and re-use guideline for the drive belt tensioner.
Date	11-Apr-2017
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021530-t107-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t107-tr.html)
Procedure Title	Lubricating Oil Temperature Above Specification
Update Reason	Replaced link in 4th node from 007-028 to 007-038.

Date	11-Apr-2017
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	56-016-004-tr (/qs3/pubsys2/xml/en/procedures/56/56-016-004-tr.html)
Procedure Title	Flexplate
Update Reason	Updated the Flexplate Face and Radial Runout threshold limits.

Date	17-May-2017
Section	Section 10 - Air Intake System
Procedure Number	56-010-033-tr (/qs3/pubsys2/xml/en/procedures/56/56-010-033-tr.html)
Procedure Title	Turbocharger
Update Reason	Adding the HX 80 turbocharger to the compressor impeller axial endplay & compressor impeller radial endplay measurements.

Date	16-Jun-2017
Section	Section 10 - Air Intake System
Procedure Number	56-010-034-tr (/qs3/pubsys2/xml/en/procedures/56/56-010-034-tr.html)
Procedure Title	Turbocharger, High Pressure
Update Reason	Added Note: Make sure that the turbocharger is correctly aligned during installation to prevent damage to the turbocharger bellows.

Date	16-Jun-2017
Section	Section 10 - Air Intake System
Procedure Number	56-010-035-tr (/qs3/pubsys2/xml/en/procedures/56/56-010-035-tr.html)
Procedure Title	Turbocharger, Low Pressure
Update Reason	Added Note: Make sure that the turbocharger is correctly aligned during installation to prevent damage to the turbocharger bellows.

Date	17-Jul-2017
Section	Section 2 - Cylinder Head
Procedure Number	56-002-004-tr (/qs3/pubsys2/xml/en/procedures/56/56-002-004-tr.html)
Procedure Title	Cylinder Head
Update Reason	Added Note: Valve stem seals must be replaced during cylinder rebuild.
Date	18-Jul-2017
Section	Section 16 - Mounting Adaptations- Group 16
Procedure Number	56-016-002-tr (/qs3/pubsys2/xml/en/procedures/56/56-016-002-tr.html)
Procedure Title	Engine Support Bracket, Front
Update Reason	Updated Install step.
Date	20-Jul-2017
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-016-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-016-tr.html)
Procedure Title	Crankshaft
Update Reason	Updated crankshaft counterweight re-use guidelines.
Date	28-Jul-2017
Section	Section 10 - Air Intake System - Group 10
Procedure Number	56-010-083-tr (/qs3/pubsys2/xml/en/procedures/56/56-010-083-tr.html)
Procedure Title	Intercooler Assembly
Update Reason	Changed torque value: Bolt is a M16x2 grade 9.8, to be torque to 155 ft-lbs into aluminum, as stated in ES98065.

Date	14-Aug-2017
Section	Section V - Specifications
Procedure Number	56-018-015-tr (/qs3/pubsys2/xml/en/procedures/56/56-018-015-tr.html)
Procedure Title	General Engine
Update Reason	Revised engine weights.
Date	25-Aug-2017
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-016-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-016-tr.html)
Procedure Title	Crankshaft
Update Reason	Updated Clean and Inspect for Reuse step.
Date	26-Oct-2017
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-028-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-028-tr.html)
Procedure Title	Cylinder Liner
Update Reason	Updated procedure to include information on steel pistons versus FCD pistons.
Date	27-Oct-2017
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-043-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-043-tr.html)
Procedure Title	Piston
Update Reason	Updated procedure to include information on steel pistons versus FCD pistons.

Date	26-Oct-2017
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-045-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-045-tr.html)
Procedure Title	Piston and Cylinder Liner
Update Reason	Updated procedure to include information on steel pistons versus FCD pistons.
Date	26-Oct-2017
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-047-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-047-tr.html)
Procedure Title	Piston Rings
Update Reason	Updated procedure to include information on steel pistons versus FCD pistons.
Date	26-Oct-2017
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-054-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-054-tr.html)
Procedure Title	Piston and Connecting Rod Assembly
Update Reason	Updated procedure to include information on steel pistons versus FCD pistons.
Date	13-Nov-2017
Section	Section 11 - Exhaust System - Group 11
Procedure Number	56-011-007-tr (/qs3/pubsys2/xml/en/procedures/56/56-011-007-tr.html)
Procedure Title	Exhaust Manifold, Dry
Update Reason	Updated for the new stainless steel long thread capscrew. Replaces stainless short capscrew.

Date	11-Dec-2017
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021530-t048-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t048-tr.html)
Procedure Title	Engine Noise Excessive - Combustion Knocks
Update Reason	Added procedure reference for injector 006-026-tr to TS tree.
Date	12-Jan-2018
Section	Section 9 - Drive Units
Procedure Number	56-009-039-tr (/qs3/pubsys2/xml/en/procedures/56/56-009-039-tr.html)
Procedure Title	Accessory Drive Cover
Update Reason	Added Loctite® 675 sealant to cover.
Date	15-Jan-2018
Section	Section 1 - Cylinder Block
Procedure Number	56-001-047-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-047-tr.html)
Procedure Title	Piston Rings
Update Reason	Revised Piston Ring Gap for FCD Pistons Table.
Date	22-Jan-2018
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	56-006-051-tr (/qs3/pubsys2/xml/en/procedures/56/56-006-051-tr.html)
Procedure Title	Injector Supply Lines (High Pressure)
Update Reason	Inserted note on checking for fuel leaks on warm engine in Leak Test section.

Date	05-Feb-2018
Section	Section 16 - Mounting Adaptations
Procedure Number	56-016-005-tr (/qs3/pubsys2/xml/en/procedures/56/56-016-005-tr.html)
Procedure Title	Flywheel
Update Reason	Remove step: Added bullet statement, Remove and discard the roll pin in the rear face of the crankshaft

Date	20-Mar-2018
Section	Section 2 - Cylinder Head
Procedure Number	56-002-004-tr (/qs3/pubsys2/xml/en/procedures/56/56-002-004-tr.html)
Procedure Title	Cylinder Head
Update Reason	Injector protusion max limit for Electronically Actuated Injector (MCRS) has been increased to allow for recon heads.

Date	15-Jun-2018
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021530-t027-tr (/qs3/pubsys2/xml/en/manual/4021530/4021530-t027-tr.html)
Procedure Title	Crankcase Gases (Blowby) Excessive
Update Reason	Corrected reference to Fault Codes 556, 1843, and 1844 in the TS tree.

Date	21-Jun-2018
Section	Section 16 - Mounting Adaptations
Procedure Number	56-016-004-tr (/qs3/pubsys2/xml/en/procedures/56/56-016-004-tr.html)
Procedure Title	Flexplate
Update Reason	Removed statement from Preparatory Steps about ESN first and removed reference to Procedure 016-008.

Date	21-Jun-2018
Section	Section 10 - Intake Air System
Procedure Number	56-010-034-tr (/qs3/pubsys2/xml/en/procedures/56/56-010-034-tr.html)
Procedure Title	Turbocharger, High Pressure
Update Reason	Updated flange nut torque value to 55 N•m [40 ft-lb].

Date	21-Jun-2018
Section	Section 10 - Intake Air System
Procedure Number	56-010-035-tr (/qs3/pubsys2/xml/en/procedures/56/56-010-035-tr.html)
Procedure Title	Turbocharger, Low Pressure
Update Reason	Added: Apply anti-seize compound to capscrew threads. Updated flange nut torque value to 55 N•m [40 ft-lb].

Date	19-Jul-2018
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-050 (/qs3/pubsys2/xml/en/procedures/56/56-007-050.html)
Procedure Title	Cylinder Smokes (Blue Smoke)
Update Reason	Added direction for the manifold to cool before removing.

Date	20-Jul-2018
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	56-013-021-tr (/qs3/pubsys2/xml/en/procedures/56/56-013-021-tr.html)
Procedure Title	Charging System Alternator Automatic Belt Tensioner
Update Reason	Removed step regarding belt tension gauge as is doesn't apply to automatic tensioners.

Date	19-Nov-2018
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-050 (/qs3/pubsys2/xml/en/procedures/56/56-007-050.html)
Procedure Title	Cylinder Smokes (Blue Smoke)
Update Reason	Procedure was updated to make it clear not to run the engine with the exhaust manual OFF.
Date	06-Dec-2018
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	56-008-062-tr (/qs3/pubsys2/xml/en/procedures/56/56-008-062-tr.html)
Procedure Title	Water Pump
Update Reason	Corrected impeller inside diameter measurements.
Date	21-Jan-2019
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-067-tr (/qs3/pubsys2/xml/en/procedures/56/56-007-067-tr.html)
Procedure Title	Eliminator™ Filter
Update Reason	Revised graphic in Install step and updated guide stud installation.
Date	07-Feb-2019
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-067-tr (/qs3/pubsys2/xml/en/procedures/56/56-007-067-tr.html)
Procedure Title	Eliminator™ Filter
Update Reason	Revised final step in the 'Install' section.

Date	28-Feb-2019
Section	Section 7 - Lubricating Oil System
Procedure Number	56-007-037-tr (/qs3/pubsys2/xml/en/procedures/56/56-007-037-tr.html)
Procedure Title	Lubricating Oil and Filters
Update Reason	Added instructions to drain the eliminator filter when the engine oil is drained.
Date	14-Mar-2019
Section	Section 10 - Intake Air System
Procedure Number	56-010-046-tr (/qs3/pubsys2/xml/en/procedures/56/56-010-046-tr.html)
Procedure Title	Turbocharger Oil Supply Line
Update Reason	Added QSK45 and QSK60 Marine content to the Remove and Install sections.
Date	20-Mar-2019
Section	Section 11 - Exhaust System - Group 11
Procedure Number	56-011-007-tr (/qs3/pubsys2/xml/en/procedures/56/56-011-007-tr.html)
Procedure Title	Exhaust Manifold, Dry
Update Reason	Revised Install step to include a statement to ensure the threads in the cylinder head is clear from debris.
Date	18-Mar-2019
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-045-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-045-tr.html)
Procedure Title	Piston and Cylinder Liner
Update Reason	Updated liner protrusion table in either Measure or Install section.

Date	18-Mar-2019
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-064 (/qs3/pubsys2/xml/en/procedures/56/56-001-064.html)
Procedure Title	Cylinder Liner Protrusion
Update Reason	Updated liner protrusion table in either Measure or Install section.
Date	27-Mar-2019
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	56-003-011-tr (/qs3/pubsys2/xml/en/procedures/56/56-003-011-tr.html)
Procedure Title	Rocker Lever Cover
Update Reason	The smooth side of seal faces upward with groove facing downward.
Date	03-Apr-2019
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	56-006-051-tr (/qs3/pubsys2/xml/en/procedures/56/56-006-051-tr.html)
Procedure Title	Injector Supply Lines (High Pressure)
Update Reason	Added a Note to connect INSITE™ electronic service tool to monitor fuel pressure relief.
Date	13-May-2019
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-045-tr (/qs3/pubsys2/xml/en/procedures/56/56-007-045-tr.html)
Procedure Title	Lubricating Oil Cooler Cover
Update Reason	Changed the torque sequence and torque value.

Date	13-Jun-2019
Section	Section 10 - Air Intake System - Group 10
Procedure Number	56-010-002-tr (/qs3/pubsys2/xml/en/procedures/56/56-010-002-tr.html)
Procedure Title	Aftercooler Assembly
Update Reason	Added note to Inspect section.
Date	13-Jun-2019
Section	Section 10 - Air Intake System - Group 10
Procedure Number	56-010-033-tr (/qs3/pubsys2/xml/en/procedures/56/56-010-033-tr.html)
Procedure Title	Turbocharger
Update Reason	Added note to Inspect section.
Date	13-Jun-2019
Section	Section 10 - Air Intake System - Group 10
Procedure Number	56-010-083-tr (/qs3/pubsys2/xml/en/procedures/56/56-010-083-tr.html)
Procedure Title	Intercooler Assembly
Update Reason	Added note to Inspect section.
Date	27-Aug-2019
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-109-tr (/qs3/pubsys2/xml/en/procedures/56/56-008-109-tr.html)
Procedure Title	Low-Temperature Aftercooler (LTA) Water Pump
Update Reason	Added information about the Duckbill drain.
Date	25-Sep-2019
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-015-tr (/qs3/pubsys2/xml/en/procedures/56/56-007-015-tr.html)
Procedure Title	Lubricating Oil Filter Head
Update Reason	Corrected torque values for the filter head adapters.

Date	14-Oct-2019
Section	Section 1 - Cylinder Block - Group 1
Procedure Number	56-001-052-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-052-tr.html)
Procedure Title	Vibration Damper, Viscous
Update Reason	Added in all applications except haul trucks. Haul Truck dampers can be replaced at rebuild in the note in the Clean and Inspect for Reuse.
Date	17-Dec-2019
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	56-016-004-tr (/qs3/pubsys2/xml/en/procedures/56/56-016-004-tr.html)
Procedure Title	Flexplate
Update Reason	Added information for 60L engines fitted with an insulated flexplate.
Date	08-Nov-2019
Section	Section F - Familiarization
Procedure Number	56-200-002 (/qs3/pubsys2/xml/en/procedures/56/56-200-002.html)
Procedure Title	Flow Diagram, Lubricating Oil System
Update Reason	Reversed positions of the oil flow arrows in graphic 07e00194 to indicate the proper flow of oil.
Date	02-Jan-2020
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	56-006-051-tr (/qs3/pubsys2/xml/en/procedures/56/56-006-051-tr.html)
Procedure Title	Injector Supply Lines (High Pressure)
Update Reason	Added content to procedure.

Date	22-Jan-2020
Section	Section 14 - Engine Testing - Group 14
Procedure Number	56-014-005-tr (/qs3/pubsys2/xml/en/procedures/56/56-014-005-tr.html)
Procedure Title	Engine Testing (Engine Dynamometer)
Update Reason	Removed sensor reference value from the QSK78 Blowby Limits table.

Date	03-Feb-2020
Section	Section 14 - Engine Testing - Group 14
Procedure Number	56-022-001_14-tr (/qs3/pubsys2/xml/en/procedures/56/56-022-001_14-tr.html)
Procedure Title	Service Tools
Update Reason	Added cylinder diagnostic tool to the Service Tools table.

Date	20-Mar-2020
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-043-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-043-tr.html)
Procedure Title	Piston
Update Reason	Corrected the listed specifications for the FCD Piston Skirt Diameter.

Date	25-Mar-2020
Section	Section 14 - Engine Testing - Group 14
Procedure Number	00-014-012 (/qs3/pubsys2/xml/en/procedures/00/00-014-012.html)
Procedure Title	Engine Compression
Update Reason	Added additional information to the procedure.

Date	26-Mar-2020
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	56-012-020 (/qs3/pubsys2/xml/en/procedures/56/56-012-020.html)
Procedure Title	Air Compressor (Oil Carryover)
Update Reason	Reconfigured procedure to make it common.
Date	26-Mar-2020
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-062-tr (/qs3/pubsys2/xml/en/procedures/56/56-008-062-tr.html)
Procedure Title	Water Pump
Update Reason	Corrected the minimum maximum tables for the diameter of the water pump shaft and water pump impeller to include the correct specifications.
Date	12-May-2020
Section	Section 5 - Fuel System - Group 05
Procedure Number	102-005-232 (/qs3/pubsys2/xml/en/procedures/102/102-005-232.html)
Procedure Title	Fuel Pump Pressurizing Assembly
Update Reason	Added Resistance Check step to the procedure.
Date	14-May-2020
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-110-tr (/qs3/pubsys2/xml/en/procedures/56/56-007-110-tr.html)
Procedure Title	Fuel Pump Drive Lubricating Oil Filter
Update Reason	Added procedure to manual.

Date	14-May-2020
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-111 (/qs3/pubsys2/xml/en/procedures/56/56-007-111.html)
Procedure Title	Fuel Pump Drive Lubricating Oil Filter Head
Update Reason	Added procedure to manual.
Date	03-Jun-2020
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-030-tr (/qs3/pubsys2/xml/en/procedures/56/56-007-030-tr.html)
Procedure Title	Lubricating Oil Pressure Regulator (Piston Cooling)
Update Reason	Corrected the listed torque specification for the straight thread o-ring that is to be placed into the flywheel housing.
Date	14-Aug-2020
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-064 (/qs3/pubsys2/xml/en/procedures/56/56-001-064.html)
Procedure Title	Cylinder Liner Protrusion
Update Reason	Seperated specification table added for in field measurements.
Date	10-Sep-2020
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	56-006-026-tr (/qs3/pubsys2/xml/en/procedures/56/56-006-026-tr.html)
Procedure Title	Injector
Update Reason	Added note to refer to procedure 002-004 for steps on how to measure injector protrusion and to select the correct seal.

Date	06-Nov-2020
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	56-006-051-tr (/qs3/pubsys2/xml/en/procedures/56/56-006-051-tr.html)
Procedure Title	Injector Supply Lines (High Pressure)
Update Reason	Added details pertaining to the rubber grommet throughout the procedure.
Date	12-Nov-2020
Section	Section 11 - Exhaust System - Group 11
Procedure Number	56-011-001-tr (/qs3/pubsys2/xml/en/procedures/56/56-011-001-tr.html)
Procedure Title	Exhaust Connection Pipe
Update Reason	Corrected the torque values listed in the Install step for Exhaust Connection to Bellows.
Date	18-Jan-2021
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-035-tr (/qs3/pubsys2/xml/en/procedures/56/56-007-035-tr.html)
Procedure Title	Lubricating Oil Suction Tube (Block-Mounted)
Update Reason	Revised the content of the Install step of procedure and graphic.
Date	22-Jan-2021
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	102-001-026 (/qs3/pubsys2/xml/en/procedures/102/102-001-026.html)
Procedure Title	Cylinder Block
Update Reason	Updated first graphic shown in General Information step. Added list items fuel pump oil supply blanking plate capscrew holes and fuel pump oil supply passage.

Date	12-Feb-2021
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-035-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-035-tr.html)
Procedure Title	Hand Hole Cover
Update Reason	Added note for Low NOx emissions capability products, the dipstick hand hole cover is reversed, with dipstick on the left, and filling point on the right.
Date	12-Feb-2021
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	56-006-017-tr (/qs3/pubsys2/xml/en/procedures/56/56-006-017-tr.html)
Procedure Title	Fuel Filter Head
Update Reason	Added Remove, Clean and Inspect for Reuse and Install steps that specifically are for Generator Model DQKAN with Low NOx Emissions Capability.
Date	15-Feb-2021
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-011-tr (/qs3/pubsys2/xml/en/procedures/56/56-007-011-tr.html)
Procedure Title	Lubricating Oil Dipstick Tube
Update Reason	Added note for Low NOx emissions capability products, the dipstick hand hole cover is reversed, with dipstick on the left, and filling point on the right.
Date	17-Feb-2021
Section	Section 10 - Air Intake System - Group 10
Procedure Number	56-010-002-tr (/qs3/pubsys2/xml/en/procedures/56/56-010-002-tr.html)
Procedure Title	Aftercooler Assembly
Update Reason	Added note to indicate that engines using high pressure ratio compressor turbochargers use different air crossovers to ensure alignment.

Date	22-Feb-2021
Section	Section 11 - Exhaust System - Group 11
Procedure Number	56-011-007-tr (/qs3/pubsys2/xml/en/procedures/56/56-011-007-tr.html)
Procedure Title	Exhaust Manifold, Dry
Update Reason	Added note that indicates that there are two types of v-bands on the QSK45/60 and that the v-bands can be identified by the nut size.
Date	05-Mar-2021
Section	Section 9 - Drive Units - Group 09
Procedure Number	56-009-004-tr (/qs3/pubsys2/xml/en/procedures/56/56-009-004-tr.html)
Procedure Title	Accessory Drive Pulley
Update Reason	Added instruction remove and discard oil seal, along with new graphic depicting the action. Added instruction to install oil seal as well.
Date	17-Mar-2021
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-136 (/qs3/pubsys2/xml/en/procedures/56/56-001-136.html)
Procedure Title	Oil Passage Cover Plate
Update Reason	Added procedure to manual.
Date	22-Mar-2021
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-043-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-043-tr.html)
Procedure Title	Piston
Update Reason	Added information for standard and offset pistons into the General Information steps of the procedure.

Date	22-Mar-2021
Section	Section F - Familiarization
Procedure Number	56-006-999-tr (/qs3/pubsys2/xml/en/procedures/56/56-006-999-tr.html)
Procedure Title	Injectors and Fuel Lines - Overview
Update Reason	Added information for the low NOx emission sensors that pertains to QSK engines.
Date	26-Mar-2021
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	56-016-004-tr (/qs3/pubsys2/xml/en/procedures/56/56-016-004-tr.html)
Procedure Title	Flexplate
Update Reason	Added information regarding the insulated flexplate to the procedure.
Date	01-Apr-2021
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	56-006-013-tr (/qs3/pubsys2/xml/en/procedures/56/56-006-013-tr.html)
Procedure Title	Fuel Drain Lines
Update Reason	Added content pertaining to new bracket, Part Number 5634309.
Date	07-Apr-2021
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-009-tr (/qs3/pubsys2/xml/en/procedures/56/56-007-009-tr.html)
Procedure Title	Lubricating Oil Dipstick
Update Reason	Added note for Low NOx emissions capability products, the dipstick hand hole cover is reversed, with dipstick on the left, and filling point on the right.

Date	22-Apr-2021
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-003-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-003-tr.html)
Procedure Title	Accessory Drive Seal
Update Reason	Added steps in procedure to include information pertaining to new accessory drive seal.

Date	26-Apr-2021
Section	Section F - Familiarization
Procedure Number	56-200-001-tr (/qs3/pubsys2/xml/en/procedures/56/56-200-001-tr.html)
Procedure Title	Flow Diagram, Fuel System
Update Reason	Added updated image of Low NOx Fuel System.

Date	10-Jun-2021
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-028-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-028-tr.html)
Procedure Title	Cylinder Liner
Update Reason	Corrected minimum specification listed for cylinder liner inside diameter.

Date	21-Jul-2021
Section	Section 19 - Electronic Controls - Group 19
Procedure Number	122-019-450 (/qs3/pubsys2/xml/en/procedures/122/122-019-450.html)
Procedure Title	Exhaust Gas Temperature Sensor Converter
Update Reason	Added procedure to manual.

Date	12-Aug-2021
Section	Section 5 - Fuel System - Group 05
Procedure Number	56-005-240 (/qs3/pubsys2/xml/en/procedures/56/56-005-240.html)
Procedure Title	Fuel Pump Oil Supply Line
Update Reason	Added procedure to manual.
Date	17-Aug-2021
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	56-006-024-tr (/qs3/pubsys2/xml/en/procedures/56/56-006-024-tr.html)
Procedure Title	Fuel Supply Lines
Update Reason	Revised procedure to include information for generator model DQKAN with low NOx emissions capability. Added warning and instruction for connecting and disconnecting batteries in Preparatory and Finishing steps.
Date	24-Aug-2021
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-112 (/qs3/pubsys2/xml/en/procedures/56/56-007-112.html)
Procedure Title	Fuel Pump Drive Lubricating Oil Supply Line
Update Reason	Added procedure to manual.
Date	11-Oct-2021
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	102-006-061 (/qs3/pubsys2/xml/en/procedures/102/102-006-061.html)
Procedure Title	Fuel Pressure Relief Valve
Update Reason	Added mention of graduated cylinder into the procedure.

Date	03-Nov-2021
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	56-006-051-tr (/qs3/pubsys2/xml/en/procedures/56/56-006-051-tr.html)
Procedure Title	Injector Supply Lines (High Pressure)
Update Reason	Added note that the he Low NOx emissions product uses a different fuel crossover connection line to the standard product, to prevent interference with air filter tubing.
Date	08-Nov-2021
Section	Section 19 - Electronic Controls - Group 19
Procedure Number	56-019-011 (/qs3/pubsys2/xml/en/procedures/56/56-019-011.html)
Procedure Title	Blowby Pressure Sensor
Update Reason	Added procedure to manual.
Date	01-Dec-2021
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-053-tr (/qs3/pubsys2/xml/en/procedures/56/56-008-053-tr.html)
Procedure Title	Heat Exchanger
Update Reason	Updated plate location in Heat Exchanger and Plate Identification Number table. Corrected exploded view graphic.
Date	01-Dec-2021
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	56-016-004-tr (/qs3/pubsys2/xml/en/procedures/56/56-016-004-tr.html)
Procedure Title	Flexplate
Update Reason	Corrected misspelling in procedure and torque value in procedure.

Date	01-Dec-2021
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	56-006-020-tr (/qs3/pubsys2/xml/en/procedures/56/56-006-020-tr.html)
Procedure Title	Fuel Inlet Restriction
Update Reason	Added information for generator model DQKAN with low NOx emissions capability.
Date	01-Dec-2021
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	56-013-081 (/qs3/pubsys2/xml/en/procedures/56/56-013-081.html)
Procedure Title	Alternator Guard
Update Reason	Added procedure to manual.
Date	08-Dec-2021
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	56-006-109 (/qs3/pubsys2/xml/en/procedures/56/56-006-109.html)
Procedure Title	Fuel Leak Check16
Update Reason	Added procedure to manual.
Date	06-Jul-2022
Section	Section 19 - Electronic Controls - Group 19
Procedure Number	122-019-043 (/qs3/pubsys2/xml/en/procedures/122/122-019-043.html)
Procedure Title	Engine Wiring Harness
Update Reason	Corrected typo found in procedure.
Date	12-Jul-2022
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-067-tr (/qs3/pubsys2/xml/en/procedures/56/56-007-067-tr.html)
Procedure Title	Eliminator™ Filter
Update Reason	Minor wording corrections made to procedure.

Date	03-Aug-2022
Section	Section 2 - Cylinder Head - Group 02
Procedure Number	56-002-004-tr (/qs3/pubsys2/xml/en/procedures/56/56-002-004-tr.html)
Procedure Title	Cylinder Head
Update Reason	Revised information to note that exhaust valve seat inserts color-coded Brown have 20-degree angle seats and must only be installed to QSK60-G3, G4, and G7 engines.
Date	04-Aug-2022
Section	Section 19 - Electronic Controls - Group 19
Procedure Number	122-019-675 (/qs3/pubsys2/xml/en/procedures/122/122-019-675.html)
Procedure Title	Metal Particle Detector
Update Reason	Added procedure to manual.
Date	17-Aug-2022
Section	Section 10 - Air Intake System - Group 10
Procedure Number	56-010-033-tr (/qs3/pubsys2/xml/en/procedures/56/56-010-033-tr.html)
Procedure Title	Turbocharger
Update Reason	Added mention of the HE850 type model throughout procedure.
Date	11-Oct-2022
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	56-003-006-tr (/qs3/pubsys2/xml/en/procedures/56/56-003-006-tr.html)
Procedure Title	Overhead Set (OBC)
Update Reason	Both Valve Clearances - Recheck minimum and maximum tables in the Adjust step were updated with correct specifications.

Date	11-Oct-2022
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	56-012-007 (/qs3/pubsys2/xml/en/procedures/56/56-012-007.html)
Procedure Title	Air Compressor Cylinder Head, Single Cylinder
Update Reason	Added procedure to manual.
Date	13-Oct-2022
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-006 (/qs3/pubsys2/xml/en/procedures/56/56-001-006.html)
Procedure Title	Bearings, Main
Update Reason	Removed instruction from the Clean and Inspect for Reuse steps that the head of each capscrew must be inspected to count the number of punch marks.
Date	13-Oct-2022
Section	Section 8 - Cooling System - Group 08
Procedure Number	56-008-062-tr (/qs3/pubsys2/xml/en/procedures/56/56-008-062-tr.html)
Procedure Title	Water Pump
Update Reason	Corrected water pump shaft diameter (impeller end) minimum/maximum specification table.
Date	11-Nov-2022
Section	Section F - Familiarization
Procedure Number	56-200-003 (/qs3/pubsys2/xml/en/procedures/56/56-200-003.html)
Procedure Title	Flow Diagram, Cooling System
Update Reason	Corrected art to remove unnecessary callout.

Date	02-Jan-2023
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	56-006-003 (/qs3/pubsys2/xml/en/procedures/56/56-006-003.html)
Procedure Title	Air in Fuel
Update Reason	Added new test instructions.
Date	03-Jan-2023
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	56-003-009-tr (/qs3/pubsys2/xml/en/procedures/56/56-003-009-tr.html)
Procedure Title	Rocker Lever Assembly
Update Reason	Revised text and graphic to show installing an o-ring in the rocker lever socket, not on the rocker lever ball.
Date	21-Feb-2023
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	56-006-051-tr (/qs3/pubsys2/xml/en/procedures/56/56-006-051-tr.html)
Procedure Title	Injector Supply Lines (High Pressure)
Update Reason	Added part number 4918935 in Select Service Tools list. Included a new statement in Preparatory Steps to clarify.
Date	01-Mar-2023
Section	Section 10 - Air Intake System - Group 10
Procedure Number	56-010-002-tr (/qs3/pubsys2/xml/en/procedures/56/56-010-002-tr.html)
Procedure Title	Aftercooler Assembly
Update Reason	Corrected part number listed from 3824579 to 3824759.

Date	12-Apr-2023
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-047-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-047-tr.html)
Procedure Title	Piston Rings
Update Reason	Corrected specification listed for piston ring end gap.
Date	17-Jul-2023
Section	Section 14 - Engine Testing - Group 14
Procedure Number	56-014-002 (/qs3/pubsys2/xml/en/procedures/56/56-014-002.html)
Procedure Title	Engine Testing (Chassis Dynamometer)
Update Reason	Corrected procedure reference within procedure to direct to 014-010 instead of 014-005.
Date	20-Jul-2023
Section	Section 14 - Engine Testing - Group 14
Procedure Number	56-014-010-tr (/qs3/pubsys2/xml/en/procedures/56/56-014-010-tr.html)
Procedure Title	Crankcase Blowby, Measure
Update Reason	Added procedure to manual.
Date	30-Aug-2023
Section	Section 1- Cylinder Block - Group 01
Procedure Number	56-001-040-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-040-tr.html)
Procedure Title	Idler Gear, Water Pump
Update Reason	Added note to indicate for assembly purposes, the recommendation is to have the water pump idler gear part number facing away from the cylinder block.

Date	30-Aug-2023
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-031-tr (/qs3/pubsys2/xml/en/procedures/56/56-007-031-tr.html)
Procedure Title	Lubricating Oil Pump
Update Reason	Added note to indicate for assembly purposes, the recommendation is to have the water pump idler gear part number facing away from the cylinder block.
Date	16-Oct-2023
Section	Section 9 - Drive Units - Group 09
Procedure Number	56-009-011 (/qs3/pubsys2/xml/en/procedures/56/56-009-011.html)
Procedure Title	Fuel Pump Drive
Update Reason	Changed bolts from imperial to metric, inserted correct torque value and removed woodruff key insertion step.
Date	09-Jun-2025
Section	Section 13 - Electrical Equipment
Procedure Number	56-013-020-tr (/qs3/pubsys2/xml/en/procedures/56/56-013-020-tr.html)
Procedure Title	Starting Motor
Update Reason	In Install step, updated torque value specification for capscrews.
Date	08-Jul-2025
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	56-007-067-tr (/qs3/pubsys2/xml/en/procedures/56/56-007-067-tr.html)
Procedure Title	Eliminator™ Filter
Update Reason	Added instructions and torque value for oil sampling fitting into Pressure Test steps.

Date	21-Sep-2025
Section	Section 1- Cylinder Block - Group 01
Procedure Number	56-001-027 (/qs3/pubsys2/xml/en/procedures/56/56-001-027.html)
Procedure Title	Cylinder Block and Liner Seats
Update Reason	Updated specification in procedure in the statement that the four measurements must not vary more than 0.25 mm [0.010 in]. Replaced 0.25 mm [0.010 in] with 0.055 mm [0.0021 in] instead.
Date	21-Sep-2025
Section	Section 1- Cylinder Block - Group 01
Procedure Number	56-001-064 (/qs3/pubsys2/xml/en/procedures/56/56-001-064.html)
Procedure Title	Cylinder Liner Protrusion
Update Reason	Removed statement that the measurements must not vary more than 0.03 mm [0.001 in] for cylinder liner protrusion.
Date	12-Nov-2025
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	56-006-026-tr (/qs3/pubsys2/xml/en/procedures/56/56-006-026-tr.html)
Procedure Title	Injector
Update Reason	Updated procedure to improve injector fitment process.
Date	11-Mar-2026
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	56-016-002-tr (/qs3/pubsys2/xml/en/procedures/56/56-016-002-tr.html)
Procedure Title	Engine Support Bracket, Front
Update Reason	Corrected specification in Front Support Bore maximum so that the inches and mm equivalents are correctly listed. Changed 294.07 to 294.132 mm so that the correct metric equivalent of 11.58 in is listed.

Date	20-Mar-2026
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	56-001-006 (/qs3/pubsys2/xml/en/procedures/56/56-001-006.html)
Procedure Title	Bearings, Main
Update Reason	Updated 102-001-026 reference in procedure to engine specific 56-001-026.
Date	20-Mar-2026
Section	Section 1- Cylinder Block - Group 01
Procedure Number	56-001-010-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-010-tr.html)
Procedure Title	Camshaft Bushings
Update Reason	Updated 102-001-026 reference in procedure to engine specific 56-001-026.
Date	20-Mar-2026
Section	Section 1- Cylinder Block - Group 01
Procedure Number	56-001-027 (/qs3/pubsys2/xml/en/procedures/56/56-001-027.html)
Procedure Title	Cylinder Block and Liner Seats
Update Reason	Updated 102-001-026 reference in procedure to engine specific 56-001-026.
Date	20-Mar-2026
Section	Section 2 - Cylinder Head - Group 02
Procedure Number	56-002-004-tr (/qs3/pubsys2/xml/en/procedures/56/56-002-004-tr.html)
Procedure Title	Cylinder Head
Update Reason	Updated 102-001-026 reference in procedure to engine specific 56-001-026.