



Service Tool Instruction

**Service Tool Instruction
Number: 3400269-2**

Revision Level:

**Released Date: 09-jun-
2008**

Description

Piston Assembly Replacer Kit

Purpose

This document provides information for Piston Assembly Replacer Kit, Part Number 4919227. The kit is used to remove and install the piston and liner assembly in the QSK45 and QSK60 engines due to a design change of the connecting rod from an angle split to a horizontal split.

- For additional information, refer to Procedure 001-045 (Piston and Cylinder Liner) in Section 1 of the Service Manual, QSK45 and QSK60, Bulletin 4021530 (</qs3/pubsys2/xml/en/procedures/56/56-001-045-tr.html>)
- For additional information, refer to Procedure 001-045 (Piston and Cylinder Liner) in Section 1 of the Troubleshooting and Repair Manual, QSK45G and QSK60G Industrial Series Engines, Bulletin 4021383 (</qs3/pubsys2/xml/en/procedures/84/84-001-045-tr.html>)
- For additional information, refer to Procedure 001-045 (Piston and Cylinder Liner) in Section 1 of the Troubleshooting and Repair Manual, QSK60G Generator CM700, Bulletin 4021396. (</qs3/pubsys2/xml/en/procedures/84/84-001-045-tr.html>)




Table 1, Piston Assembly Replacer Kit, Part Number 4919227. Items can be purchased separately			
Item Number	Part Number	Description	Quantity
1	4918985	Cylinder liner replacer	1
2	4918986	Replacer fixture	1
4	4919120	Cylinder liner remover	1
Table 2, Items included with the Replacer Fixture, can be purchased separately			
Item Number	Part Number	Description	Quantity
3	4918939	Replacer housing	1