



Technical Service Bulletin

Technical Service Bulletin: tsb100048	Released Date: 11-May-2010
INSITE™ Electronic Service Tool 7.4 - Windows® 7 - Internet Explorer® 8 - Fault Information System Issue	

INSITE™ Electronic Service Tool 7.4 - Windows® 7 - Internet Explorer® 8 - Fault Information System Issue

Core Issue

This Technical Service Bulletin describes an issue with INSITE™ electronic service tool version 7.4 (7.4.0.244), on Windows® 7, with Internet Explorer® 8, when opening the fault information system (FIS). After opening a fault code, a script error window will open, instead of the troubleshooting steps.

Confirmation

All engines supported with INSITE™ electronic service tool.

When opening the troubleshooting steps for a Fault Code with INSITE™ electronic service tool, a Script Error window will open.


None

The older FIS files format includes a pop-up warning window.

None

Resolution

Click Yes or No on the Script Error window to open the Fault Code troubleshooting steps.



19000001

Screenshot of error message in INSITE™ Update Manager

The FIS files are being reformatted and will have this warning window removed. Periodically check the Cummins INSITE™ Update Manager for updated FIS files.

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.