



Technical Service Bulletin

Technical Service Bulletin: tsb100149

Released Date: 22-Jan-2002

New LTA Pipe Hoses

New LTA Pipe Hoses

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents


This Technical Service Bulletin introduces new low temperature aftercooling(LTA) pipe hoses for the QSK45 and QSK60 engines. The new hose has been released for improved durability.

The old hose, Part Number 3073123, is a three ply design using glass fibre reinforcement.

The new hose, Part Number 4080544, is a four ply design using a polyester fibre reinforcement.

Note : The old and new hoses are similar in appearance.

The new LTA pipe hose went into production at the Daventry Engine Plant with engine serial number first 33150762.



Note : This is a product improvement and is not subject to campaign.