



Technical Service Bulletin

Technical Service Bulletin: tsb100227	Released Date: 03-Aug-2009
New Pre-Lube Oil Pressure Shutdown Switch	

New Pre-Lube Oil Pressure Shutdown Switch

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Technical Service Bulletin announces the release of a new oil pressure switch for use on the QSK45 and QSK60 pre-lubrication system.

The original pre-lube pressure switch, Part Number 4065465, is replaced with Part Number 4101287. The original switch has a pressure setting of 17.2 kPa [2.5 psi] and the new switch has an improved pressure setting of 31.0 kPa [4.5 psi].

The new pressure switch went into production at the Daventry Engine Plant on May 13, 2003. The engine serial number first is 33154015.

This is a product improvement and is **not** subject to campaign.

Last Modified: 03-Aug-2009
