



Technical Service Bulletin

Technical Service Bulletin: tsb100229

Released Date: 04-Sep-2003

Revision 8.0 Injectors

Revision 8.0 Injectors

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Note : This Technical Service Bulletin supercedes SPT 02T6-4; replace 02T6-4 with this one.

The purpose of This Technical Service Bulletin is to introduce the new revision 8.0 injectors which supercede the revision 6.0 CF (cavitation fix) injectors for QSK45/60 applications. The revision 8.0 injectors have an improved design which will increase reliability.

No calibration change is required, and they can be used interchangeably with the old injectors. The parts matrix below illustrates the part number supercession trail.

The Engine Serial Number first (ESN) for the injector is 33154438.

Injector Supercession Matrix

Rev 8.0	Rev 6.0CF	Rev 6.0	Detail
4088427	4087893NX	4010025	QSK46/60 Industrial High BMEP*
4088426	4087892NX	4010157	QSK46/60 Industrial Low BMEP*
4088428	4087894NX	4010160	QSK45/60 Power Generation, QSK60 Marine Auxiliary
4902974	N/A	N/A	QSK60 Marine Propulsion
4088430	N/A	N/A	QSK78 All Applications

BMEP = Brake Mean Effective Pressure

Note : This is a product improvement and not subject to campaign.

