



Technical Service Bulletin

Technical Service Bulletin: tsb100284

Released Date: 08-Jul-2004

New Cylinder Head Valve Spring

New Cylinder Head Valve Spring

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Technical Service Bulletin introduces a new valve spring, Part Number 3635455, for the QSK45 and QSK60 series engines. The new spring has a revised material which has been changed to increase durability. Table 1 provides information with regard to part numbers and identification for the new and old valve spring.

Cummins Inc recommends replacing the valve spring when the cylinder head is rebuilt.

Table 1. Cylinder Head Valve Springs

Part Number	Color Code Identification	Spring Status
3085962	Blue	Obsolete
3635455	Red	New

Engine Serial Number first was 33156447 built April 2004.

Note : This is a product improvement and is not subject to campaign.

Last Modified: 08-Jul-2004