



# Technical Service Bulletin

Technical Service Bulletin: tsb100302

Released Date: 13-Sep-2004

New Intercooler Connection Hose

## New Intercooler Connection Hose

### Warranty Statement


The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

### Contents

This Technical Service Bulletin details the introduction of a new intercooler connection hose on the dual stage QSK60 series engines. The new hose has been released to improve hose durability. The hose material has changed from a glass fibre material to a knitted polyester hose material.

#### Intercooler Connection Hose Material Change Matrix

| Criteria    | Old Hose    | New Hose          |
|-------------|-------------|-------------------|
| Part Number | 4100590     | 3636448           |
| Material    | Glass Fibre | Knitted Polyester |
| Color       | Orange      | Blue              |



This change was implemented into production beginning with Engine Serial Number first of 33157569, built 23rd August 2004.

**Note :** This is a product improvement not subject to campaign.