



Technical Service Bulletin

Technical Service Bulletin: tsb100502	Released Date: 08-Dec-2009
Connecting Rod Reuse Guidelines at Rebuild or Repair	

Connecting Rod Reuse Guidelines at Rebuild or Repair

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Technical Service Bulletin has been superseded by topic 10T1-1. Replace 06T1-34 with Topic 10T1-1.

Last Modified: 08-Dec-2009
