



Technical Service Bulletin

Technical Service Bulletin: tsb100707

Released Date: 03-Jul-2008

New Oil Filter

New Oil Filter

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Technical Service Bulletin introduces a new Fleetguard® oil filter to replace the existing LF9024 model filter. The new LF9050 filter utilizes a 1.4 mm [0.055 in] shell thickness versus the previous LF9024 filter which utilized a 0.9 mm [0.035 in] thickness shell. This new thicker shell will provide additional protection from oil filter can damage due to oil pressure spikes.

The LF9050 oil filter retains all of the outside dimensions of the previous LF9024 and will fit on all of the same applications.

The LF9024 will be obsolete and supersede to the new LF9050 part number. Existing stock should be used up before going to the new filter. Please reference Table 1 below for the Cummins® Part Number for this new filter.

Table 1

Old Part Number	New Part Number	Description
Cummins® 3101870	Cummins® 4920071	Filter, Oil
Fleetguard® LF9024	Fleetguard® LF9050	Filter, Oil

Last Modified: 03-Jul-2008