



Technical Service Bulletin

Technical Service Bulletin: tsb100956

Released Date: 07-Apr-2011

New CENSE™ Wiring Harness and Exhaust Gas Temperature Sensors

New CENSE™ Wiring Harness and Exhaust Gas Temperature Sensors

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document introduces a new CENSE™ wiring harness and exhaust gas temperature sensors for use on QSK45 and QSK60 series engines.

The new CENSE™ wiring harness contains an additional clipping location for the exhaust gas temperature sensor harness. The new exhaust gas temperature sensor kit contains an additional grommet seal.

The new and old style CENSE™ harnesses can be mixed within an engine at repair. The installation procedure requires the harness to have a second grommet seal added to the exhaust gas temperature sensor harness in the additional clipping location.

The modified CENSE™ harness and sensors went into production at the Daventry Engine Plant on April 12, 2010. Engine Serial Number (ESN) first is 33180597.

Note : There are changes to the installation procedure.

Note : New and old CENSE™ harnesses can be mixed within an engine.

Note : This a product improvement, and is not subject to TRP and campaign actions.

Engine	Configur ation	Compon ent Name	Sensor Kit		Parts in Kit		
			Old Part Number	New Part Number	PN	Name	Quantity
GQSK38- G	D363003 GX03	Sensor, Tempera ture	3642537	3642537	3408542	Sensor, Tempera ture	1
					3408541	Seal, Gromme t	2

Engine	Configuration	Component Name	Sensor Kit		Parts in Kit		
			Old Part Number	New Part Number	PN	Name	Quantity
GQSK45-G	D863001 GX03	Sensor, Temperature	3408543	3642536	3408538	Sensor, Temperature	1
					3408541	Seal, Grommet	2
GQSK60-G	D843001 GX03	Sensor, Temperature	3642537	3642537	3408500	Sensor, Temperature	1
					3408541	Seal, Grommet	2
QSK45-C	D583003 CX03	Sensor, Temperature	3408544	3408544	3408542	Sensor, Temperature	1
					3408541	Seal, Grommet	2
QSK45-C	D583003 CX03	Sensor, Temperature	3408539	3642536	3408538	Sensor, Temperature	1
					3408541	Seal, Grommet	2
QSK45-C	D583003 CX03	Sensor, Temperature	3642537	3642537	3408500	Sensor, Temperature	1
					3408541	Seal, Grommet	2
QSK60-C	D593001 CX03	Sensor, Temperature	3408544	3408544	3408542	Sensor, Temperature	1
					3408541	Seal, Grommet	2

Engine	Configuration	Component Name	Sensor Kit		Parts in Kit		
			Old Part Number	New Part Number	PN	Name	Quantity
QSK60-C	D593001 CX03	Sensor, Temperature	3642537	3642537	3408500	Sensor, Temperature	1
					3408541	Seal, Grommet	2
QSK60-M	D593003 MX03	Sensor, Temperature	3408544	3408544	3408542	Sensor, Temperature	1
					3408541	Seal, Grommet	2
QSK60-M	D593003 MX03	Sensor, Temperature	3642537	3642537	3408500	Sensor, Temperature	1
					3408541	Seal, Grommet	2
QTA60-C	D593004 CX03	Sensor, Temperature	3408544	3408544	3408542	Sensor, Temperature	1
					3408541	Seal, Grommet	2
QTA60-C	D593004 CX03	Sensor, Temperature	3642537	3642537	3408542	Sensor, Temperature	1
					3408541	Seal, Grommet	2
QSK60-D(M)	D593005 MX03	Sensor, Temperature	3408544	3408544	3408542	Sensor, Temperature	1
					3408541	Seal, Grommet	2

Engine	Configuration	Component Name	Sensor Kit		Parts in Kit		
			Old Part Number	New Part Number	PN	Name	Quantity
QSK60-D(M)	D593005 MX03	Sensor, Temperature	3624537	3642537	3408500	Sensor, Temperature	1
					3408541	Seal, Grommet	2
QSKTTA 60-CE	D593006 CX03	Sensor, Temperature	3642537	3642537	3408500	Sensor, Temperature	1
					3408541	Seal, Grommet	2
QSKTA60-CE	D593007 CX03	Sensor, Temperature	3642537	3642537	3408500	Sensor, Temperature	1
					3408541	Seal, Grommet	2

Document History

Date	Details
2011-3-28	Incorrect table contents for all affected engines

Last Modified: 07-Apr-2011
