



Technical Service Bulletin

Technical Service Bulletin: TSB101042

Released Date: 06-Jan-2011

New Mounting Brackets for Pre-lubricating Pump Check Valves.

New Mounting Brackets for Pre-lubricating Pump Check Valves.

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document describes a design improvement made to the mounting brackets for the QSK45/60/78 pre-lubricating pump check valves. The design has changed from a solid u-bolt to a two-piece rubber clamp. This new design prevents the check valve from being crushed if overtightening of the mounting hardware should occur during installation, which can lead to an external oil leak from the pre-lubricating pump motor. A new check valve has also been released with improvements to the internal locknut.

This change was implemented at the Daventry Engine Plant starting with the following engines:

Engine	Engine Serial Number (ESN)	Build Date
QSK45/QSK60	33184025	22-Nov-2010
QSK78	66301586	29-Nov-2010

If a malfunction of the pre-lubricating pump or check valve does occur, the following parts should be replaced in order to upfit an engine to the latest design. Service parts for the previous design will **not** be available.

Affected options: PL 6769, PL 6787, PL 6800, PL 6804, PL 6818, PL 6819, PL 6832, and PL 6837

Old Part Number	Quantity	Part Name	New Part Number	Quantity	Part Name
3639025	1	Bracket, Check Valve	3643712	1	Bracket, Check Valve
3625826	4	Nut, Lock	3643722	1	Clamp, Tube
4007584	2	Clamp, U-bolt	3920115	2	Screw, Hex Flange Head
			4007601	2	Nut, Lock

Affected options: PL 6850, PL 6851, PL 6852, and PL 6853					
Old Part Number	Quantity	Part Name	New Part Number	Quantity	Part Name
3625826	4	Nut, Lock	3643722	1	Clamp, Tube
3639025	1	Bracket, Check Valve	3643712	1	Bracket, Check Valve
4007204	1	Valve, Check	3643839	1	Valve, Check
4007584	2	Clamp, U-bolt	3920115	2	Screw, Hex Flange Head
			4007601	2	Nut, Lock
Affected options: PL 6724, PL 6727, PL 6843, PL 6844, PL 6845, PL 6847, PL 6848, and PL 6849					
Old Part Number	Quantity	Part Name	New Part Number	Quantity	Part Name
3625826	4	Nut, Lock	3643722	1	Clamp, Tube
4007204	1	Valve, Check	3643839	1	Valve, Check
4007584	2	Clamp, U-bolt	3920115	2	Screw, Hex Flange Head
			4007601	2	Nut, Lock
Affected options: PL 6757, PL 6759, and PL 6743					
Old Part Number	Quantity	Part Name	New Part Number	Quantity	Part Name
4007204	1	Valve, Check	3643839	1	Valve, Check
Affected option: PL 6806					
Old Part Number	Quantity	Part Name	New Part Number	Quantity	Part Name
3625826	4	Nut, Lock	3643722	1	Clamp, Tube
4065979	1	Valve, Check	3643839	1	Valve, Check
4007584	2	Clamp, U-bolt	3920115	2	Screw, Hex Flange Head
			4007601	2	Nut, Lock
Affected option: LF 6067					
Old Part Number	Quantity	Part Name	New Part Number	Quantity	Part Name
3637648	1	Bracket, Connection	3643718	1	Bracket, Connection
Affected option: LF 6711					
Old Part Number	Quantity	Part Name	New Part Number	Quantity	Part Name

Affected option: LF 6711					
3642187	1	Bracket, Connection	3643715	1	Bracket, Connection

Document History

Date	Details
2010-8-30	Module Created

Last Modified: 06-Jan-2011
