



Technical Service Bulletin

Technical Service Bulletin: TSB101100

Released Date: 01-Dec-2010

New Connecting Rod Bearings

New Connecting Rod Bearings

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document announces the release of a new connecting rod bearing for use on QSK45 and QSK60 series diesel engines.

Straight Split Connecting Rods

- The new bearing has reverted back to the original VP2q bearing material to improve durability and has revised geometry to improve oil film characteristics.
- The new bearing will be installed into industrial engines **only**, as of 22-Nov-2010, starting with engine serial number (ESN) first 33184033. The new bearing will be installed in all QSK45 and QSK60 diesel engines starting January 2011.
- Prior to the ESN first above, the following ESN's had the new connecting rod bearings installed: 33183984, 33183989, and 33184007.
- **Only** the new bearing will be available for service as of December 2010.

Angle Split Connecting Rods

- The previous VP2q bearing for the angle split connecting rods has been reinstated to improve durability.
- The reinstated bearings will be available as of December 2010.
- Since **only** the straight split connecting rod is used in production, the angle split bearing will be used for service **only**, therefore no engine serial number first is being provided.

Table 1: New parts listing

Straight Split Connecting Rod	Old Part Number	Old Bearing Material	New Part Number	New Bearing Material
Standard	3640763	VP2i	3643984	VP2q
0.25 undersize	3640764	VP2i	3643985	VP2q
0.50 undersize	3640765	VP2i	3643986	VP2q
0.75 undersize	3640766	VP2i	3643987	VP2q

Table 1: New parts listing				
Straight Split Connecting Rod	Old Part Number	Old Bearing Material	New Part Number	New Bearing Material
1.00 undersize	3640767	VP2i	3643988	VP2q
-				
Angle Split Connecting Rod	Old Part Number	Old Bearing Material	New Part Number	New Bearing Material
Standard	3639827	VP2i	3636495	VP2q
0.25 undersize	3639828	VP2i	3636496	VP2q
0.50 undersize	3639829	VP2i	3636497	VP2q
0.75 undersize	3639830	VP2i	3636498	VP2q
1.00 undersize	3639831	VP2i	3636499	VP2q
Table 2: Quantity requirement per engine.				
Part Description	QSK45		QSK60	
Straight split connecting rod bearings	24		32	

Document History

Date	Details
2010-11-23	Module Created