



Technical Service Bulletin

Technical Service Bulletin: tsb101156

Released Date: 10-May-2002

Exhaust Gas Temperature Upfit Sensor

Exhaust Gas Temperature Upfit Sensor

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This service/parts topic is to describe the installation instructions for the new service upfit exhaust gas temperature sensor for the CENSE™ 1.0 AND 1.5 wiring harnesses. The revised design will eliminate the rigid lead of the previous sensor and replace it with a flexible silicon encased stainless steel braided lead. The new sensor has a Deutsch connector and a protective silicone sheath. The sensor also uses an extension harness.

The part number for the new sensor is 3408540 and supersedes the old part number, 3408374.

Table 1, New Upfit Parts for the Exhaust Gas Temperature Sensor

Part Description	Part Number	Quantity per Cylinder
Sensor, exhaust gas temperature	3408540	1
Harness, exhaust gas temperature extension	4066813	1
Kit, butt splice	3823336	2
P-Clip, 6.35 mm [.25 in]	180371	2
P-Clip	3081825	1
Z-bracket	4066560	1



19600217

New Exhaust Gas Temperature Sensor Design With Deutsch Connector



19600218

Old Inconel Exhaust Gas Temperature Sensor

Note : This is a product improvement and is **not** subject to campaign.

