



Technical Service Bulletin

Technical Service Bulletin: tsb101183	Released Date: 27-Sep-2002
Connecting Rod Inspection and Reuse Guidelines	

Connecting Rod Inspection and Reuse Guidelines

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This service/parts topic is to inform the field of the inspection and reuse guidelines for the QSK45 and QSK60 connecting rods.

Note : This is a product improvement not subject to campaign.

Last Modified: 27-Sep-2002
