



Technical Service Bulletin

Technical Service Bulletin: tsb101326

Released Date: 10-Feb-2004

New Single Box Breather Assembly

New Single Box Breather Assembly

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This service/parts topic introduces a new crankcase breather system for the QSK45 and QSK60 series engines. This design replaces the conventional head deck and crankcase side mounted breather arrangement in order to alleviate oil carryover which the conventional head deck and crankcase side mounted breather system exhibits.

The new crankcase breather system went into production at the Daventry Engine Plant from Engine Serial Number first of 33152044 for the QSK45 and 33153219 for the QSK60.

Information contained within this topic covers the removal and installation instructions for the new single box breather system with the Phase 2.0 wiring harness only.

Figure 1. shows the new design fitted to a QSK60 series engine (QSK45 series engines are similar).




Figure 1.

Related Procedures

56-003-001-tr
(/qs3/pubsys2/xml/en/procedures/56/56-003-001-tr.html)

Crankcase Breather (External)
(/qs3/pubsys2/xml/en/procedures/56/56-003-001-tr.html)

Last Modified: 10-Feb-2004