



Technical Service Bulletin

Technical Service Bulletin: tsb101926

Released Date: 30-Jun-2006

Maintenance Schedule Update - Centinel™ Oil Replacement Interval

Maintenance Schedule Update - Centinel™ Oil Replacement Interval

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the maintenance schedule for the QSK45 and QSK60 engines. The revision adds a new maintenance item under the interval of Maintenance Procedures at 250 Hours or 6 Months, and a new interval to the schedule for engines utilizing the Centinel™ oil system.

Related Procedures

56-102-002-om
(/qs3/pubsys2/xml/en/procedures/56/56-102-002-om.html)

Maintenance Schedule
(/qs3/pubsys2/xml/en/procedures/56/56-102-002-om.html)

Last Modified: 30-Jun-2006