



Technical Service Bulletin

Technical Service Bulletin: tsb101957

Released Date: 17-Aug-2006

Revision to Fuel Inlet Restriction Procedure, Tool Name Change

Revision to Fuel Inlet Restriction Procedure, Tool Name Change

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the service tool noun name from Diagnostic Orifice Tool, to Fuel System Tester, Part Number 4918612, to provide consistency between all sources of information.

Related Procedures

56-006-020
(/qs3/pubsys2/xml/en/procedures/56/56-006-020.html)

Fuel Inlet Restriction
(/qs3/pubsys2/xml/en/procedures/56/56-006-020.html)

Last Modified: 17-Aug-2006