



Technical Service Bulletin

Technical Service Bulletin: tsb102111

Released Date: 24-Apr-2008

Revision, Clean and Inspect for Reuse, Cylinder Head Procedure

Revision, Clean and Inspect for Reuse, Cylinder Head Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the Inspect for Reuse guidelines for Procedure 002-004.

Related Procedures

56-002-004-tr
(/qs3/pubsys2/xml/en/procedures/56/56-002-004-tr.html)

Cylinder Head
(/qs3/pubsys2/xml/en/procedures/56/56-002-004-tr.html)

Last Modified: 24-Apr-2008