



Technical Service Bulletin

Technical Service Bulletin: tsb102215

Released Date: 11-Jun-2007

Revised Maintenance Schedule - Mechanically Actuated Fuel Injectors

Revised Maintenance Schedule - Mechanically Actuated Fuel Injectors

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Section 9, Maintenance Procedures at 10,000 Hours, to include injector replacement at engine half life to rebuild.

Related Procedures

56-006-026-om
(/qs3/pubsys2/xml/en/procedures/56/56-006-026-om.html)

Injector
(/qs3/pubsys2/xml/en/procedures/56/56-006-026-om.html)

Last Modified: 11-Jun-2007