



Technical Service Bulletin

Technical Service Bulletin: tsb102237

Released Date: 18-Jun-2007

Revision, Multiple Steps, Fuel Filter Head Procedure

Revision, Multiple Steps, Fuel Filter Head Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 006-017 (Fuel Filter Head) in Section 1. Changes include instructions for the removal and installation of filter spuds and a leak check in the Finishing Step.

Related Procedures

56-006-017-tr
(/qs3/pubsys2/xml/en/procedures/56/56-006-017-tr.html)

Fuel Filter Head
(/qs3/pubsys2/xml/en/procedures/56/56-006-017-tr.html)

Last Modified: 18-Jun-2007