



Technical Service Bulletin

Technical Service Bulletin: tsb102250

Released Date: 08-May-2007

Revision, Install Step, Straight Thread Plug Procedure

Revision, Install Step, Straight Thread Plug Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 017-011 (Straight Thread Plug) in Section 17. The torque specifications for metric straight thread o-rings plugs used on QSK45 and QSK60 engines have been included.

Related Procedures

56-017-011
(/qs3/pubsys2/xml/en/procedures/56/56-017-011.html)

Straight Thread Plug
(/qs3/pubsys2/xml/en/procedures/56/56-017-011.html)

Last Modified: 08-May-2007