



Technical Service Bulletin

Technical Service Bulletin: tsb102347

Released Date: 22-Aug-2007

Addition, Service Tool Procedure

Addition, Service Tool Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic adds the Drop Gauge service tool for checking the valve guides, to the Service Tool Procedure 022-001_02 in Section 22.

Note : This is a product improvement and is not subject to campaign.

Related Procedures

56-022-001_02
(/qs3/pubsys2/xml/en/procedures/56/56-022-001_02.html)

Service Tools
(/qs3/pubsys2/xml/en/procedures/56/56-022-001_02.html)

Last Modified: 22-Aug-2007