



Technical Service Bulletin

Technical Service Bulletin: tsb102367

Released Date: 11-Jul-2007

Addition, Pressure Test Step, Cooling System Procedure

Addition, Pressure Test Step, Cooling System Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic adds the Pressure Test step to the Cooling System Procedure 008-018 in Section 8.

Note : This is a product improvement and is **not** subject to campaign.

Related Procedures

56-008-018-tr
(/qs3/pubsys2/xml/en/procedures/56/56-008-018-tr.html)

Cooling System
(/qs3/pubsys2/xml/en/procedures/56/56-008-018-tr.html)

Last Modified: 11-Jul-2007