



Technical Service Bulletin

Technical Service Bulletin: tsb102400

Released Date: 27-Jul-2007

Revision, General Information, Overhead Set (OBC) Procedure

Revision, General Information, Overhead Set (OBC) Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic intends to make it clear that QSK45 and QSK60 engines with the Quantum fuel system (mechanically actuated injectors) no longer require a valve and injector set to be performed at 1500 hours. Instead, the valves and injectors will **only** be adjusted when the injector is serviced.

This Service/Parts Topic revises the General Information step of Procedure 003-006 (Overhead Set (OBC)) to include a statement that reflects the guidelines for adjusting the overhead.

Related Procedures

56-003-006-tr
(/qs3/pubsys2/xml/en/procedures/56/56-003-006-tr.html)

Overhead Set (OBC)
(/qs3/pubsys2/xml/en/procedures/56/56-003-006-tr.html)

Last Modified: 27-Jul-2007