



Technical Service Bulletin

Technical Service Bulletin: tsb102401

Released Date: 26-Jul-2007

Revision, Maintenance Schedule

Revision, Maintenance Schedule

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic intends to make it clear that QSK45 and QSK60 engines with the Quantum fuel system (mechanically actuated injectors) no longer require a valve and injector set to be performed at 1500 hours. Instead, the valves and injectors will **only** be adjusted when the injector is serviced.

This Service/Parts Topic revises the maintenance schedule, Procedure 102-002 (Maintenance Schedule) to remove the scheduled item for adjusting the overhead.

Related Procedures

56-102-002-om
(/qs3/pubsys2/xml/en/procedures/56/56-102-002-om.html)

Maintenance Schedule
(/qs3/pubsys2/xml/en/procedures/56/56-102-002-om.html)

Last Modified: 26-Jul-2007