



Technical Service Bulletin

Technical Service Bulletin: tsb102460

Released Date: 07-Sep-2007

Revision, Clean and Inspect for Reuse, Cylinder Liner Procedure

Revision, Clean and Inspect for Reuse, Cylinder Liner Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

The purpose of this Service/Parts Topic is to revise the Clean and Inspect for Reuse steps for Procedure 001-028 (Cylinder Liner).

Related Procedures

56-001-028-tr
(/qs3/pubsys2/xml/en/procedures/56/56-001-028-tr.html)

Cylinder Liner
(/qs3/pubsys2/xml/en/procedures/56/56-001-028-tr.html)

Last Modified: 07-Sep-2007