



Technical Service Bulletin

Technical Service Bulletin: tsb102556

Released Date: 14-Dec-2007

Revision, Multiple Steps, Maintenance Schedule Procedure

Revision, Multiple Steps, Maintenance Schedule Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the maintenance schedule by removing the reference in the schedule to 'see Section V for oil replacement based on analysis' statement and replacing the statement with a reference to the Cummins® Engine Oil and Oil Analysis Recommendations, Bulletin 3810340. Multiple revisions to the Oil Drain Interval step have been made also.

Related Procedures

56-102-002-om
(/qs3/pubsys2/xml/en/procedures/56/56-102-002-om.html)

Maintenance Schedule
(/qs3/pubsys2/xml/en/procedures/56/56-102-002-om.html)

Last Modified: 14-Dec-2007