



Technical Service Bulletin

Technical Service Bulletin: tsb102697

Released Date: 12-Mar-2008

Revision, Multiple Steps, Connecting Rod Procedure

Revision, Multiple Steps, Connecting Rod Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

The purpose of the Service/Parts Topic is to add a General Information section, revise the Clean and Inspect for Reuse section, and revise the Measure section in the Connecting Rod procedure (001-014).

Related Procedures

56-001-014
(/qs3/pubsys2/xml/en/procedures/56/56-001-014.html)

Connecting Rod
(/qs3/pubsys2/xml/en/procedures/56/56-001-014.html)

Last Modified: 12-Mar-2008