



# Technical Service Bulletin

Technical Service Bulletin: tsb102744

Released Date: 18-Mar-2008

Revision, Specifications, Lubricating Oil System

## Revision, Specifications, Lubricating Oil System

### Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

### Contents

This Service/Parts topic revises the specifications for the Lubricating Oil System, sump configuration and capacities.

### Related Procedures

56-018-017  
(/qs3/pubsys2/xml/en/procedures/56/56-018-017.html)

Lubricating Oil System  
(/qs3/pubsys2/xml/en/procedures/56/56-018-017.html)

Last Modified: 18-Mar-2008