



Technical Service Bulletin

Technical Service Bulletin: tsb102851

Released Date: 13-May-2008

Addition, Measurement for Oversize Head Gasket for Cylinder Block and Liner Seats Procedure

Addition, Measurement for Oversize Head Gasket for Cylinder Block and Liner Seats Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic adds measurement specifications for oversize head gaskets to the Clean and Inspect for Reuse step in Procedure 001-027 (Cylinder Block and Liner Seats).

Related Procedures

56-001-027
(/qs3/pubsys2/xml/en/procedures/56/56-001-027.html)

Cylinder Block and Liner Seats
(/qs3/pubsys2/xml/en/procedures/56/56-001-027.html)

Last Modified: 13-May-2008