



Technical Service Bulletin

Technical Service Bulletin: tsb102853

Released Date: 20-May-2008

Low-Temperature Aftercooler Water (LTA) Pump Procedure, Oil Feed Hose Information Addition

Low-Temperature Aftercooler Water (LTA) Pump Procedure, Oil Feed Hose Information Addition

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the Remove and Install sections of Procedure 008-109 (Low-Temperature Aftercooler (LTA) Water Pump). Instructions for the oil feed hose has been included.

Related Procedures

56-008-109-tr
(/qs3/pubsys2/xml/en/procedures/56/56-008-109-tr.html)

Low-Temperature Aftercooler (LTA) Water Pump
(/qs3/pubsys2/xml/en/procedures/56/56-008-109-tr.html)

Last Modified: 20-May-2008