



Technical Service Bulletin

Technical Service Bulletin: tsb102854

Released Date: 30-May-2008

Lubricating Oil Pump Procedure, Clean and Inspect for Reuse Section Revision

Lubricating Oil Pump Procedure, Clean and Inspect for Reuse Section Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the Clean and Inspect for Reuse section of Procedure 007-031 (Lubricating Oil Pump). The pressure regulator spring specifications were revised.

Related Procedures

56-007-031-tr
(/qs3/pubsys2/xml/en/procedures/56/56-007-031-tr.html)

Lubricating Oil Pump
(/qs3/pubsys2/xml/en/procedures/56/56-007-031-tr.html)

Last Modified: 30-May-2008